GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI- 110001

NO. F6/DFS/MS/EH/2018/SZ/ 2744

Dated: 24/12/18

FIRE SAFETY CERTIFICATE

Certified that the M/s Kadimi Foods Pvt. Ltd. located at Plot no.7 Sector-11, Pkt-IV, Dwarka, New Delhi-110075, is running at 2nd Second floor of the building comprised of ground plus three upper floors was issued Fire Safety Certificate by this department vide letter no. F6/ DFS/MS/EH/09/3683 dated 03.12.2009. The premises was re-inspected by the officer concerned of this department on 07.12.2018 in presence of Sh. Mansa Ram (Manager) and found the premises have deemed complied with fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules 2010, and that the building is fit for occupancy class D "Assembly building "Restaurant" with effect from.

Issued onat New Delhi by

(Vipin Kental)
Chief Fire Officer

Copy to:-

1. The Addl.CP/Lic. Unit, 1st floor, Police Station Defence Colony, New Delhi.

2. Sh. Manish Jain S/o Sh. Mahender Jain R/o B-1/600 A, Janakpuri, New Delhi.

CONDITIONS

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 6. All comments / directions of licensing Department shall always be permitted and followed.
- 7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner / occupier shall apply for renewal of this **Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37)**along with copy of the certificate, six months prior to its expiry.

		INSPECTION REPORT		
1		M/s Kadimi's Food Pvt. Ltd Sector-11, Pkt-IV, Dwarka		r, Plot no.7
2	Type of Occupancy	Assembly "D" Restaurant		
3	Type of case	Renewal		
4	Details of previous NOC	No. F-6/DFS/MS//EH/09/3	3683 dated 3.12.2009	
5	Botanio di proviocio i i c	UBBL/NBC Requirements		
353	The canety amount of	07.12.2018		
6	Date of inspection			
7	Training or any map of any	ADO S.P Bhardwaj (Dwarka)		
8	Name and designation of officers from building side	Sh. Mansa Ram (Manager)		
9	Year of construction	Before 2009	Restaurant Runini	g at 2nd Floo
10	Applicant's letter No.	5143/Addl.CP/EH/(DA- VI) dated 6.11.2018	Building Comprise 3 upper F	loors
S. NO.	Minimum Standards on fire prevention and fire safety U/R 33	BBL/NBC Requirement/letter dated 3.12.2009	Provided at site	Remarks MR / NMR
1	Access to building		I	MD
	1) Road width	6 Mtrs.	Provided Dircet accesible	MR
	2) Gate width	4.5 Mtrs.	from road	MR
	3) Width of internal road	N/A	N/A	N/A
2	Number, width Type & arrangemen	t of exits		
	a. Number of staircases			T.A.D.
	1. Upper floors	One	One	MR
	2. basements	N/A	N/A	N/A
	b. Width of staircase			
	1. Upper floors	1.25 Mtrs.	1.25 Mtrs.	MR
	2. basements	N/A	N/A	N/A
	c. Protection of exits			21/4
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	d. No. of continuous staircase to	Requied	One	MR
	terrace		N1/A	N/A
	e. Width of corridor	N/A	N/A	MR being old
	f. Door size	2.0 Mtrs.	1.25 Mtrs & 1 Mtr.	case
3	Compartmentation.			TALLA
	1. Fire check door	N/A	N/A	N/A
	2. Sealing of electrical shafts	N/A	N/A	N/A
	3. Fire Rating of shaft door	N/A	N/A	N/A
	4. water curtain	N/A	N/A	N/A
N. Faur	5. Fire dampers	N/A	N/A	N/A
4	Smoke Management system.			
	basement	N/A	N/A	N/A
The state of the s				

	5	Fire Extinguishers			
		Total number	04 nos.	Provided	MR
I		Types	CO2 & ABC	Provided	MR
		ISI marking	ISI Marked	Provided	
	6	First-Aid Hose Reels.	TOT Warked	Frovided	MR
		total numbers on each floor	One	Provided	IMD.
-		Length of Hose reel hose	30 m		MR
		Nozzle Diameter	5 mm	Provided	MR
ľ	7	Automatic fire detection and ala	erming evetem	Provided	MR
		Type of detectors	N/A		
		location of Main Panel	N/A	smoke	MR
		location of Repeater panel		N/A	N/A
		Alternate source of power	N/A	N/A	N/A
		hooter's location	N/A	N/A	MR
-	8	MOEFA	N/A	N/A	MR
-	9		Required	Provided	MR
-	10	Public Address System.	N/A	N/A	N/A
-	10	Automatic Sprinkler System.			
		basement	N/A	N/A	N/A
		Required in restaurant area	Required	Drovided	MD
				Provided	MR
-	44	sprinkler above false ceiling	N/A	N/A	N/A
-	11	Internal Hydrants			
		Size of riser/down-corner	100 MM	Provided	MR
		Number of Hydrants per floor	One	Provided	MR
		hose Box	Required	Provided	MR
	12	Yard Hydrants.		1.1011000	1411.
		total number of hydrants	N/A	N/A	N/A
		hose box	N/A	N/A	N/A
	13	Pumping arrangements		11// \	IN/A
		1. Ground level/			
		a. Discharge of main Pump	N/A	N/A	· INI/A
1		b.Head of main pump	N/A	N/A	N/A
		c.Number of main pumps	N/A		N/A
		d.jockey pump out put	N/A	N/A	N/A
		e.jockey pump head	N/A	N/A	N/A
		f. Standby Pump output	N/A	N/A	N/A
		g.Stanby Pump head	N/A	N/A	N/A
		h.Auto Starting/Manual stopping	N/A	N/A	N/A
		pump house access		N/A	N/A
		2.Terrace level	N/A	N/A	N/A
		a. Discharge of pump	450 400 1 514		
			450, 180 LPM	Provided	MR
		b. head of the pump	30 Mtrs.	Provided	MR
		c. Power supply	Required	Provided	MR
10		d. Auto starting of pump	Required		
		Captive water storage for fire	required	Provided	MR
	14	fighting	*		8 8
		Underground tank capacity	N/A	D1/0	
		a. Draw-off connection	N/A	N/A	N/A
	-	b. fire service inlet		N/A	N/A
	-	c.Access to tank	N/A	N/A	N/A
V		Over head tank Capacity	N/A	N/A	N/A
		Exit Signage.	50000 Ltrs.	Provided	MR
		Provision of lifts.	Required	Provided	MR
			N1/0		
		a. Pressurization of lift shaft	N/A	N/A	N/A
		b. pressurization of lift lobby	N/A	N/A	N/A
		c. communication in lift car	N/A	N/A	N/A
		The state of the s			

7	Standby power supply	Required	Provided	MR
8	Refuge Area.		Not Required	IVIIX
	total area	N/A	N/A	N/A
	location	N/A	N/A	N/A
19	Fire control room			13// \
	a. detector system Panel	N/A	N/A	N/A
	b. Flow switch Panel	N/A	N/A	N/A
	c. PA system Panel	N/A	N/A	N/A
	d. Batter backup	N/A	N/A	N/A
	e. Building floor plans	N/A	N/A	N/A

The fire protection systems provided in the building were checked and found functional at the time of inspection.

Keeping in view the demmed compliance of the minimum standards on fire prevention and fire safety requirements under the rules, renewal of Fire Safety Certificate issued vide letter no.F6/DFS/MS/EH/09/3683 dated 03.12.2009 is recommended.

Accordingly DFA is put up for approval and signature please.

SP Bhardwaj ADO Dwarka

MR

provided near electric panel