GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2019/ 487

Dated :--- 3-/---

FIRE SAFETY CERTIFICATE

Certified that the M/s Welcome Guest House located at 1349, Pujabi Phatak, Haveli Hisamuddin, Ballimaran, Chandani Chowk, Delhi comprised of Ground floor (Commercial use), 1st floor (04 guest rooms + reception & 03 rooms found sealed), 2nd floor (05 guest rooms & 01 store sealed) and 3rd floor (01 hall for 05 beds + 02 stores), total 09 guest rooms & 01 hall for 05 beds owned/occupied by M/s Welcome Guest House was granted FSC by this department vide letter No.F6/DFS/MS/GH/2015/NDZ/1614 dated 04/09/15. The premises was re-inspected by the officer concerned of this department on 15/02/19 in the presence of Sh. Minnatullah (Manager) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 as above 09 guest rooms + 05 beds only with effect from -8/3/1/2------for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued ---- at New Delhi by.

(Sunil Chowdhary) Dy. Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi.
- The Manager, M/s Welcome Guest House at 1349, Pujabi Phatak, Haveli Hisamuddin, Ballimaran, Chandani Chowk, Delhi.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

9. Any flammable material for interior decoration is prohibited.

INSPECTION REPORT

1. Name & address of the building:-M/s Welcome Guest House at 1349, Pujabi

Phatak, Haveli Hisamuddin, Ballimaran,

Chandani Chowk, Delhi

2. Type of occupancy:-Residential, Sub Division-A-1

Gr. + 03 Upper floors (total 09 Guest rooms+ 05 beds) Ground floor (Commercial use), 1st floor (04 guest rooms + reception & 03 rooms found sealed), 2nd floor (05 guest rooms & 01 store sealed) and 3rd floor (01 hall

for 05 beds + 02 stores)

3. Type of case:-Renewal

4. Details of previous FSC:-No. F6/DFS/MS/GH/2015/NDZ/1614 dated

04/09/15.

5. Fire safety directives No.-N/A

6. Date of inspection:-15/02/19

7. Name of the inspecting officer:-

Sh. Manoj Kumar Sharma (ADO/CC)

8. Name & designation of officer

From the building side:-

Sh. Minnatullah (Manager) 1985

9. Year of construction:-

10. Applicant's letter No:-Nil dated 17/01/2019.

Old Case

				Old Case	
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement Existing fire safety arrangements	Provided at site	Remarks MR/NMR	
1.	Access to Building				
	1) Road width	N/A	09 mtr.	MR	
	2) Gate width	N/A	N/A	N/A	
	3) Width of internal road	N/A	N/A	N/A	
2.	Number, Width Type & Arr	angement of Ex	xits		
	A. Number of staircases				
	1. Upper floors	01 Nos.	01 Nos.	MR	
	2. Basements	N/A	N/A	N/A	
	B. Width of staircase				
	1. Upper floors	0.80 mtr.	0.94 mtr.	MR	
	2. Basements	N/A	N/A	N/A	
	C. Protection of exits				
	1. Fire check door	N/A	N/A	N/A	
	2. Pressurization	N/A	N/A	N/A	
	D. No. of continuous	01	01	MR	
	staircase to terrace				
	E. Width of corridor	N/A	N/A	N/A	
	F. Door size	0.80 mtr.	0.90 mtr.	MR	
3.	Compartmentation				
	1) Fire check door	N/A	N/A	N/A	
	2) Sealing of electrical shafts	N/A	N/A	N/A	
	3) Fire rating of shaft door	N/A	N/A	N/A	
	4) Water curtain	N/A	N/A	N/A	
	5) Fire Dampers	N/A	N/A	N/A	
1.	Smoke Management System				
	1) Basements	30 ACPH	N/A	N/A	
	2) Upper floors	12 a/c per hour	Natural	MR	
5.	Fire Extinguishers	1			
	1) Total numbers	06 Nos.	06 Nos.	MR	
	2) Types	ABC & CO2	ABC & CO2	MR	
	3) ISI marking	Required	Provided	MR	

14/19

6.	First-Aid Hose Reel			
	1) Total number of eachfloo	r 01at 2 nd floo	or 01at 2 nd floor	MR
	2) Length of hose reel hose	30 mtr.	30 mtr.	MR
	3) Nozzle diameter	05 mm	05 mm	MR
7.	Automatic Fire Detection &	& Alarming Sys	stem	IVIK
	1) Type of detectors	N/A	N/A	N/A
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	I N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
	5) Hooter's Location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	
9.	Public Address System	Required	Provided	N/A
10.	Automatic Sprinkler System	n	Flovided	MR
	1) Basement	N/A	N/A	77/
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false	N/A	N/A	N/A
	ceiling		11/71	N/A
11.	Internal Hydrants	Į.		
	1) Size of riser/down-comer	N/A	N/A	NI/A
	2) Number of hydrants per	N/A	N/A	N/A
	floor		1 1/2	N/A
	3) Hose box	N/A	N/A	NI/A
12.	Yard Hydrants		11//1	N/A
	1) Total number of hydrants	N/A	N/A	NI/A
	2) Hose box	N/A	N/A	N/A
3.	Pumping Arrangement	1	11//1	N/A
	1) Ground level	N/A	N/A	77/4
	a) Discharge of main	N/A	N/A N/A	N/A
	pump	11/11	IV/A	N/A
	b) Head of main pump	N/A	N/A	DI/A
	c) Number of main pump	N/A	N/A N/A	N/A
	d) Jockey pump out put	N/A	N/A N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
e	h) Auto starting/Manual	N/A		N/A
	stopping	14/71	N/A	N/A
	2) Terrace level			
	a) Discharge of pump	225 LPM	225 LPM	I I I
	b) Head of pump	25 mtr.	25 LPM 25 mtr.	MR
	c) Power supply	Required	Provided	MR
	d) Auto starting of pump	Required	Provided	MR
•	Captive Water Storage for Fi	re Fighting	rrovided	MR
e e			N/A	77/4
	capacity	~ 1/ 4 &	1 1/ 1	N/A
	\ D	N/A	N/A	NT/A
e .	1) 71		N/A	N/A
	\ A		N/A	N/A
	1) 0 1			N/A
	capacity	2500 Iti.	2500 ltr.	MR
	T 1: 61	Required	Dag 1 1	
		required	Provided	MR

an

16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any:			NA

The fire protection systems provided in the guest house building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F6/DFS/MS/GH/2015/NDZ/1614 dated 04/09/2015 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

Signature of the Inspecting Officer

Name: - M.K. Sharma Designation: - ADO (CC)

Dy. CFONDZ

F. S. letter is put up for som