GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6 DFS/MS/School/2019/SZ/ 822

Dated: 1.57.41.4.9

FIRE SAFETY CERTIFICATE

Certified that the C.S. Public School located at 586 Devli Village, New Delhi-110062 comprised of ground plus first floor was issued FSC by this department vide letter No. F.6/DFS/MS/2007/2177 dated 10/08/2007. The said premises was re-inspected by officer concerned of this department on 30/03/2019 in the presence of Mr. Paramjeet Singh (Manager) of the school and found that fire prevention and fire safety requirements have deemed complied in accordance with Circular No. 262-362 dated 17/01/2005 issued by Education Directorate Govt. of NCT of Delhi, Old Secretariat, New Delhi and that the premises fit for occupancy class Educational Building, Group-B, as above with effect from the date of issue of this certificate for a period of **Three years** subject to compliance of conditions mentioned below.

Issued on at New Delhi by

(Rajesh Panwar)
Dy. Chief Fire Officer
Tel. 011-26189168

Copy to: -

1. The Principal, C.S. Public School, 586, Devli Village, New Delhi-110062

2. Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054

Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

3		INSPEC	CTION REPORT				
1	Name & Address of the Building		C.S. Public School,586,Devli Village, New Delhi-				
_			110062				
2		of Occupancy	Educational, Group–B (School)				
3		ing Comprised of	Ground plus one upper floor only				
4		of Case	Renewal				
5		ls of Previous NOC	F.6/DFS/MS/2007/2177 dated 10/08/2007				
6		afety Directives Letter No	DOE Circular 262-232 dated 17/01/2005				
7		of Inspection	30/03/2019				
8		of the Inspecting Officers	Mehmood, ADO (SJ)				
9		& Designation of Officers	Mr. Paramjeet Singh (Manager)				
1.0		the building side			20		
10		of construction	2003				
11		cant letter No.	CSPS/001/NOC/2018-2019 dated 11/12/2018				
S. No.		num standards on Fire	As Per Old NOC	Provided at Site	Remarks		
4		ention and Fire Safety U/R 33		V	MR/NMR		
11		s to Building.		; r			
	•	Road width	6 mtr	5 mtr	MR(Old Case		
	•	Gate width	-NA-	-NA-	-NA-		
	•	Width of internal road	-NA-	-NA-	-NA-		
2		er, width, type & arrangement o	f exits.				
		umber of Staircase					
	>	I I	01 nos	02 nos	MR		
	>	Basement floor.	-NA-	-NA-	-NA-		
	b) W	idth of Staircase					
	>	Upper floors	1.50m/0.75m	1m & 0.89m	MR		
	>	Basement floor	-NA-	-NA-	-NA-		
	c) Pr	otection of exits	1111	11/1	-IVA-		
	>	Fire check door	-NA-	-NA-	-NA-		
	A	Pressurization	-NA-	-NA-	-NA-		
	d) No	. of continuous staircase to terrace	01no	Provided			
		idth of corridor			MR		
		or size	1.50m	Provided	MR		
3			1m	Provided	MR		
3	-	artmentation.					
	1	Fire check door.	-NA-	-NA-	-NA-		
	•	Sealing of electrical shafts.	-NA-	-NA-	-NA-		
		Fire rating of shaft door.	-NA-	-NA-	-NA-		
		Water curtain	-NA-	-NA-	-NA-		
4	Const	Fire dampers.	-NA-	-NA-	-NA-		
4.		e Management system.	20 1 001				
	•	Basement	30 ACPH	-NA-	-NA-		
5	Fine F	Upper floors	12 ACPH	-NA-	-NA-		
5.	rire E	xtinguishers.	0.7.3.4				
, ·	•	Total numbers	05 Nos	05 Nos	MR		
		Types	ABC / CO2	ABC & Co2	MR		
6	Diam'r	ISI Marking	ISI marked	Provided	MR		
6.	rirst A	Aid Hose Reels.					
	•	Total numbers on each floor.	-NA-	-NA-	-NA-		
	•	Length of hose-reel hose.	-NA-	-NA-	-NA-		
	•	Nozzle Diameter	-NA-	-NA-	-NA-		
7	Aret						
7.	Automa	atic fire detection & alarming					

	system.				
	Type of detectors	-NA-	-NA-		-NA-
	 Location of Main Panel 	-NA-	-NA-		-NA-
	 Location of Repeater Panel 	-NA-	-NA-		-NA-
	Alternate source of power	-NA-	-NA-		-NA-
	Hooter's location	-NA-	-NA-		-NA-
8.	MOEFA	-NA-	-NA-		-NA-
9.	Public Address System	-NA-	-NA-		-NA-
10.	Automatic Sprinkler System	1171	-IVA-		-IVA-
	Basement	-NA-	-NA-		-NA-
	Upper floors	-NA-	-NA-		-NA-
	Sprinkler above false ceiling	-NA-	-NA-		-NA-
11.	Internal Hydrants.		1 17 1		-14/1-
	Size of Riser/Down-comer	-NA-	-NA-		-NA-
	Number of Hydrant per floor	-NA-	-NA-		-NA-
	Hose box.	-NA-	-NA-		-NA-
12.	Yard Hydrants.	A 14 X	1421		-1 A\-/
	Total number of hydrants.	-NA-	-NA-		-NA-
	Hose box.	-NA-	-NA-		-NA-
13.	Pumping arrangements.	1111	-14/4-		-IVA-
	Ground Level				
	Discharge of main pump.	-NA-	-NA-		-NA-
	► Head of main pump.	-NA-	-NA-		-NA-
	Number of main pumps.	-NA-	-NA-		-NA-
	➤ Jockey Pump output.	-NA-	-NA-		-NA-
	➤ Jockey Pump head.	-NA-	-NA-		NA-
	Standby Pump output.	-NA-	-NA-		NA-
	Standby Pump head.	-NA-	-NA-		NA-
	Auto Starting / Manual	-NA-	-NA-		NA-
	Stopping.	-NA-	S		
	Pump house access.	-INA-	-NA-	•	·NA-
	Terrace Level		-	S N	
	Discharge of pump.	225 LPM	Provided		MR
	➢ Head of pump.➢ Power supply	35m	Provided		MR
	Power supply.Auto starting of pump.	Required	Provided	-	MR
14.		Required	Provided		MR
14.	Captive water storage for fire fighting.	214			
	Underground tank capacity. Draw off compaction.	-NA-	-NA-		NA-
	Draw-off connection.Fire Service Inlet.	-NA-	-NA-		NA-
	Access to tank.	-NA-	-NA-		NA-
	Overhead tank capacity.	-NA-	-NA-		NA-
15.	Exit Signage.	2,500 liter	Provided		MR
16.	Provision of Lifts.	Required	Provided		MR
100	Pressurization of lift shaft.	NIA T	T. T. A		N T A
		-NA-	-NA-		NA-
	1 ressarization of fift loody.	-NA-	-NA-		NA-
	Communication in lift car. Fireman's quitelet	-NA-	-NA-		NA-
	• Fireman's switch.	-NA-	-NA-		NA-
17.	Lift signage. Standby Power Symple.	-NA-	-NA-		NA-
1/.	Standby Power Supply	-NA-	-NA-	-	NA-

18.	Refuge Area				
	•	Total area	-NA-	-NA-	-NA-
	•	Location	-NA-	-NA-	-NA-
19.	Fire Control Room.		Vs.		
	Detector system panel.	-NA-	-NA-	-NA-	
		Flow switch panel.	-NA-	-NA-	-NA-
		PA system panel.	-NA-	-NA-	-NA-
		Battery backup.	-NA-	-NA-	-NA-
		Building floor plan.	-NA-	-NA-	-NA-
20.	Special Fire Protection System for the Protection of special Risk, if any.			-NA-	

The Fire protection systems provided in the premises were checked / operated at random and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the DOE circular, FSC issued vide letter No. F.6/DFS/MS/2007/2177 dated 10/08/2007 renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Mehmood Design: ADO (SJ)

DO (SD)

A FIT Letter burry for Signowne Aleane
James Jam