GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2019/SZ/ 934

Dated: 3/5/19

FIRE SAFETY CERTIFICATE

Certified that the **Meena Public School,** Q-52, Vikas Vihar, Uttam Nagar, New Delhi-110059 comprised of ground plus one upper floor in a three storied building, owned/occupied by Meena Public School was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/School/2016/SZ/537 dated 07.04.2016. The school building was re- inspected by the officer concerned of this department on 04.04.2019 in the presence of Sh. V.D. Kinger (Chairman) and found that the Meena Public School have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises (**Ground floor plus one upper floor**) is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

(RAJESH PANWAR) Dy. CHIEF FIRE OFFICER SOUTH ZONE

Copy to:-

- The Principal, Meena Public School, Q-52, Vikas Vihar, Uttam Nagar, New Delhi-110059
- Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. In case of usage of second floor for schooling purpose then this FSC will be null and void.

1. Name & address of the building : Meena Public School, Q-52, Vikas Vihar, Uttam Nagar, New Delhi-59 Type of Occupancy Educational Type of Case Renewal 4. Details of Previous NOC F.6/DFS/MS/School/2016/SZ/537 dated 07.04.2016 5. Fire Safety directives letter No Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 6. Date of inspection 04.04.2019 7. Name of Inspecting Officer A.D.O. Sandeep Duggal 8. Name and designation of officers From the building side Sh. V.D. Kinger (Chairman) 9. Year of Construction 1992 10. Applicant's letter No. MPS/2019/Feb dated 19.02.19 Minimum Standards on fire prevention and Dir. of Edu. Provided at Remarks fire safety U/R 33 Circular dt. site MR/NMR 01.03.2011 1. Access to building Road width Accessible 05 mtrs. MR, being old case Gate width N/A Directly accessible N/A Width of internal road N/A from road N/A N/A 2. Number, Width, Type & Arrangement of Exits a. Number of staircases Upper Floors 01 no.'s 02 no.'s MR Basements N/A N/A N/A b. Width of staircases Upper Floor 150 cms/additional 78 & 90 cms Basements MR staircase of 75 cms if less than 150 cms N/A N/A N/A c. Protection of exits Fire check door N/A N/A N/A Pressurization N/A N/A N/A No. of continuous staircases to terrace N/A N/A N/A Width of Corridor N/A N/A N/A Class room Door Size 100 cms 90 cms MR, being old case 3. Compartmentation Fire check door N/A N/A N/A Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain Fire Dampers N/A N/A N/A N/A N/A N/A 4. Smoke Management System Basements N/A N/A N/A Upper floors Required Natural Ventilation MR provided 5. Fire Extinguishers Total numbers 06 No's Provided MR **Types** ABC/CO₂ type Provided MR IS marking ISI marked ISI marked MR 6. First-Aid Hose Reels Total numbers on each floor N/A N/A N/A Length of hose reel hose N/A N/A N/A Nozzle diameter N/A N/A N/A

CHONIELONI

				0
7.	Automatic fire detection and alarming system	20020000		
	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System	13		
	Basement	N/A	N/A	N/A
	Ground Floor	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
1.	Internal Hydrants			
	Size of riser/down-comer	N/A	N/A	N/A
	Number of hydrants per floor	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
12.	Yard Hydrants			
	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements	representation of the second o		2
	Ground Level			
	Discharge of main Pump	N/A	N/A	N/A
	➤ Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	Jockey Pump out put			
	> Jockey pump head	N/A	N/A	N/A
	> Standby Pump out put	N/A	N/A	N/A
	Standby Pump HeadAuto Starting/Manual Stopping	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
	> Pump House Access		1, 10,	
	 Terrace level Discharge of pump 	N/A	N/A	N/A
	Discharge of pumpHead of the pump	N/A	N/A	N/A
	> Power Supply	N/A	N/A	N/A
	> Auto Starting of pump	N/A N/A	N/A	N/A
	, ratio starting or panip	1N/ <i>F</i> A	IN/A	19/74
14.	Captive Water Storage for fire fighting			
	Underground tank capacity	N/A	N/A	N/A
	> Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	> Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	N/A	N/A
15.	Exit Signage.	N/A	N/A	N/A

16.	Provision of Lifts.			No Lift)
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	• Fireman's Grounding Switch	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
17.	Standby power supply	N/A	N/A	N/A
410	~ manual porter suppry	T 1/ T F	11/11	

1/8

Fire Control Room			
 Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans 	N/A	N/A	N/A
	N/A	N/A	N/A
Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A
	 Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans Special Fire Protection System for Protection of	Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans Special Fire Protection System for Protection of N/A N/A N/A	● Detector System Panel N/A N/A ● Flow Switch Panel N/A N/A ● PA System Panel N/A N/A ● Battery backup N/A N/A ● Building Floor Plans N/A N/A Special Fire Protection System for Protection of N/A N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2016/SZ/537 dated 07.04.2016 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Note:- As per the undertaking submitted by Head Mistress (placed at C-19) school comprised of ground floor, first floor and second floor but school is running at ground & first floor only. Second floor is used for residence.

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

DCF (SZ)

24/4/1/

28/4

ADO (SKP)

P.T. letter is putyp for signature

e photos