GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2019/SZ/ 9 5 6

Dated: 7/57/9

FIRE SAFETY CERTIFICATE

Certified that the **Sarvodaya Kanya Vidyalaya**, Deendarpur, New Delhi-110043 comprised of ground plus one upper floor, owned/occupied by Govt. of NCT of Delhi was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/School/2016/SZ/445 dated 21.03.2016. The school building was reinspected by the officer concerned of this department on 26.03.2019 in the presence of Smt. Kumud Walia (Principal) and found that the Sarvodaya Kanya Vidyalaya have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

(RAJESH PANWAR) Dy. CHIEF FIRE OFFICER SOUTH ZONE

Copy to:-

- The Principal, Sarvodaya Kanya Vidyalaya, Deendarpur, New Delhi-110043
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

	INSPECTIO	N REPORT					
4. 5. 6. 7. 8.	Type of Occupancy Type of Case Details of Previous NOC Fire Safety directives letter No Date of inspection Name of Inspecting Officer Name and designation of officers From the building side Year of Construction Educational Renewal Circular No. F.: 26.03.2019 A.D.O. Sando Smt. Kumud Year of Construction Before 2010 SKV/DP/129	anya Vidyalaya, Dee /School/2016/SZ/445 16/Estate/CC/Fire Safet eep Duggal Walia (Principal) 3 dated 18.02.2019 Dir. of Edu.	dated 21.03.2016				
	fire safety U/R 33	Circular dt. 01.03.2011	site	MR/NMR			
1.	Access to building						
	Road widthGate widthWidth of internal road	Accessible 4.5 mtrs N/A	Available Provided N/A	MR MR N/A			
2.	Number, Width, Type & Arrangement of Exits	3					
	a. Number of staircases						
	Upper Floors	04 no.'s	04 no.'s	MR			
	Basements	N/A	N/A	N/A			
	b. Width of staircasesUpper Floor		-				
	Basements	150 cms	189, 170, 172 & 146 cms	MR			
	9	N/A	N/A	N/A			
	c. Protection of exits • Fire check door	N/A	N/A	N/A			
	Fire check doorPressurization	N/A	N/A	N/A			
		14/11	13/11	11/11			
	d. No. of continuous staircases to	N/A	N/A	N/A			
	e. Width of Corridor	N/A	N/A	N/A			
	e. Width of Corridor f. Class room Door Size	100 cms	100 cms	MR			
3.	Compartmentation						
	Fire check door	N/A	N/A	N/A			
	Sealing of electrical shafts	N/A	N/A	N/A			
	Fire Rating of shaft door	N/A	N/A	N/A			
	Water CurtainFire Dampers	N/A	N/A	N/A			
		N/A	N/A	N/A			
4.	Smoke Management System	27/1	27/4	27/4			
	Basements	N/A	N/A	N/A			
	Upper floors	Required	Natural Ventilation provided	MR			
5.	Fire Extinguishers						
	Total numbers	14 No's	Provided	MR			
	• Types	ABC/CO ₂ type	Provided	MR			
	IS marking	ISI marked	ISI marked	MR			
6.	First-Aid Hose Reels						
	Total numbers on each floor	N/A	N/A	· N/A			
	Length of hose reel hose	N/A	N/A	N/A			
	Nozzle diameter	N/A	N/A	N/A			

7.	Automatic fire detection and alarming system			
	Type of detectors	N/A	N/A	N/A
	 Location of Main Panel 	N/A	N/A	N/A
	 Location of Repeater Panel 	N/A	N/A	N/A
	 Alternate source of power 	N/A	N/A	N/A
	 Hooters' Location 	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	N/A	N/A
10				e d
10.	Automatic Sprinkler System	27/4	27/4	27/4
	BasementGround Floor	N/A	N/A	N/A
	NY CONTROL (19) 00246464 000 000 000 000 000 000 000 000 00	N/A	N/A	N/A
11.	Sprinkler above false ceiling Internal Hydrants	N/A	N/A	N/A
11.	Size of riser/down-comer	N/A	NI/A	DT/A
	Service of the servic	N/A N/A	N/A N/A	N/A N/A
	Number of hydrants per floorHose Box	N/A	N/A	N/A N/A
12.	Yard Hydrants	IV/A	IN/A	IN/A
12.		NI/A	NI/A	NI/A
	Total number of hydrantsHose Box	N/A N/A	N/A N/A	N/A N/A
13.	Pumping Arrangements	N/A	N/A	N/A
13.	Ground Level			
	Ground LevelDischarge of main Pump	NT/A	NI/A	27/4
	Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	Jockey Pump out put	N/A	N/A	N/A
	Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	Auto Starting/Manual Stopping	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A N/A	N/A	N/A N/A
	Pump House Access	IV/A	11/71	IN/A
	Terrace level	27/4	27/4	27/4
	Discharge of pumpHead of the pump	N/A	N/A	N/A
	Head of the pumpPower Supply	N/A	N/A	N/A
	> Auto Starting of pump	N/A	N/A	N/A
	Trace starting of paintp	N/A	N/A	N/A
14.	Captive Water Storage for fire fighting		1	
	Underground tank capacity	N/A	N/A	N/A
	Draw-off connection	N/A	N/A	N/A
	> Fire service inlet	N/A	N/A	N/A
	> Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	N/A	1000 1000 July 1000
15.	Exit Signage.	N/A N/A	N/A N/A	N/A N/A
	Exit Signage.	IN/A	IN/A	IN/A
16.	Provision of Lifts.		T	No Lift)
	 Pressurization of Lift Shaft 	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	• Fireman's Grounding Switch	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
17.	Standby power supply	N/A	N/A	N/A
				1111
18.	Refuge Area.			
	> Total Area	N/A	N/A	N/A

N/A	N/A	N/A
N/A	N/A	N/A
f N/A	N/A	N/A
	N/A N/A N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2016/SZ/445 dated 21.03.2016 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

S/CD FT. letter do protup for signature of