GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2019/SZ/ \ O2->

Dated: 14/5/18

FIRE SAFETY CERTIFICATE

Certified that the S.D.M.C Primary Girls Pratibha School, Dichaon Kalan, New Delhi-110043 comprised of ground plus one upper floor, owned/occupied by S.D.M.C was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/School/2015/SZ/2241 dated 23.12.2015. The school building was reinspected by the officer concerned of this department on 06.05.2019 in the presence of Smt. Sunita (Principal) and found that the S.D.M.C Primary Girls Pratibha School have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the

(RAJESH PANWAR) Dy. CHIEF FIRE OFFICER SOUTH ZONE

Copy to:-

- The Principal, S.D.M.C Primary Girls Pratibha School, Dichaon Kalan, New Delhi-110043
- 2. Director of Education, S.D.M.C, Civic Centre, Minto Road, New Delhi-110001.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if

1. Name & address of the building : S.D.M.C Primary Girls Pratibha School, Dichaon Kalan, New Delhi-110043 Type of Occupancy Educational Type of Case Renewal 4. Details of Previous NOC F.6/DFS/MS/School/2015/SZ/2241 dated 23.12.2015 5. Fire Safety directives letter No Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 6. Date of inspection 06.05.2019 7. Name of Inspecting Officer A.D.O. Sandeep Duggal 8. Name and designation of officers From the building side Smt. Sunita (Principal) 9. Year of Construction Before 2010 10. Applicant's letter No. Nil dated 06.03.2019 Minimum Standards on fire prevention and S. No. Dir. of Edu. Provided at Remarks fire safety U/R 33 Circular dt. site MR/NMR 01.03.2011 1. Access to building Road width Accessible 06 06 mtrs MR Gate width mtrs. 03 mtrs. MR, being old case 4.5 mtrs Width of internal road N/A N/A N/A 2. Number, Width, Type & Arrangement of Exits a. Number of staircases **Upper Floors** 02 no.'s 02 no.'s MR **Basements** N/A N/A N/A b. Width of staircases Upper Floor 150 cms/additional 133 & 133 cms **Basements** MR staircase of 75 cms if less than 150 cms N/A N/A N/A c. Protection of exits Fire check door N/A N/A N/A Pressurization N/A N/A N/A d. No. of continuous staircases to terrace N/A N/A N/A Width of Corridor N/A e. N/A N/A f. Class room Door Size 100 cms 110 cms MR (double door) 3. Compartmentation Fire check door N/A N/A N/A Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A Fire Dampers N/A N/A N/A N/A N/A 4. Smoke Management System N/A Basements N/A N/A Upper floors Required Natural Ventilation MR provided 5. Fire Extinguishers Total numbers 05 No's Provided MR ABC/CO₂ type **Types** Provided MR IS marking ISI marked ISI marked MR First-Aid Hose Reels 6. Total numbers on each floor N/A N/A N/A Length of hose reel hose N/A N/A N/A Nozzle diameter N/A N/A N/A

7	A			
7.	Automatic fire detection and alarming system Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A		
	Location of Nam Fanel Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location	N/A	N/A	N/A
0			N/A	N/A
3.	MOEFA	N/A	N/A	N/A
	Public Address System	N/A	N/A	N/A
0.	Automatic Sprinkler System		1,500	8
	Basement	N/A	N/A	N/A
	 Ground Floor 	N/A	N/A	N/A
	 Sprinkler above false ceiling 	N/A	N/A	N/A
1.	Internal Hydrants		,	
	 Size of riser/down-comer 	N/A	N/A	N/A
	 Number of hydrants per floor 	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
2.	Yard Hydrants			
	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
3.	Pumping Arrangements			
	Ground Level			
	Discharge of main Pump	N/A	N/A	N/A
	> Head of Main pump	N/A	N/A	N/A
	Number of main pumpsJockey Pump out put	N/A	N/A	N/A
	> Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	> Standby Pump Head	N/A	N/A	N/A
	Auto Starting/Manual Stopping			
	•	N/A	N/A	N/A
		N/A	N/A	N/A
	> Pump House Access	N/A	N/A	N/A
	Terrace level	NI/A	NI/A.	NI/A
	Discharge of pump	N/A	N/A	N/A
	Head of the pumpPower Supply	N/A	N/A N/A	N/A N/A
	> Auto Starting of pump	N/A N/A	N/A	N/A N/A
	Trate stateing of pump	IN/A	IN/A	IN/A
4.	Captive Water Storage for fire fighting			
	Underground tank capacity	N/A	N/A	N/A
	Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	N/A	N/A
5.	Exit Signage.	N/A	N/A	N/A
6.	Provision of Lifts.			(No Lift)
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift Interpretation of Lift lobby			*
	Communication In lift Car	N/A	N/A	N/A N/A
	A MANUTE OF A DESCRIPTION OF A DESCRIPTI	N/A	N/A	
	FIREMAN S CITOLINGING SWITCH	N/A	N/A	N/A
	Fireman's Grounding SwitchLift Signage	IVA	14/11	
	Y 10 G1	N/A	N/A	N/A
17.				

Fire Control Room		2	
Detector System Panel	N/A	N/A	N/A
Flow Switch Panel	N/A	N/A	N/A
PA System Panel	N/A	N/A	N/A
Battery backup	N/A	N/A	N/A
Building Floor Plans	N/A	N/A	N/A
Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A
	 Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans Special Fire Protection System for Protection of	Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans Special Fire Protection System for Protection of N/A N/A N/A	• Detector System Panel N/A N/A • Flow Switch Panel N/A N/A • PA System Panel N/A N/A • Battery backup N/A N/A • Building Floor Plans N/A N/A Special Fire Protection System for Protection of N/A N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number $\underline{F.6/DFS/MS/School/2015/SZ/2241}$ dated $\underline{23.12.2015}$ renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

8/5/201

DCFO (S2)

9/0

50/5m day 10/5

A 00 (3 Kp)

F.T. Seller is put up for signature please

Dycholse) (In