GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/2019/SZ/ 1086

Dated: 29/05/9

FIRE SAFETY CERTIFICATE

Certified that the D' Presidente Guest House, B2B/12, Janak Puri, Near Janak Puri East Metro Station, Metro Pillar No.-541, New Delhi-110058 comprised of basement, ground floor plus three upper floors, basement, ground floor plus three upper floors using basement as Storage & parking, ground floor as reception, office and lobby, 05 guest rooms on first floor, 05 rooms on second floor and 04 guest rooms on third floor (Total 14 guest rooms), owned/occupied by D' Presidente Guest House was issued FSC by this department vide letter no. F6/DFS/MS/GH/2016/SZ/433 dated 17.03.2016. The guest house building was re-inspected by the officer concerned of this department on 25.04.2019 in presence of Sh. Kulmohan Singh (Owner) and found that D' Presidente Guest House have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi fire service Rules 2010 and that the building/premises (Fourteen Guest Rooms at first floor, second floor & third floor as above) is fit for occupancy class "Residential" (Guest house) w.e.f the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on $\frac{22/05/19}{}$ at New Delhi.

(RAJESH PANWAR)
Dy. CHIEF FIRE OFFICER
SOUTH ZONE

Copy to: -

- 1. The Joint. C.P (Lic.), Police Station, Defence Colony, 1st floor, New Delhi,
- The Manager,
 D' Presidente Guest House, B2B/12, Janak Puri,
 Near Janak Puri East Metro Station,
 Metro Pillar No.-541, New Delhi–110058

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement shall be used as per the building bye laws.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

DOS Ra/sma

INSPECTION REPORT D' Presidente Guest House, B2B/12, Janak Puri, Near Janak Puri Name & address of the building: East Metro Station, Metro Pillar No.-541, New Delhi-110058 Residential (Guest House) Type of Occupancy 2. Renewal Type of Case 3. F6/DFS/MS/GH/2016/SZ/433 dated 17.03.2016. 4. Details of Previous NOC F.6/DFS/MS/HQ/2012/GH/4504 dated 07.12.2012 5. Fire Safety directives letter No : 25.04.2019 6. Date of inspection A.D.O. Sandeep Duggal Name of Inspecting Officer 7. Name and designation of officers Sh. Kulmohan Singh (Owner) From the building side 2011 Year of Construction 1463/Jt.C.P/Lic.(H) dated New Delhi the 22.02.2019 10. Applicant's letter No. Guest house is comprised of basement, ground floor plus three upper floors using basement as Storage & parking, ground floor as reception, office and lobby, 05 guest rooms on first floor, 05 rooms on second floor and 04 guest rooms on third floor (Total 14 guest rooms). Remarks Provided at NBC/ BBL Minimum Standards on fire prevention S. No. MR/NMR Requirement site and fire safety U/R 33 Access to building M/R 09 mtrs Accessible Road width MR 4.5 mtrs. 4.5 mtrs Gate width N/A N/A N/A Width of internal road Number, Width, Type & Arrangement of Exits a. Number of staircases M/R Two Two Upper Floors M/R 01 staircase & 01 Two **Basements** ramp b. Width of staircases M/R, being old case 100 & 125 to 125 cms & 100 Upper Floor 135 cms (spiral) cms Basements M/R 100 cms & 275 125 cms & 100 cms ramp c. Protection of exits cms Fire check door M/R Provided Pressurization Required N/A N/A N/A d. No. of continuous staircases to terrace M/R Provided Required Width of Corridor M/R 300 cms. 125 cms Door Size 79 cms Compartmentation N/A N/A N/A Fire check door N/A N/A Sealing of electrical shafts N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A **Smoke Management System** M/R Exhaust fans Required **Basements** are provided M/R Natural Required Upper floors Ventilation **Fire Extinguishers** 5. M/R Provided 10 no.'s Total numbers M/R Provided W/CO₂/ CO₂type **Types** M/R ISI marked ISI marked IS marking **First-Aid Hose Reels** N/A 6. 01 no. provided

N/A

N/A

N/A

30 mtrs.

5 mm

1 D .: Fast Matro Station Metro Pillar No.-

N/A

N/A

Total numbers on each floor

Length of hose reel hose

Nozzle diameter

1.

2.

3.

4.

	Automatic fire detection and alarming sys		TI			
1.	Type of detectors	N/A	N/A	N/A		
	Location of Main Panel	N/A	N/A	N/A		
	Location of Repeater Panel	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
	Hooters' Location	N/A	N/A	N/A		
	MOFEA	N/A	N/A	N/A		
•	MOEFA Public Address System	N/A	N/A	N/A		
	Automatic Sprinkler System	11/12				
0.	Basement	N/A	Provided	N/A		
	Ground Floor	N/A	N/A	N/A		
	Sprinkler above false ceiling	N/A	N/A	N/A		
11.	Internal Hydrants					
1.	Size of riser/down-comer	N/A	N/A	N/A		
	Number of hydrants per floor	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
2.	Yard Hydrants					
	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
3.	Pumping Arrangements		Market			
/	Ground Level		Occurred day to			
	Discharge of main Pump	N/A	N/A	N/A		
	➤ Head of Main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	Jockey Pump out put	N/A	N/A	N/A		
	Jockey pump head	1001111		N/A		
	Standby Pump out put	N/A	N/A			
	Standby Pump HeadAuto Starting/Manual	N/A	N/A	N/A		
	Stopping	N/A	N/A	N/A		
	Stopping	N/A	N/A	N/A		
	> Pump House Access	N/A	N/A	N/A		
	Terrace level					
	> Discharge of pump	N/A	450 & 180 LPM	N/A		
	➤ Head of the pump	N/A	30 mtrs	N/A		
	> Power Supply	N/A	N/A	N/A		
	Auto Starting of pump	N/A	N/A	N/A		
		2.00				
14.	Captive Water Storage for fire fighting					
	Underground tank capacity	N/A	N/A	N/A		
	> Draw-off connection	N/A	N/A	N/A		
15	Fire service inlet	N/A	N/A	N/A		
	Access to tank	N/A	N/A	N/A		
	 Overhead Tank capacity 	5000 Ltrs	Provided	M/R		
	E-14 Cinnaga	Required	Provided	M/R		
15.	Exit Signage.	Required				
16.	Provision of Lifts.			All the second s		
16.	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	N/A	N/A	N/A		
	Fireman's Grounding Switch	Required	Provided	M/R		
	Lift Signage	1		:		
		Required	Provided	M/R		
17.	Standby power supply	Required	Provided	M/R		
18.	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		

NE

Building is comprised of basement, ground floor plus three upper floors

19.	Fire Control Room			e e
	Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	PA System PanelBattery backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
		N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F6/DFS/MS/GH/2016/SZ/433 dated 17.03.2016 renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Note:- As per the undertaking submitted by Mr. Kulmohan Singh (placed at C-39) Both the staircases will be kept obstruction free/usable at all times without any hindrance. The basement staircase is segregated from upper floors by providing two hours fire rated gypsum board and lift is running from ground floor to upper floors only.

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation:- Asstt. Divisional Officer

D.C. (South West)

D.C. (South W