GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/Hotel/2019/SZ/ 1211 Dated: 06/06/19

FIRE SAFETY CERTIFICATE

Certified that M/s **Hotel Vivanta by Taj (Ambassador)** situated at Subramaniam Bharti Marg, Sujan Singh Park, New Delhi–110003, comprised of basement, ground + 04 upper floors was issued FSC by this department vide letter No. F6/DFS/MS/Hotel/2016/SZ/812 dated 19/05/2016. The premise was re-inspected by officer concern of this department on 29/05/2019 in the presence of Mr. Ravi Bhan (Manager-Security) and observed that the said hotel building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "**Hotel Building**" with effect from 6/6/2019 for period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Rules 2010.

Issued on 06/06/19 at New Delhi by

06/6/19

(Atul Garg)
Chief Fire Officer
Tel. 011-23414250

Copy to: -

1. Mr. Vikas Parimoo (Gen. Manager), M/s Hotel Vivanta by Taj (Ambassador) situated at Subramaniam Bharti Marg, Sujan Singh Park, New Delhi–110003
2. The Joint. Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-49

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire fighting system.
4. The owner/occupier shall submit a declaration every year in form 'K' provided in the First schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not be treated as regularization (Clause 2.8 of UBBL- 2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

INSPECTION REPORT				
1	Name & Address of the Building	M/s Hotel Vivanta by Taj (Ambassador), Subramaniam Bharti Marg, Sujan Singh Park, New Delhi –110 003		
2	Type of Occupancy	Residential Building (Hotel)		
3	Building Comprised of	Basement, Ground + 04 upper floors.		
4	Type of Case	Renewal		
5	Details of Previous NOC	F.6/DFS/MS/GH/SZ/2016/634 dated 26-04-2016		
6	Fire Safety Directives Letter No	Nil		
7	Date of Inspection	29-05-2019		
8	Name of the Inspecting Officers	Mehmood, ADO (SJ)		
9	Name & Designation of Officers from the building side	Mr. Ravi Bhan (Manager-Security)		
10	Year of construction	1945		
11	Applicant letter No.	Outdoor Diary No. 8717 dated 05-04-2019		
S. No.	**Minimum standards on Fire Prevention and Fire Safety U/R 33**	**Requirements**	**Provided at Site**	**Remarks MR/NMR**
1	**Access to Building.**			
	• Road width	15 mtr	Provided	MR
	• Gate width	4.5 mtr	Provided	MR
	• Width of internal road	Required	Provided	MR
2	**Number, width, type & arrangement of exits.**			
	a) Number of Staircase			
	➢ Upper floors.	04 Nos	GF to Terrace=03 Nos, 1st F to Terrace=01 No	MR
	➢ Basement floor.	02 Nos	Provided	MR
	b) Width of Staircase			
	➢ Upper floors	1.25 mtr	1.25m, 1.2m, 1.4m & 1.45m	MR (old case)
	➢ Basement floor	1.25 mtr	1.07m & 1.10m	MR (old case)
	c) Protection of exits			
	➢ Fire check door	Required	Provided	MR
	➢ Pressurization	Required	Provided	MR
	d) No. of continuous staircase to terrace	Required	03 Nos	MR
	e) Width of corridor	NA	NA	NA
	f) Door size	1m	1m provided	MR
3	**Compartmentation.**			
	• Fire check door.	Required	Provided	MR
	• Sealing of electrical shafts.	Required	Provided	MR
	• Fire rating of shaft door.	NA	NA	NA
	• Water curtain	NA	NA	NA
	• Fire dampers.	NA	NA	NA
4.	**Smoke Management system.**			
	• Basement	30 ACPH	Exhaust fan	MR
	• Upper floors	12 ACPH	Exhaust fan	MR
5	**Fire Extinguishers.**			
	• Total numbers	08 Nos	130 Nos	MR
	• Types	ABC / CO_2	ABC, CO_2 & W.CO_2	MR
	• ISI Marking	ISI marked	Provided	MR
6	**First Aid Hose Reels.**			
	• Total numbers on each floor.	04 Nos	Provided	MR
	• Length of hose-reel hose.	30m	Provided	MR
	• Nozzle Diameter	5mm	Provided	MR
7	**Automatic fire detection & alarming system.**			
	• Type of detectors	Required	Smoke & Heat	MR
	• Location of Main Panel	Required	Control Room (GF)	MR
	• Location of Repeater Panel	NA	NA	NA
	• Alternate source of power	Required	Provided	MR
	• Hooter's location	Required	All floors	MR

8	**MOEFA**	Required	Provided	MR
9	**Public Address System**	Required	Provided	MR
10	**Automatic Sprinkler System**			
	• Basement	Required	Provided	MR
	• Upper floors	Required	Guest areas & Restt.	MR
	• Sprinkler above false ceiling	NA	NA	NA
11	**Internal Hydrants.**			
	• Size of Riser/Down-comer	100 mm	Provided	MR
	• Number of Hydrant per floor	04 Nos	Provided	MR
	• Hose box.	04 Nos	Provided	MR
12	**Yard Hydrants.**			
	• Total number of hydrants.	07 Nos	Provided	MR
	• Hose box.	07 Nos	Provided	MR
13	**Pumping arrangements.**			
	• **Ground Level**			
	➢ Discharge of main pump.	1620 LPM	1620 LPM	MR
	➢ Head of main pump.	45m	45m	MR
	➢ Number of main pumps.	02	02	MR
	➢ Jockey Pump output.	180 LPM	180 LPM	MR
	➢ Jockey Pump head.	45m	45m	MR
	➢ Standby Pump output.	NA	NA	NA
	➢ Standby Pump head.	NA	NA	NA
	➢ Auto Starting/Manual Stopping.	Required	Provided	MR
	➢ Pump house access.	Required	Provided	MR
	• **Terrace Level**			
	➢ Discharge of pump.	NA	NA	NA
	➢ Head of pump.	NA	NA	NA
	➢ Power supply.	NA	NA	NA
	➢ Auto starting of pump.	NA	NA	NA
14	**Captive water storage for fire fighting.**			
	• Underground tank capacity.	1,00,000 Ltr	Provided	MR
	➢ Draw-off connection.	Required	Provided	MR
	➢ Fire Service Inlet.	Required	Provided	MR
	➢ Access to tank.	Required	Provided	MR
	• Overhead tank capacity.	10,000 Ltr	Provided	MR
15	**Exit Signage.**	Required	Provided	MR
16	**Provision of Lifts.**			
	• Pressurization of lift shaft.	NA	NA	NA
	• Pressurization of lift lobby.	NA	NA	NA
	• Communication in lift car.	Required	Provided	MR
	• Fireman's switch.	Required	Provided	MR
	• Lift signage.	Required	Provided	MR
17	**Standby Power Supply**	Required	Provided	MR
18	**Refuge Area**			
	• Total area	NA	NA	NA
	• Location	NA	NA	NA
19	**Fire Control Room.**			
	• Detector system panel.	Required	Provided	MR
	• Flow switch panel.	NA	NA	NA
	• PA system panel.	Required	Provided	MR
	• Battery backup.	Required	Provided	MR
	• Building floor plan.	Required	Provided	MR
20	**Special Fire Protection System for the Protection of special Risk, if any.**			NA

N/73

M/s Hotel Vivanta by Taj (Ambassador) at Subramania Bharti Marg, Sujan Singh Park, New Delhi-110003

The fire protection system provided in the building/premises were checked, tested at random and found functional at the time of inspection. Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/Hotel/2016/SZ/812 dated 19-05-2016, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

29/5/19

Signature of Inspecting Officer
Name: Mehmood
Design: ADO (SJ)

DO (SD)

30/5/19

Dy. CFO (SZ)

31/5

DELHI FIRE SERVICE
Date 31-5-19
Diary No. 1110
Dy. Chief Fire Officer (SZ)

31/05/19

FTB

ADO (SJ)

Sir, A.F.S. letter may be signed for signature please

CFO 4/6/19

4/6/19