GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI- 110001

NO.F6/DFS/MS/School/2019/SZ/ 1319 Dated: 20/6/19

FIRE SAFETY CERTIFICATE

Certified that the West Point Model School, 12, Om Vihar-III, Uttam Nagar, New Delhi-110059, comprised of ground plus three upper floors was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/School/2016/SZ/655 dated 27.4.2016. The said school building was re-inspected by the officer concerned of this department on 6.6.2019 in presence of Sh. Rajesh Tondon (Manager) and found that the premises have deemed complied with fire prevention & fire safety requirements in accordance with rule 33 of the Delhi Fire service Rules, 2010 and that the building is fit for occupancy class B "Educational building" with effect from...20/6/19.... for a period of **three** years, subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on .....20/6/19..... at New Delhi by

(Rajesh Panwar)
Dy. Chief Fire Officer
Ph. 011-26179168

Copy to:-

1. The Director (Education) GNCT of Delhi, Old Secretariat, New Delhi-110054.
2. The Manager, the West Point Model School, 12, Om Vihar-II, Uttam Nagar, New Delhi-110059.

CONDITIONS

1. All the means of escape shall be kept free of all type of obstruction all the time.
2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.
4. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
6. All comments / directions of licensing Department shall always be permitted and followed.
7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
8. The owner / occupier shall apply for renewal of this **Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37)** along with copy of the certificate, six months prior to its expiry.

Asso Dwelg

INSPECTION REPORT

1	Name & address of the building	West Point Model School, 12, Om Vihar-III, Uttam Nagar, New delhi110059.		
2	Type of Occupancy	Educational Building "B"		
3	Type of case	Renewal **(G+3)**		
4	Details of previous NOC	F6/DFS/MS/School/2016/SZ/655 dated 27.4.2016		
5	Fire safety directives letter No	Old Case		
6	Date of inspection	6.6.2019		
7	Name of the inspecting Officers :	ADO S.P. Bhardwaj		
8	Name and designation of officers from the building side	Rajesh Tondon (Manager)		
9	Year of construction	G+1 1995-96, 2nd & 3rd floor 2011-12		
10	Applicant's letter No.	Nil Dated 20.5.2019	**(Ground plus three upper floors)**	

S. NO.	Minimum Standards on fire prevention and fire safety U/R 33	NBC/BBL Requirement/letter dated 27.4.2016	Provided at site	Remarks MR / NMR
1	**Access to building**			
	1) Road width	Accessible	6 Mtrs.	MR being old case
	2) Gate width	4.5 Mtrs.	4.8 Mtrs.	MR
	3) Width of internal road	N/A	N/A	N/A
2	**Number, width Type & arrangement of exits**			
	a. Number of staircases			
	1. Upper floors	Two	Two	MR
	2. basements	N/A	N/A	N/A
	b. Width of staircase			
	1. Upper floors	150 Cms.	160 & 92 Cms.	MR being old case
	2. basements	N/A	N/A	No basement
	c. Protection of exits			
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	d. No. of continuous staircase to terrace	Required	One	MR
	e. Width of corridor	150 Cms.	186 Cms.	MR
	f. Door size	-	.90 cms	MR being old case
3	**Compartmentation.**			
	1. Fire check door	N/A	N/A	N/A
	2. Sealing of electrical shafts	N/A	N/A	N/A
	3. Fire Rating of shaft door	N/A	N/A	N/A
	4. water curtain	N/A	N/A	N/A
	5. Fire dampers	N/A	N/A	N/A
4	**Smoke Management system.**			
	basement	30 a/c per hour	N/A	No basement
	upper floors	12 a/c per hour	Natural Ventilation	MR

N117

5	**Fire Extinguishers**			
	total numbers	14 Nos. ABC/CO2 type	6 Nos	MR
	Types	ISI Marked	ABC	MR
	ISI marking		Provided	MR
6	**First-Aid Hose Reels.**			
	total numbers on each floor	One each floor	One	MR
	Length of Hose reel hose	30 m	Provided	MR
	Nozzle Diameter	5 mm	Provided	MR
7	**Automatic fire detection and alarming system**			
	Type of detectors	N/A	N/A	N/A
	location of Main Panel	N/A	N/A	N/A
	location of Repeater panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	hooter's location	N/A	N/A	N/A
8	**MOEFA**	N/A	N/A	N/A
9	**Public Address System.**	N/A	Provided	N/A
10	**Automatic Sprinkler System.**			
	basement	N/A	N/A	N/A
	upper floors	N/A	N/A	N/A
	sprinkler above false ceiling	N/A	N/A	N/A
11	**Internal Hydrants**			
	Size of riser/down-corner	N/A	100 mm	MR
	Number of Hydrants per floor	N/A	One	MR
	hose Box	N/A	One	MR
12	**Yard Hydrants.**			
	total number of hydrants	N/A	N/A	N/A
	hose box	N/A	N/A	N/A
13	**Pumping arrangements**			
	1. Ground level			
	a. Discharge of main Pump	N/A	N/A	N/A
	b.Head of main pump	N/A	N/A	N/A
	c.Number of main pumps	N/A	N/A	N/A
	d.jockey pump out put	N/A	N/A	N/A
	e.jockey pump head	N/A	N/A	N/A
	f. Standby Pump output	N/A	N/A	N/A
	g.Stanby Pump head	N/A	N/A	N/A
	h.Auto Starting/Manual stopping	N/A	N/A	N/A
	pump house access	N/A	N/A	N/A
	2.Terrace level			
	a. Discharge of pump	450 LPM	450 LPM	MR
	b. head of the pump	30 M	Provided	MR
	c. Power supply	Required	Provided	MR
	d. Auto starting of pump	N/A	N/A	N/A
14	**Captive water storage for fire fighting**			
	1. Underground tank capacity	N/A	N/A	N/A
	a. Draw-off connection	N/A	N/A	N/A
	b. fire service inlet	N/A	Provided	N/A
	c.Access to tank	N/A	N/A	N/A
	Over head tank Capacity	10,000 Ltrs.	10,000 Ltrs.	MR
15	**Exit Signage.**	Required	Provided	MR

16	**Provision of lifts.**	No lift		
	a. Pressurization of lift shaft	N/A	N/A	N/A
	b. pressurization of lift lobby	N/A	N/A	N/A
	c. communication in lift car	N/A	N/A	N/A
	d. Fireman's grounding switch	N/A	N/A	N/A
	e. Lift signage	N/A	N/A	N/A
17	**Standby power supply**	N/A	N/A	N/A
18	**Refuge Area.**	Not Required		
	total area			
	location			
19	**Fire control room**			
	a. detector system Panel	N/A	N/A	N/A
	b. Flow switch Panel	N/A	N/A	N/A
	c. PA system Panel	N/A	N/A	N/A
	d. Batter backup	N/A	N/A	N/A
	e. Building floor plans	N/A	N/A	N/A
20	**Special Fire Protection systems for protection of special risks, if any:** ABC fire extinguisher provided near electric meter.	MR		

The fire protection systems provided in the building were checked and found functional at the time of inspection. Shortcomings vide letter F6/DFS/MS/School/2019/SZ/2999 dated 21.5.2019 found rectified.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety requirements under the rules, renewal of Fire Safety Certificate vide letter no. F6/DFS/MS/School/SZ/655 dated 27.4.2016 is recommended.

Accordingly DFA is put up for approval and signature please.

S.P. Bhardwaj ADO Dwarka

DFSO - On leave

Dy CFO (SZ)

12/6

DELHI FIRE SERVICE
Date 12-6-19
Diary No. 299
Dy. Chief Fire Officer (SZ)

ADO (Dwark)

FT is put up for signature please

Dy. CFO/SZ

15/6/19