GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/GH/2019/ | (8 3

Dated: 28/8 2019

FIRE SAFETY CERTIFICATE

Certified that Hotel Shubham Vilas located at A-42, Vishal Enclave, Rajouri Garden, New Delhi-110027, running on 2nd & 3rd Floors with 6 guest rooms on each floor (Total 12 Rooms) in a building comprised of Basement, Ground + Three Upper Floors only, was earlier issued FSC by this department vide letter No. F6/DFS/MS/GH/2016/WZ/1142 Dated 14/07/2016. The premises was re-inspected by the officer from this department on dated 22/07/2019 in the presence of Mr. Amit Chadha (Partner) and observed that all the fire prevention & fire safety arrangements as provided in the premises found in good working condition. The premises have therefore deemed complied with the requirements of Rule 33 of Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class Residential Group A-1(i) with effect from 28 / 2019 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 28./8./........ at New Delhi by.

(DHARAMPAL BHARDWAJ) DY. CHIEF FIRE OFFICER.

Copy to :-

- 1. Mr. Amit Chadha (Partner), Hotel Shubham Vilas located at A-42, Vishal Enclave, Rajouri Garden, New Delhi-110027.
- 2. Add. Commissioner of Police (Licensing), First Floor, Police Station, Defence Colony, New Delhi.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided their in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to Non Functional fire safety measure shall be at the responsibility of the management.

3. The trained Fire Fighting staff should be available round the clock.

- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. The Basement shall be used strictly as per the provision of Building Bye- Laws.

6. No temporary structure on terrace/roof will be allowed.

- 7. "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry".
- 8. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The from is available on WWW.dfs.Delhigovt.nic.in
- 9. Fire Door Of minimum 1 hour capacity must be installed at the entrance of staircases at each floor where occupants are more than 10 on each floor and Carbon Mono Oxide detectors with alarm system should be installed in entire building within 3 months of issue of this FSC / NOC otherwise it will be treated null & void.

INSPECTION REPORT

1. Name & address of the building: Hotel Shubham Vilas, A-42, Vishal Enclave, Opp. TDI

Mall, Rajouri Garden, New Delhi-110027.

2. Type of Occupancy : Class-A (Residential)

3. Type of Case: Renewal (on 2nd & 3rd floor only in a building comprising B, G + Three storey building)

4. Details of previous NOC : F6/DFS/MS/GH/2016/WZ/1142 Dated 14/07/2016

5. Fire Safety directives Letter No.: Nil

6. Date of inspection

: 22/07/2019

7. Name of the Inspecting Officer: A.D.O. (JWP)

8. Name and designation of Officer

from the building side

: Mr. Amit Chadha (Partner)

9. Year of Construction : 2008

10. Applicant's letter No.

: -Nil dated 28/06/2019

S No	Minimum standards on fire prevention and fire safety U/R 33	BBL Requirements	Provided at site	Remarks MR/NMR		
1.	Access of building					
1.	Road width	Required	Provided	MR		
	Gate width	NR (On main road (24 mtr)	NR		
	Width of internal road	NR	NR	NR		
2.	Number, width, Type & Arran	ngements of exi	ts			
۷٠	a. Number of staircases					
	Upper floors	2	2	MR		
	Basements	NA	NA	NA		
	b. Width of staircases					
	Upper floors	Old Case	1.23 mtr & 0.94 mtr	MR		
	Basements	NA	NA	NA		
	c. Protection of exits	*#;				
	• Fire check door	NR	NR	NR		
	* 5	NR	NR	NR		
	d. No of continuous	01	Provided	MR		
	staircase to terrace	Old Case	1.34 mtr	MR		
	e. Width Of Corridor	Old Case	0.86 mtr	MR		
	f. Door Size	Old Case	0.00 me			
3.	Compartmentation	Required	Provided	MR		
	Fire check door		NR	NR		
	 Sealing of electrical shafts 	NR				
	Fire Rating of shaft door	NR	NR	NR		
	Water Curtain	NR	NR	NR		
	Fire Dampers	NR	NR	NR		
4.	Smoke managements System	n				
7.	Basements	NR	NR	NR		
	Upper floors	NR	Open	MR		
5.	Fire Extinguishers					
3.	Total numbers	6	6	MR		
	• Types	ISI marked ABC/CO ₂	Provided	MR		
	IS marking	Required	Provided	MR		
		da		X X		

6.	First – Aid Hose Reels	2					
	Total numbers on	1	1	MR			
	each floor		-				
	 Length of hose reel 	30Mtr.	30Mtr.	MR			
	hose						
	Nozzle diameter	5mm.	5mm.	MR			
7.	Automatic fire detection and alarming system						
	 Type of detector 	NA	NA	NA			
	 Location of Main 	NA	NA	NA			
		NA	NA	NA			
	The second secon	NA.	NA	NA			
3							
		NA	NA	NA			
8.	and the second s	Required	Provided	NR			
9.		Required	Provided	NR			
10.		ND	T	T			
	The state of the s						
			- Access				
		NR	NR	NR			
1.1							
11.		100					
		100 mm	100 mm	MR			
		1	1	MD			
		1	1	IVIK			
		1 .	1	MD			
12.		1	1	IVIK			
		NR	NR	NR			
				1410			
	Hose Box	NR	NR 🚄	NR			
13.	Pumping Arrangements						
•	each floor Length of hose reel hose Nozzle diameter Smm. Smm. MR Automatic fire detection and alarming system Type of detector NA Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location NA						
•	Discharge of main pump	NR	NR	NR			
		NR	NR	NR			
			NR	NR			
	J P P o ste P ste			NR			
	J = many out pett						
		INK .	NR	NR			
7		NR	NR	ND			
		1414	INIX	INIV			
>		450 I PM	450 LPM	MD			
>							
				N 2000 0			
			Trovided	INIZ			
14.							
		NR	NR	NR			
-		NID	N.S.				
			- 10 00000				
	7 100055 to talk	141/	IVIT	INK			

	*	11/10				
15	Exit Signage	Required	Provided	M/R		
16.	Provision of Lifts					
30 N	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of lift lobby	Required	Provided	MR		
	Communication in liftCar	Required	Provided	NR		
	Fireman's Grounding Switch	Required	Provided	NR		
	Lift Signage	Required	Provided	NR		
17.	Standby power supply	Required	Provided	MR		
18.	Refuge Area	NR	NR			
	> Total area	NR	NR	NR		
	> Location	NR	NR	NR		
19.	Fire control room					
	Detector system panel	NR	NR	NR		
	> Flow Switch Panel	NR	NR	NR		
	> PA System Panel	Required	Provided	NR		
	Battery backup	Required	Provided	NR		
	> Building Floor Plans	NR	NR	NR		
20.	Special Fire Protection Systems for Protection of special Risks, if any;	NR	NR	NR		

Note:- Basement, Ground & 1st Floor has been given to Bank on lease by the owner.

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection. MCB and Conduit Metal Wiring has also been provided.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the NOC issued vide letter No. F6/DFS/MS/GH/2016/WZ/1142 Dated 14/07/2016 renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

D0/(\$D)

Pl. put up availing to the new gazette notification. I much

Signature of the Inspecting Officer

: A.K. Jaiswal Name Designation: A.D.O. (JWP)

J. F. A. is fut up for signature as por Gazette notopication.