GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/EH/2019/SZ/

1804

Dated: 18/5/2019

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of M/s KASBAH FORUM (A Unit of Fabelhalt Hospitality) at GF, M–74, M–Block Market, Greater Kailash–II, New Delhi–110048, comprised of Basement, Ground + Three Upper Floors but the restaurant running at ground floor only have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 09/09/2019 in the presence of Mr. Rajeev (Manager) and that the premises is fit for occupancy class "Group–D Assembly" (Restaurant) with effect from the date of issue of this certificate for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 18/9/2019 at New Delhi by

Chief Fire Officer Tel. 011-23414250

Copy to: -

- 1. The Dy. Health Officer, South Zone, S.D.M.C., Public Health Department, Green Park, Aurobindo Marg, New Delhi–110016
- 2. The Auth. Signatory, M/s KASBAH FORUM (A Unit of Fabelhalt Hospitality) at GF, M-74, M-Block Market, Greater Kailash-II, New Delhi-110048

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. The owner/occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

		INSPECTIO	N REPORT		*. 1*. X		
1	Name &	Address of the Building	M/s Kasbah Forum	(A U/o Fabelhalt Hos	spitality),		
			Ground Floor, M–7	4, M-Block Market,	Greater		
			Kailash-II, New De	elhi-110048	Г 1.)		
2	Type of	Occupancy	Group-D, "Assembly" (Restaurant at GF only)				
3		Comprised of	Basement, Ground & three upper floors.				
4	Type of		New				
5		of Previous NOC	Nil				
6	Fire Safe	ety Directives Letter No	Nil				
7		Inspection	09-09-2019				
8		the Inspecting Officers	Mehmood, ADO (SJ)				
9	Name &	Designation of Officers	Mr. Rajeev (Manager)				
		building side					
10	Year of	construction	2019	. = 200 1 . 110 00 0	0010		
11		nt letter No.	Outdoor Diary No. 17300 dated 13-08-2019				
S. No.	Minimu	m standards on Fire Prevention	UBBL/NBC-2 016	Provided at Site	Remarks		
	and Fir	e Safety U/R 33	Requirements		MR/NMR		
1	Access	to Building.) (D)		
		Road width	As per MPD-2021	6m	MR		
	•	Gate width	4.5m	Abut on Road	MR		
	•	Width of internal road	N/A	N/A	N/A		
2	Numbe	r, width, type & arrangement of ex	kits.				
		mber of Staircase					
		Upper floors.	N/A	N/A	N/A		
		Basement floor.	N/A	N/A	N/A		
		dth of Staircase					
	>	Upper floors	N/A	N/A	N/A		
	>	Basement floor	N/A	N/A	N/A		
	c) Pro	otection of exits		, # 1			
		Fire check door	N/A	N/A	N/A		
	>	Pressurization	N/A	N/A	N/A		
	-	of continuous staircase to terrace	One	Provided	MR		
		dth of corridor	N/A	N/A	N/A		
	-	or size	2m & 1.5m	2m & 1.5m	MR		
3		artmentation.			3		
	Comp	Fire check door.	N/A	N/A	N/A		
		Sealing of electrical shafts.	N/A	N/A	N/A		
		Fire rating of shaft door.	N/A	N/A	N/A		
		Water curtain	N/A	N/A	N/A		
		Fire dampers.	N/A	N/A	N/A		
4							
4.		e Management system. Basement	30 ACPH	N/A	N/A		
	•	Ground floor	12 ACPH	Provided	MR		
	Trime I		12710111	110,100			
5.		Extinguishers.	Required	6 Nos	MR		
	•	Total numbers	ABC/CO2/W. CO2		MR		
	•	Types	Required	Provided	MR		
	•	ISI Marking	Required	Tiorided	TYLK		
6.		Aid Hose Reels.	One	Provided	MR		
	•	Total numbers on each floor.		THE STATE OF THE S	MR		
	•	Length of hose-reel hose.	30m	Provided			
	•	Nozzle Diameter	5mm	Provided	MR		
7	Auto	matic fire detection & alarming sys	stem.				
	Auto	TD C1	N/A	N/A	N/A		
		Y CM D 1	N/A	N/A	N/A		
	•		N/A	N/A	N/A		
	•	20 tation of the			N/A		
		Alternate source of power	N/A	N/A	N/A		
		Hooter's location	N/A	N/A	NI/A		

8	MOEFA	Required	Provided	/ MR
9	Public Address System	N/A	N/A	N/A
10	Automatic Sprinkler System			
	Basement	N/A	N/A	N/A
	Upper floors.	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants.		1771	1 11/11
	Size of Riser/Down-comer	100 mm	Provided	MR
	Number of Hydrant per floor	One	Provided	/ MR
	Hose box.	One	Provided	/ MR
12	Yard Hydrants.	Offe	Provided	/ IVIK
	Total number of hydrants.	N/A	N/A	N/A
	Hose box.			
13		N/A	N/A	N/A
13	Pumping arrangements.			
	Ground Level Discharge of main nump	21/4		
	Discharge of main pump.Head of main pump.	N/A	N/A	N/A
	Number of main pumps.	N/A	N/A	N/A
	Jockey Pump output.	N/A N/A	N/A N/A	N/A
	Jockey Pump head.	N/A	N/A N/A	N/A N/A
	Standby Pump output.	N/A	N/A	N/A
	Standby Pump head.	N/A	N/A	N/A
	Auto Starting/Manual Stopping.	N/A	N/A	N/A
	Pump house access.	N/A	N/A	N/A
	Terrace Level			
	Discharge of pump.	450 LPM	Provided /	MR
	Head of pump.	40m	Provided	MR
	Power supply.	Required	Provided	MR
1.4	Auto starting of pump.	Required	Provided /	MR
14	Captive water storage for fire fighting.	27/4		
	 Underground tank capacity. Draw-off connection. 	N/A	N/A	N/A
	Fire Service Inlet.	N/A Paguired	N/A	N/A
	Access to tank.	Required Required	Provided Provided	MR
	Overhead tank capacity.	20,000 Ltr	Provided	MR MR
15	Exit Signage.	Required	Provided	
16	Provision of Lifts.	rtoquirou	Trovided	TVIIC
	 Pressurization of lift shaft. 	N/A	N/A	N/A
	Pressurization of lift lobby.	N/A	N/A	N/A
	Communication in lift car.	N/A	N/A	N/A
	• Fireman's switch.	N/A	N/A	N/A
	Lift signage.	N/A	N/A	
17	Standby Power Supply			N/A
18	Refuge Area	Required	Provided	MR
	Total area	N/A	N/A	N/A
	• Location	N/A		
19	Fire Control Room.	IN/A	N/A	N/A
17	Detector system panel.	N/A	NI/A	> T / A
	Flow switch panel.		N/A	N/A
		N/A	N/A	N/A
	PA system panel.	N/A	N/A	N/A
	Battery backup.	N/A	N/A	N/A
•	Building floor plan.	N/A	N/A	N/A
20	Special Fire Protection System for the Prote	action of special D	ick if any	N/A

M/s Kasbah Forum (U/o Fabelhalt Hospitality) at GF, M-74, M Block Mkt, GK-II, New Delhi-110048

The Fire protection systems provided in the premise were checked, tested at random and found functional at the time of inspection. The shortcomings communicated by this department vide letter No. F6/DFS/MS/SZ/EH/2019/5093 dated 22/08/19 (C-18) has been rectified.

Keeping in view of the substantial satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules, 2010.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting

Name: Mehmood Design: ADO (SJ)

A. G. Mort sport all for Johnson