

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/2019/ 62/2134

Dated: 13/11/19

FIRE SAFETY CERTIFICATE

Certified that the Club M/s Next Level (a unit of BRD Services) located at Shop No.-47, Second Floor, Plot No.-4,5,6, West Gate Mall. Rajouri Garden, Delhi is running on 2nd Floor only in a building comprised of 02 Basement+Stilt+Ground+04 upper floors owned / occupied by M/s Club Next Level have complied with the fire prevention and fire safety requirements in accordance NBC (Part-IV) and verified by the officer concerned of Fire Service on 05.11.2019 in presence of Sh. Bhagat Singh and that the building / premises is fit for occupancy class Assembly /Eating House (Group-D)with effect from13/11/19.....for a period of 3 (three) years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS Rules, 2010 subject to conditions printed below.

Issued on13/11/19..... at New Delhi.

(ATUL GARG)
DIRECTOR

Copy to :-

1. Dy. Health Officer, Shivaji Enclave, Rajouri Garden, New Delhi-110027 w.r.t .D-1877/HD/WZ dated 15/10/2019
2. Authorized Signatory, M/s Next Level (a unit of BRD Services) located at Shop No.47, Second Floor, Plot No.-4,5,6, West Gate Mall. Rajouri Garden, Delhi -110027.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided their in shall be maintained in good working conditions at all times.
2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
6. "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry".
7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building: Club Next Level, Shop No.-47, Second Floor, Plot No.-4,5,6, West Gate Mall. Rajouri Garden, Delhi.
2. Type of Occupancy : Assembly
3. Type of Case : New
4. Details of previous NOC : Nil
5. Fire Safety directives Letter No. : NBC (Part-IV)
6. Date of inspection : 05/11/2019
7. Name of the Inspecting Officer : A.D.O. (Jwala Puri)
8. Name and designation of Officer
from the building side : Sh. Bhagat Singh
9. Year of Construction : 2010
10. Applicant's letter No. : D-1877/HD/WZ dated 15/10/2019

S No	Minimum standards on fire prevention and fire safety U/R 33	NBC Requirements	Provided at site	Remarks MR/NMR
1.	Access of building			
	• Road width	6 mtr	18 mtr	MR
	• Gate width	N/A	N/A	N/A
	• Width of internal road	N/A	N/A	N/A
2.	Number, width, Type & Arrangements of exits (Common with the Mall)			
	a. Number of staircases			
	• Upper floors	2	Provided by Mall	MR
	• Basements	N/A	N/A	N/A
	b. Width of staircases			
	• Upper floors	Required	Provided by Mall	MR
	• Basements	N/A	N/A	N/A
	c. Protection of exits			
	• Fire check door	N/A	N/A	N/A
	• Pressurization	N/A	N/A	N/A
	d. No of continuous staircase to terrace	N/A	N/A	N/A
	e. Width Of Corridor	NA	NA	NA
	f. Door Size	2.00mtr & 1.50mtr	2.00mtr x 2	MR
3.	Compartmentation			
	• Fire check door	N/A	N/A	N/A
	• Sealing of electrical shafts	N/A	N/A	N/A
	• Fire Rating of shaft door	N/A	N/A	N/A
	• Water Curtain	N/A	N/A	N/A
	• Fire Dampers			
4.	Smoke managements System			
	• Basements	N/A	N/A	N/A
	• Upper floors	N/A	N/A	N/A
5.	Fire Extinguishers			
	• Total numbers	10	15	M/R
	• Types	ISI marked ABC/CO ₂	Provided	MR
	• IS marking	Required	Provided	M/R

6.	First – Aid Hose Reels			
	• Total numbers on each floor	1	Provided by Mall	MR
	• Length of hose reel hose	30 mtr	Provided by Mall	MR
	• Nozzle diameter	5 mm	Provided by Mall	MR
7.	Automatic fire detection and alarming system			
	• Type of detector	Smoke	Common with Mall	MR
	• Location of Main Panel	Required	Provided	MR
	• Location of Repeater Panel	N/A	N/A	N/A
	• Alternate source of power	Required	Provided	MR
	• Hooters' Location	Required	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	N/A	Provided	N/A
10.	Automatic Sprinkler System			
	• Basements	N/A	N/A	N/A
	• Upper Floor	Required	Provided	MR
	• Sprinkler above false ceiling	Required	Provided	MR
11.	Internal Hydrants			
	• Size of riser/down-comer	150 mm	Common with Mall	MR
	• Number of hydrants per floor	1	Common with Mall	MR
	• Hose Box	1	Common with Mall	MR
12.	Yard Hydrants			
	• Total number of hydrants	NR	NR	NR
	• Hose Box	NR	NR	NR
13.	Pumping Arrangements (Common with Mall)			
	• Ground Level			
	• Discharge of main pump	N/A	Common with Mall	
	➤ Head of main pump	N/A	Common with Mall	N/A
	➤ Number of main pumps	N/A	Common with Mall	N/A
	➤ Jockey pump out put	N/A	Common with Mall	N/A
	➤ Jockey pump head	N/A	Common with Mall	N/A
	➤ Standby Pump out put	N/A	Common with Mall	N/A
	➤ Standby Pump Head	N/A	Common with Mall	N/A
	➤ Auto Staring/Manual stopping	N/A	Common with Mall	N/A
	➤ Pump House Access	N/A	Common with Mall	N/A
	• Terrace level			
	➤ Discharge of pump	900 LPM	Common with Mall	MR
	➤ Head of the pump	40 MH	Common with Mall	MR
	➤ Power supply	Required	Common with Mall	MR
	➤ Auto starting of pump	Required	Common with Mall	MR
14.	Captive water Storage for fire fighting (Common with Mall)			
	• Underground tank capacity	N/A	2,50,000 ltr	N/A
	➤ Draw of connection	N/A	Common with Mall	N/A
	➤ Fire service inlet	NA	Common with Mall	NA

15.	Exit Signage	Required	Provided	MR
16.	Provision of Lifts			
	➤ Pressurization of Lift Shaft	N/A	N/A	N/A
	➤ Pressurization of lift lobby	N/A	N/A	N/A
	➤ Communication in lift Car	N/A	N/A	N/A
	➤ Fireman's Grounding Switch	N/A	N/A	N/A
	➤ Lift Signage	N/A	N/A	N/A
17.	Standby power supply	Required	Provided by Mall	MR
18.	Refuge Area	N/A	N/A	
	➤ Total area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
19.	Fire control room			
	➤ Detector system panel	N/A	N/A	N/A
	➤ Flow Switch Panel	N/A	N/A	N/A
	➤ PA System Panel	N/A	N/A	N/A
	➤ Battery backup	N/A	N/A	N/A
	➤ Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection Systems for Protection of special Risks, if any;	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards of fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

80/100

6/11/19

24/10/19

6/11/19

cto on MR
Director 7/11/19

Pls Spk.

DDXW

Spoken with Director;
F.T. letter is put up for signature please. 13/11/19

Director DGS

Signature of the Inspecting Officer
Name : A.K. Jaiswal
Designation : A.D.O. (Jwala Puri)