GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001

No.F.6/DFS/MS/School/2019/SZ/ 213 (

Dated: 14/11/19

FIRE SAFETY CERTIFICATE

Certified that the **Muni International School,** A-2/16-18, Mohan Garden, (Near Gandhi Chowk), Uttam Nagar, New Delhi-110059 comprised of ground floor plus one upper floor, owned/occupied by Muni International School was issued NOC by this department vide letter no. F.6/DFS/MS/2007/2313 dated 22.08.2007. The School building was re-inspected by the officer concerned of this department on 01.11.2019 in the presence of Smt. Asha (H.O.S) and found that now school building is comprised of ground plus three upper floors. Muni International School have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class educational w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE

orc

Copy to:-

- The Principal, Muni International School, A-2/16-18, Mohan Garden, (Near Gandhi Chowk), Uttam Nagar, New Delhi-110059
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

1. Name & address of the building: Muni International School, A-2/16-18, Mohan Garden, (Near Gandhi

Chowk), Uttam Nagar, New Delhi-110059.

Type of Occupancy
 Type of Case
 New/Renewal

4. Details of Previous NOC : F.6/DFS/MS/2007/2313 dated 22.08.2007 (For GF & FF Only)

5. Fire Safety directives letter No : N/A6. Date of inspection : 01.11.2019

7. Name of Inspecting Officer : A.D.O. Sandeep Duggal

8. Name and designation of officers

From the building side : Smt. Asha (H.O.S)

9. Year of Construction : 2007 (GF & FF) & 2012 (II nd & III rd)

10. Applicant's letter No. : MIS/2019 dated 09.09.2019

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC requirements	Provided at site	Remarks MR/NMR
1.	Access to building			
. 5	Road widthGate widthWidth of internal road	Accessible 06 mtrs 4.5 mtrs. N/A	Provided Directly accessible from road N/A	M/R M/R N/A
2.	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases Upper Floors	02 No.'s	03 No.'s	M/R
	Basements	N/A	N/A	N/A
	b. Width of staircases Upper Floor	150 cms & 75 cms	150, 140 to 120 & 84 cms	M/R
	Basements c. Protection of exits	N/A	N/A	N/A
	Fire check door		2	
	Pressurization	N/A	N/A	N/A
		N/A	N/A	N/A
	d. No. of continuous staircases to		, *** a	
	terrace e. Width of Corridor	Required	Provided	M/R
	c. Thui of contact	150 cms.	190 cms	M/R
	f. Class room Door Size	100 cms	87 cms GF & FI & 120 cms on S & TF	
3.	Compartmentation			*!
	Fire check door	N/A	N/A	N/A
	Sealing of electrical shafts	N/A	N/A	N/A
	Fire Rating of shaft door	N/A	N/A	N/A
	Water Curtain	N/A	N/A	N/A
	Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System			
	Basements	N/A	N/A	N/A
	• Upper floors	Required	Natural ventilation provided	M/R
5.	Fire Extinguishers			
	Total numbers	02 no's per floor	Provided	M/R
	Types	ABC/CO ₂ type	Provided	M/R
	IS marking	ISI marked	Provided	M/R
6.	First-Aid Hose Reels			_
×	Total numbers	01 no. per floor	Provided	M/R
	Length of hose reel hose	30 mtrs	Provided	M/R
-	Length of hose reel hose	5 mm	Provided	M/R

7.	Automatic fire detection and alarming system			
	Type of detectors	N/A	N/A	N/A
	 Location of Main Panel 	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of powerHooters' Location	N/A	N/A	N/A
		N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System • Basement	N/A	N/A	N/A
	Ground Floor	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	Size of riser/down-comer	N/A	N/A	N/A
	 Number of hydrants per floor 	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
12.	Yard Hydrants			
	 Total number of hydrants 	N/A	N/A	N/A
40	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements			
	Ground Level			
	Discharge of main Pump	N/A	N/A	N/A
	> Head of Main pump	N/A	N/A	N/A
	Number of main pumpsJockey Pump out put	N/A	N/A	N/A
	> Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	Auto Starting/Manual Stopping	N/A	N/A	N/A
	* g	N/A	N/A	N/A
		N/A	N/A	N/A
	> Pump House Access			
	Terrace levelDischarge of pump	450 LPM	Provided	M/R
	> Head of the pump	40 mtrs	Provided	M/R
	> Power Supply	Required	Provided	M/R
	Auto Starting of pump	Required	Provided	M/R
14.	Captive Water Storage for fire fighting	i e		
	Underground tank capacity	N/A	N/A	N/A
	Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	10000 ltrs	Provided	M/R
15.	Exit Signage.	Required	Provided	M/R
16.	Provision of Lifts.		No Lift	
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
17.	Standby power supply	N/A	N/A	N/A
	- Sandy Pourse on Phys		2	
18.	Refuge Area.		-	3 × 2
	> Total Area	N/A	N/A	N/A
	> Location	N/A	N/A	N/A

19.	Fire Control Room					
	Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans	N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
		N/A	N/A	N/A		
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested, checked and found not functional at the time of inspection. The shortcomings communicated by this department vide letter no. F.6/DFS/MS/School/2017/SZ/1149 dated 04.05.2017 have been complied.

In view of the compliance of the minimum standards of fire prevention and fire safety measures as required under the rule 35 of the Delhi Fire Service Rules 2010 it is recommended to grant Fire Safety Certificate.

Note: Earlier FSC was issued by this department vide letter no. F.6/DFS/MS/2007/2313 dated 22.08.2007 for ground plus one upper floor only

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation: - Asstt. Divisional Officer

Divisional Officer (South West)

sw? 15.86du