GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/EH/2019/SZ/ 2202

Dated: 2 11/19

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of M/s Highbae (A Unit of Donna Bar and Kitchen Pvt. Ltd.) situated at Shop no. 3 & 4, Ground Floor, Dhaula Kuan, Metro Station, Delhi–110010, comprised of Basement, Ground + 02 Upper floors. The restaurant running at Ground floor of the building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Delhi Fire Service on 05/11/2019 in the presence of Mr. Sanjay Pandey and that the premise is fit for occupancy class Group—D Assembly (Eating House) with effect from the date of issue of this certificate for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010

Issued on 22/11/2019 at New Delhi by

(Vipin Kental) Chief Fire Officer, Delhi Fire Service

si go

Copy to: -

- 1. The Joint Comm. of Police (Lic.), First floor, P.S. Defence Colony, New Delhi-110049
- 2. The Revenue Supdt., Delhi Cantonment Board, Delhi Cantonment, Sadar Bazar, Delhi-10 w.r.t letter no. DCD/4/RS/Trade Licence/2019 dated 17/10/2019
- 3. M/s **Highbae** (A Unit of Donna Bar and Kitchen Pvt. Ltd.), Shop no. 3 & 4, Ground Floor, Dhaula Kuan, Metro Station, Delhi–110010

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."
- 7. This FSC will become null & void, if the FSC of the main premise is not renewed under rule 37 of DFS Rules-2010

TAL TO INSPECTION REPORT Name & Address of the Building M/s Highbae (A Unit of Donna Bar and Kitchen Pvt. Ltd.) located at Shop no. 3 & 4, Ground Floor, Dhaula Kuan, Metro Station, Delhi-110010 Assembly 'Group-D' (Restaurant at 2pd Floor) 2 Type of Occupancy 3 Building comprised of Basement, Ground + 02 Upper floors. 4 Type of Case New 5 Details of Previous NOC Nil Fire Safety Directives Letter No 6 Nil 7 Date of Inspection 05-11-2019 8 Name of the Inspecting Officers S K Dua, DO (SD) 9 Name & Designation of Officers Sh. Sanjay Pandey from the building side 10 Year of construction 2010 FSC has been issued to Macsen Consultancy India Pvt. Ltd. at CPD-05R PD Area (Food Court) vide letter no.F.6/DFS/MS/EH/2019/SZ/687 dated 02-04-2019 11 Applicant letter No. Outdoor Diary No. 22959 dated 17/10/2019 S. No. Minimum standards on Fire Prevention BBL/NBC-2005 Remarks Provided at Site and Fire Safety U/R 33 Requirement MR/NMR 1 Access to Building. F.6/DFS/MS/EH/2019/SZ/687 dated 02-04-2019 Road width Restaurant As above MR Gate width within PD As above -NA-Area Width of internal road As above -NA-2 Number, width, type & arrangement of exits **Number of Staircase** Provided & Maintained by DMRC Management Upper floors -NA-As above -NA-Basement floor -NA-As above -NA-Width of Staircase Provided & Maintained by DMRC Management Upper floors -NA-As above -NA-Basement floor -NA-As above Protection of exits Provided & Maintained by DMRC Management Fire check door -NA-As above -NA--NA-Pressurization As above -NA-No. of continuous staircase to terrace Required MR As above Width of corridor 2.5 m As above MR Door size 2m/1.5m 2m & 1.85m MR 3 Compartmentation. Provided & Maintained by DMRC Management Fire check door. -NA-As above -NA-Sealing of electrical shafts. -NA-As above -NA-Fire rating of shaft door. -NA--NA-As above Water curtain -NA-As above -NA-Fire dampers. As above -NA--NA-4 Smoke Management system. Provided & Maintained by DMRC Management Basement 30 ACPH N/A N/A Upper floors 12 ACPH Provided in Kitchen MR 5 Fire Extinguishers. Total numbers Required 06 Nos MR Types ABC / CO2 ABC & Co2 MR ISI Marking ISI marked Provided MR 6 First Aid Hose Reels. Provided & Maintained by DMRC Management Total numbers on each floor. One As above MR Length of hose-reel hose. 30m As above MR Nozzle Diameter 5mm As above MR 7 Automatic fire detection & alarming system. Provided & Maintained by DMRC Management Type of detectors -NA-As above -NA-Location of Main Panel -NA-As above -NA-

M/s **Highbae** (A Unit of Donna Bar and Kitchen Pvt. Ltd.). Shop no. 3 & 4, Ground Floor, Dhaula Kuan, Metro Station, Delhi–110010

3	MOEFA	Required	As above	MR		
)	Public Address System	-NA-	As above	-NA-		
0	Automatic Sprinkler System	The DMPC M				
10		-NA-	As above	-NA-		
	• Basement	-NA-	As above	-NA-		
	• Upper floors	-NA-	As above	-NA-		
	Sprinkler above false ceiling		ntained by DMRC M	anagement		
11	Internal Hydrants.	, NA				
	Size of Riser/Down-comer	-NA-	As above			
	 Number of Hydrant per floor 	-NA-	As above	-NA-		
	 Hose box. 	-NA-	As above	-NA-		
12	Yard Hydrants.	Provided & Maintained by DMRC Management				
		-NA-	As above	-NA-		
	Total number of hydrants.	-NA-	As above	-NA-		
	Hose box.			- time bldg		
13	Pumping arrangements.	Pumping arrangements are common for entire bldg.				
	Ground Level	Provided & Maintained by DMRC Management				
		-NA-	4500 LPM	-NA-		
	Discharge of main pump.	-NA-	80 mtr	-NA-		
	Head of main pump.	-NA-	One	-NA-		
	Number of main pumps.Jockey Pump output.	-NA-	180 LPM	-NA-		
	> Jockey Pump head.	-NA-	80 mtr	-NA-		
	> Standby Pump output.	-NA-	4500 LPM	-NA-		
	Standby Pump head.	-NA-	80 mtr Provided	-NA-		
	> Auto Starting / Manual Stopping.	-NA-	Provided	-NA-		
	> Pump House Access	-NA-	Pumping arrangements are common for entire bldg.			
	Terrace Level		As above	MR		
	Discharge of pump.	450 LPM 40m	As above As above	MR		
	> Head of pump.	Required	As above	MR		
	Power supply.Auto starting of pump.	Required	As above	MR		
14	Captive water storage for Fire Fighting.	Fire Safety Systems are common for entire bldg.				
14		-NA-	4,60,000 Ltr	-NA-		
	Underground tank capacity.	-NA-	Provided	-NA-		
	Draw-off connection.Fire Service Inlet.	-NA-	Provided	-NA-		
	Access to tank.	-NA-	Provided	-NA-		
	Overhead tank capacity.	10,000 Ltr	As above	MR		
15	Exit Signage.	Required	Provided	MR		
16	Provision of Lifts.	Provided & Maintained by DMRC Managem		Managemen		
10		-NA-	As above	-NA-		
	Pressurization of lift shaft.	-NA-	As above	-NA-		
	• Pressurization of lift lobby.	-NA-	As above	-NA-		
	Communication in lift car.	-NA-	As above	-NA-		
	• Fireman's switch.	-NA-	As above	-NA-		
	Lift signage.					
17	Standby Power Supply	Required	Provided	MR		
18						
	Total area	-NA-	-NA-	-NA		
	• Location	-NA-	-NA-	-NA		
1		Provided & Maintained by DMRC Managemen				
	Detector System Panel.	-NA-	As above	-NA		
	• Flow Switch Panel.	-NA-	As above	-NA		
	I IOW DWITCH I WHO!	-NA-	As above	-NA		

7		NIBT.		
Special Fir Protection	e Protection System for the of special Risk, if any:	-NA-	As above	-NA-
M/s Highbae (A Unit o	f Donna Bar and Kitchen Pvt. Ltd.) S	Shop no. 3 & 4, Gro	ound Floor, Dhaula Kuan, I	Metro Station,
	otection systems provided in			
functional at the tin	ne of inspection.			~

d functional at the time of inspection.

Keeping in view the substantial satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules, 2010.

Accordingly, DFA is put up for approval and signature please.

LIV TOSALI Signature of the Inspecting Officer

Name: S.K. Dua Designation: DO (SD)

The inspection report of FSC den't medels
with respect to location of restament.
The need-ful may be done

Grand floor only. Notesheet has been corrected.

Culmitted bl., Living.