GOVERNMENT OF NATIONAL CAPITAL TÉRRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE **NEW DELHI- 110 001**

No. F6/DFS/MS/Hotel/2019/NDZ/ 2234

Dated: 27 11 8

FIRE SAFETY CERTIFICATE

Certified that the M/s Hotel Fraser Suits located at Plot No. 4A, Distt Centre, Mayur Vihar, Delhi-110096, comprised of three basement, ground plus nine upper floors owned/occupied by M/s Hotel Fraser New Delhi was issued FSC vide letter No. F6/DFS/MS/Hotel/2016/NDZ/1069 dated 15/11/16. The hotel building was re-inspected by the officer concered of this department in the presence Mr. Kulbushan Dhawan (G.M.) and found that the hotel have deemed complied with the fire prevention and fire safety requirements in accordance with the rule 33 of Delhi Fire, Service Rules 2010 and observed that the building are fit for occupancy Group A "Hotel Building" with effect from 27 (u/4.9... for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the condition under rule 38 of the Delhi Fire Service Rules, 2010, subject to conditions printed Below.

Issued on ...2.7..(11) at New Delhi by

Chief Fire Officer. Delhi Fire Service

Copy to:-

- 1. The Joint Commissioner of Police(Lic.) 1st Floor, Police Station, Defence Colony, New Delhi
- 2. Mr. Kulbhushan Dhawan (G.M.) M/s Hotel Fraser Suits located at Plot No. 4A, Distt Centre, Mayur Vihar, Delhi-110096

Conditions for the validity of Fire Safety Certificate

1. All the means of escape shall be kept free of all type of obclauction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipment shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.

4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities. 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized

construction /unauthorized use of land if any. 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

7. The owner / occupier shall apply for renewal of this Fire Saíety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry.

1. Name & address of the building

: Hotel Fraser Suits

Plot No. 4A, Distt Centre, Mayur Vihar, Delhi-96

2. Building is comprised of

3. Type of Occupancy

4. Type of Case

5. Details of Previous NOC letter

6. Fire Safety directive letter No

7. Date of Inspection

8. Name of the Inspecting officers

9. Name and designation of officer from the building side

10. Year of construction

11. Applicant's letter No

: 03 Basement plus 09 upper floor

: Residential (Hotel Building)

: Renewal

: F6/DFS/MS/Hotel/2016/NDZ/1069 dt 15/11/16

: F6/DFS/MS/BP/Hotel/2009/1940 dated 02/07/09

: 11/11/2019

: DO F. Brown

: Mr. Kulbushan Dhawan (G.M.)

: 2009

: Nil, Dated-02/11/2019

Sr. No.	Minimum Standards on Fire Prevention and Fire Safety U/R3:		Provided at Site	Remark MR/NMI			
01	Access to Building.	Guidelines		- TOTAL			
	Road width	12 mtr.	30 mtr.	MFR			
	Gate width Width of interest.	4.50 mtr.	06 mtr.	MFR			
02	Width of internal road Number, Width, Type and A	06 mtr.	06 mtr	MF			
	Arrangement of Exits.						
	a. Number of Staircases						
	Upper floor	02 nos	02				
	 Basement 	03nos. +	03 nos	MR			
	D Midu COL	Ramp	04 nos. + 01 ramp	MR			
	B. Width of Staircases						
	Upper floor	1.50 mtr.	1.50 mtr & 1.25 mtr	MR			
	Basement	1.50 mtr &	1.50 mtr & 1.25 mtr	MR			
	c. Protection of Exits	1.25 mtr	20 1110	IVIT			
	Fire check door						
	Pressurization	Required	Provided	MR			
	d. No. of Continuous Staircases	Required	Provided	MR			
	to Terrace	02 nos	03 nos	MR			
	e. Width of Corridor	1.50 mtr.					
	f. Door Size	01 mtr.	1.50 mtr.	MR			
3	Compartmentation.	OT IIIII.	01 mtr.	MR			
	Fire check door						
	Sealing of electrical shafts	Required	Provided	MR			
	Fire rating of shaft door	Required	Sealed	MR			
	Water curtain	02 hrs N/A	Provided	MR			
	Fire dampers	Required	N/A	N/A			
	Smoke Management System./	required	Provided	MR			
	Basement	00 /	ж.	25			
	Upper floor	30a/c per hrs	Provided	MR			
. F	ire Extinguishers.	12a/c per hrs	Provided	MIR			
	 Total numbers 	6.5					
	Types	60 nos.	70 nos.	MR			
	IS marking	ABC /CO ₂	ABC /CO ₂	MR			
	sirining	IS! marked	ISI marked	MR			

3	First-Aid-Hose Reels.			NAID		
	Total numbers on each floor	02 no.	02 no.	MR		
	Length of hose reel hose	30 mtr.	30 mtr.	MR		
	Nozzle diameter	05 mm	05 mm	MR		
7	Automatic Fire Detection and Alarming Sys	stem.				
		Smoke/Heat	Provided	MR		
	Type of detectors	1 st Bsement	Provided	MR		
	Location of main panel	Security Room	Provided	MR		
	Location of repeater panel	Batter & DG Set	Provided	MR		
	Alternate source of power	Staircase	Provided	MR		
	Hooter's location	Required	Provided	MR		
8(MOEFA	Required	Provided	MR		
)9	Public Address System.	required				
10	Automatic Sprinkler System.					
	Basement	Required	Provided	MR		
	upper floor (P. S. only)	Required	Provided	MR		
	sprinkler above false ceiling	Required	Provided	MR		
11	Internal Hydrants		¥			
1. 1.		150 mm	150 mm	MR		
	size of riser/down-comer New hor of hydronts per floor	02 nos.	02 nos.	MR		
	Number of hydrants per floor	02 nos.	02 nos.	MR		
	Hose box		ele F			
12	Yard Hydrants.		04 200	MR		
	 Total number of hydrants 	04 nos.	04 nos 04 nos.	MR		
	Hose box	04 nos.	04 1105.	IVIIX		
13	Pumping Arrangements.					
	> Ground Level					
	Discharge of main pump	2850 Lpm	2850 Lpm	MR		
	Discharge of main pump Head of main pump	100 M	100 M	MR		
	Number of main pumps	02 no.	02 no.	MR		
	Jockey pump out put	180 Lpm x 2nos.	180 Lpm x 2nos.	MR		
	la la same hood	100 M	100 M	MR		
	Of the street out out	2850 Lpm.	2850 Lpm.	MR		
	Ol - Il muman hood	100 M	100 M	MR		
	a to the discount of stopping	Required	Provided	MR		
	 Auto starting /maridal stopping Pump house access 	Required	Provided	MR		
	Terrace Level					
		900 lpm	900 lpm	MF		
	Discharge of pump	70 mtr	70 mtr	MF		
	Head of the pump	Required	Provided	MF		
	Power supply	Required	Provided	MF		
	Auto starting of pump					
14						
	 Underground tank capacity 	2,00,000 Ltr.	2,00,000 Ltr	MI		
	Draw-off connection	Required	Provided	M		
	Fire service inlet	Required	Provided	M		
	Access to tank	Required	Provided	M		
	Overhead tank capacity	20,000 Ltr.	20,000 Ltr.	M		
	5 Exit Signage.	Required	Provided	IVI		



16	Provision of Lifts.					
	Pressurization of lift shaft	Required	Provided	MR		
	Pressurization of lift lobby	Required	Provided	MR		
	Communication in lift car	Required	Provided	MR		
	Firemen's grounding switch	Required	Provided	MR		
	Lift signage	Required	Provided	MR		
17	Standby Power Supply	Required	Provided	MR		
18	Refuge Area.					
	Total area	183.18 mtr	183.18 mtr	MR		
	 Location 	రో డి 8 th floor	Provided	MR		
19	Fire Control Room					
	Detector system panel	Required	Provided	MR		
	Flow switch panel	Required	Provided	MR		
	 PA system panel 	Required	Provided	MR		
	Battery backup	Required	Provided	MR		
	Building floor plans	Required	Provided	MR		
20	Special Fire Protection systems for protection of special Risks, if Any:	Required for HT/LT Panels	Provided	MR		

The fire protection systems provided in the building were tested/checked and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire directive letter NO. the required under and fire safety prevention F6/DFS/MS/BP/Hotel/2009/1940 dated 02/07/09, it is recommended to renew Fire Safety

Certificate.

Signature of the Inspecting Officer

Name

: F. Brown

Designation : D.O (E.D.)