GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6 / DFS / MS / School/2019 / 2228

Dated: 27/11 / 2019

FIRE SAFETY CERTIFICATE

Certified that the M.C.D Primary Girls School located at I-Block (New) J.J Colony, Sawda Ghewra, Delhi-110081 comprised of Ground + 01 upper floor owned/occupied by M.C.D Primary Girls School was granted FSC by this department vide letter no.F6/DFS/MS/School/2016/WZ/988 dated 09.06.2016 The premises was re-inspected by the officer concerned of this department on 06.11.2019 in presence of Sh. Suresh Bala (Principal) and observed that all the fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education vide letter no 3298-3398 dated 01.03.2011 and the building/ premise is fit for occupancy class Group B Educational with effect from mentioned below:

Issued on at New Delhi by

(Dharampal Bhardwaj) Dy.Chief Fire Officer Ph.-011-25104544

Copy to: -

- 1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi 110054.
- The Principal, MCD Primary Girls School, I-Block (New) J.J Colony, Sawda Ghewra, Delhi-110081.

Conditions for the validity of Fire Safety Certificate:

All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of firefighting system.

The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.

This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if

"The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its

INSPECTION REPORT

1. Name & address of the building : MCD Primary Girls School, I-Block (New) J.J Colony, Sawda Ghewra, Delhi-81.

2. Type of Occupancy :Educational

.Educational

3. Type of Case

: Renewal (G+1 upper Floors)

4. Details of previous NOC

: F6/DFS/MS/School/2016/WZ/988 dated: 09.06.2016

5. Fire Safety directives letter No

: Director of Education Circular dated 01.03.2011

6. Date of inspection

: 06.11.2019

7. Name of the Inspecting Officers

: ADO (RN)

8. Name and designation of officers

from the building side

: Sh. Subhash Chandar (Principal)

9. Year of Construction


. 2009

10. Applicant's letter No.

: Nil Dairy No.1887 Dated: 26.09.2019

	Minimum Standards on fire prevention and fire safety U/R 33	Circular of Director of Education	Provided at site	Remarks MR/NMR	
1	Access to building				
	Road width	Accessible	Accessible	MR	
	Gate width	Accessible	Accessible	MR	
	Width of internal road	NA	NA	NA	
2	Number, Width, Type & Arrangement of Exits				
	a. Number of staircases				
	Upper Floors	02	02	MR	
	Basements	NA	NA	NA	
	b. Width of staircases				
	Upper Floors	1.50m	1.50m each	MR	
	Basements	NA	NA	NA	
	c. Protection of exits				
	Fire check door	NA	NA	NA	
	Pressurization	NA	NA	NA	
	d. No. of continuous staircases to terrace	NA	NA	NA	
	e. Width of Corridor	NA	NA	NA	
	f. Door Size	1 m	1m double door	MR	
3	Compartmentation.				
	Fire check door	NA	NA	NA	
	Sealing of electrical shafts	NA	NA	NA	





	Hose Box	NA	NA	NA		
3	Pumping Arrangements.					
	Ground Level					
	Discharge of main Pump	N/A	N/A	N/A		
	Head of Main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	> Jockey Pump out put	,	N/A	N/A		
	> Jockey pump head	N/A N/A	N/A N/A	N/A		
	Standby Pump out put					
	Standby Pump Head Auto Starting/ Manual stanning	N/A	N/A	N/A		
	Auto Starting/ Manual stoppingPump House Access	N/A	N/A	N/A		
	Terrace level	N/A	N/A	N/A		
	Discharge of pump					
	➤ Head of the pump	NA	N/A	NA		
	Power Supply	NA	N/A	NA		
	Auto Starting of pump	N/A	N/A	N/A		
		N/A	N/A	N/A		
14	Captive Water Storage for fire fighting.					
	Underground tank capacity	NA	NA	NA		
	> Draw-off connection	NA	NA	NA		
	Fire service inlet	NA	NA	NA		
	> Access to tank	NA	NA	NA		
	Overhead Tank capacity	NA	N/A	NA		
5	Exit Signage.	NA	NA	NA		
16	Provision of Lifts.					
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	N/A	N/A	N/A		
	Fireman's Grounding Switch					
	Lift Signage	N/A	N/A	N/A		
		N/A	N/A	N/A		
7	Standby power supply	N/A	N/A	N/A		
18	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		

9	Fire Control Room			77/4
	Detector System Panel	N/A	N/A	N/A
	Flow Switch PanelPA System Panel	N/A	N/A	N/A
		N/A	N/A	N/A
	Batter backup	N/A	N/A	N/A
	Building Floor Plans	- 20 5 12	N/A	N/A
		N/A	N/A.	N/A
0	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	IV/IX.	

The fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in director of education Circular dated 01.03.2011, it is recommended to renewal of fire safety certificate issued vide this department letter of even no.988 dated 09.06.2016.

Recived on 19/8/19 DOINWO

Signature of the Inspecting Officer Name: - Rajesh Kumar

Designation: - ADO/RN

bettel en putup