

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F.6/DFS/MS/School/2019/SZ/ 2184

Dated: 22/11/19

FIRE SAFETY CERTIFICATE

Certified that the M.G. Public School located at J-29, Sourabh Vihar, Badarpur, New Delhi- 110044 comprised of ground plus one upper floor was issued NOC by this department vide letter No. F6/DFS/MS/2006/3286 Dated 08/11/2006. The premises was re-inspection by officer concerned by this department on 11/11/2019 in the presence of Mr. Mishra (Manager) of the school and found that fire prevention and fire safety requirements have deemed complied in accordance with Circular No. 262-362 dated 17/01/05 issued by Education Directorate, Govt. of NCT of Delhi, Old Secretariat, New Delhi and that the premises fit for occupancy class Education Building, Group-B as above with effect from the date of issue of this certificate for period of three years subject to compliance of conditions mentioned below.

Issued on 22/11/19 at New Delhi by

(Rajesh Panwar)
Dy. Chief Fire Officer
Tel: 011-26189168
dlc
Ar

Copy to: -

1. The Principal, M.G. Public School, J-29, Sourabh Vihar, Badarpur, New Delhi-110044.
2. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi.

Conditions for the validity of Fire Safety Certificate

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of firefighting system.
4. This Certificate cannot be treated as regularization of unauthorized construction, if any.
5. The Owner/Occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available on www.dfs.delhigovt.nic.in.
6. The Owner/Occupier shall apply for renewal of this Fire Safety Certificate to the Director in the form 'J' [sub rule (1) of rule 37] along with copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in.

1	Name & Address of the Building	M.G.Public School, J-29, Sourabh Vihar, Badarpur, New Delhi- 110044		
2	Type of Occupancy	Educational Building Group-B (School)		
3	Building Comprised of	Ground + 01 upper floor		
4	Type of Case	Renewal		
5	Details of Previous NOC	F6/DFS/MS/2006/3286 Dated 08/11/2006		
6	Fire Safety Directives Letter No	DOE Circular 262-232 Dated 17/01/2005		
7	Date of Inspection	11/11/2019		
8	Name of the Inspecting Officers	ADO Avtar Singh		
9	Name & Designation of Officers from the building side	Mr. Mishra (Manager)		
10	Year of construction	2000		
11	Applicant letter No.	Outdoor Diary no 16786 dt 05/08/2019		
S. No	Minimum standards on Fire Prevention and Fire Safety U/R 33	DOE Circular dated 01/03/2011 Requirement	Provided at Site	Remarks MR/NMR
1	Access to Building.			
	• Road width	Accessible	Provided	MR
	• Gate width	-N/A-	-N/A-	-N/A-
	• Width of internal road	-N/A-	-N/A-	-N/A-
2	Number, width, type & arrangement of exits.			
	a) Number of Staircase			
	➤ First floors	02 nos	02 nos	MR
	➤ Second floor	-N/A-	-N/A-	-N/A-
	b) Width of Staircase			
	➤ First floors	1.5 m & 0.75 m	1.06, 1.06 & 0.98 m	MR(old case)
	➤ Second floor	-N/A-	-N/A-	-N/A-
	c) Protection of exits			
	➤ Fire check door	-N/A-	-N/A-	-N/A-
	➤ Pressurization	-N/A-	-N/A-	-N/A-
	d) No. of continuous staircase to terrace	One	One	MR
	e) Width of corridor	-N/A-	-N/A-	-N/A-
	f) Door size	1.0 m	1.0 m	MR
3	Compartmentation.			
	• Fire check door.	-N/A-	-N/A-	-N/A-
	• Sealing of electrical shafts.	-N/A-	-N/A-	-N/A-
	• Fire rating of shaft door.	-N/A-	-N/A-	-N/A-
	• Water curtain	-N/A-	-N/A-	-N/A-
	• Fire dampers.	-N/A-	-N/A-	-N/A-
4.	Smoke Management system.			
	• Basement	30 ACPH	-N/A-	-N/A-
	• Upper floors	12 ACPH	-N/A-	-N/A-
5.	Fire Extinguishers.			
	• Total numbers	06 nos	06 nos	MR
	• Types	ABC / Co2	ABC & Co2	MR
	• ISI Marking	Provided	Provided	MR
6.	First Aid Hose Reels.			
	• Total numbers on each floor	One	Provided	MR
	• Length of hose-reel hose.	30 m	Provided	MR

	• Nozzle Diameter	5 mm	Provided	MR
7	Automatic fire detection & alarming system.			
	• Type of detectors	-N/A-	-N/A-	-N/A-
	• Location of Main Panel	-N/A-	-N/A-	-N/A-
	• Location of Repeater Panel	-N/A-	-N/A-	-N/A-
	• Alternate source of power	-N/A-	-N/A-	-N/A-
	• Hooter's location	-N/A-	-N/A-	-N/A-
8.	MOEFA	-N/A-	-N/A-	-N/A-
9.	Public Address System	-N/A-	-N/A-	-N/A-
10.	Automatic Sprinkler System			
	• Basement.	-N/A-	-N/A-	-N/A-
	• Upper floors	-N/A-	-N/A-	-N/A-
	• Sprinkler above false ceiling	-N/A-	-N/A-	-N/A-
11.	Internal Hydrants.			
	• Size of Riser / Down-comer	-N/A-	-N/A-	-N/A-
	• Number of Hydrant per floor	-N/A-	-N/A-	-N/A-
	• Hose box.	-N/A-	-N/A-	-N/A-
12.	Yard Hydrants.			
	• Total number of hydrants.	-NA-	-NA-	-NA-
	• Hose box.	-NA-	-NA-	-NA-
13.	Pumping arrangements.			
	• Ground Level			
	Discharge of main pump.	-N/A-	-N/A-	-N/A-
	➤ Head of main pump.	-N/A-	-N/A-	-N/A-
	➤ Number of main pumps.	-N/A-	-N/A-	-N/A-
	➤ Jockey Pump output.	-N/A-	-N/A-	-N/A-
	➤ Jockey Pump head.	-N/A-	-N/A-	-N/A-
	➤ Standby Pump output.	-N/A-	-N/A-	-N/A-
	➤ Standby Pump head.	-N/A-	-N/A-	-N/A-
	➤ Auto Starting/Manual stopping.	-N/A-	-N/A-	-N/A-
	➤ Pump house access.	-N/A-	-N/A-	-N/A-
	• Terrace Level			
	➤ Discharge of pump.	225 LPM	Provided	MR
	➤ Head of pump.	30 m	30 m	MR
	➤ Power supply.	Required	Provided	MR
	➤ Auto starting of pump.	Required	Provided	MR
14.	Captive water storage for firefighting.			
	• Underground tank capacity.	-N/A-	-N/A-	-N/A-
	➤ Draw-off connection.	-N/A-	-N/A-	-N/A-
	➤ Fire Service Inlet.	-N/A-	-N/A-	-N/A-
	➤ Access to tank.	-N/A-	-N/A-	-N/A-
	• Overhead tank capacity.	2,500 ltrs	Provided	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	• Pressurization of lift shaft.	-N/A-	-N/A-	-N/A-
	• Pressurization of lift lobby.	-N/A-	-N/A-	-N/A-
	• Communication in lift car.	-N/A-	-N/A-	-N/A-
	• Fireman's switch.	-N/A-	-N/A-	-N/A-
	• Lift signage.	-N/A-	-N/A-	-N/A-


— N/S —

7	Standby Power Supply	-N/A-	-N/A-	-N/A-
18.	Refuge Area			
	• Total area	-N/A-	-N/A-	-N/A-
	• Location	-N/A-	-N/A-	-N/A-
19.	Fire Control Room.			
	• Detector System Panel.	-N/A-	-N/A-	-N/A-
	• Flow Switch Panel.	-N/A-	-N/A-	-N/A-
	• PA system Panel.	-N/A-	-N/A-	-N/A-
	• Battery backup	-N/A-	-N/A-	-N/A-
	• Building floor plan	-N/A-	-N/A-	-N/A-
20.	Special Fire Protection System for the Protection of special Risk, if any.			-N/A-

The Fire protection system provided in the building / premises were checked at random and found functional at the time of inspection. The declaration form submitted by the school management at C-10 for no construction change in building.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the DOE circular, Fire Safety Certificate issued vide letter no. F.6/DFS/MS/2006/3286 dated 08/11/2006, renewal under rule 37 of Delhi Fire Service 2010 is recommended.

Accordingly DFA is put up for approval and signature please.



13/11/19

Signature of the Inspecting Officer


Name : Avtar Singh


Designation: ADO (M.RD)

DO (SD)


14/11


15/11/19


15/11


15/11


15/11

F.T letter is put up for sign please



