GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/GH/SZ/2019/ 2 (9)

Dated: 21/11/19

FIRE SAFETY CERTIFICATE

Certified that M/s. Surva International Guest House located at 4/33, WEA, Karol Bagh, Saraswati Marg, New Delhi- 110005 comprised of basement, ground plus three upper floors department vide letter No. granted Fire Safety Certificate by this F.6/DFS/MS/GH/2016/1527 dated 18.10.2016 for using basement as hall, ground floor as reception & 03 guest rooms, first & second floor each having 08 guest rooms, & third floor having 05 guest rooms. The guest house building was re-inspected by the officer concerned of this department on 05-11-2019 in presence Sh. Sumit Gupta, manager of the guest house and found that the said guest house owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class residential (guest house) for ground floor having 03 guest rooms, first & second floor each having 08 guest rooms respectively and third floor having 05 guest rooms (total 24 guest rooms only), with effect from for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed overleaf.

Issued on 21/11/9 at New Delhi by.

(Rajesh Panwar)
Dy. Chief Fire Officer (SZ)
Delhi Fire Service
Ph.- 011-26189168

Copy to:-

- 1. The Manager, M/s Surya International guest house, 4/33, WEA, Karol Bagh, Saraswati Marg, New Delhi- 110005.
- 2. The Additional C.P. (Lic.), Police Station Defence Colony, 1st floor, New Delhi.
- 3. Municipal Health officer, NDMC, Civic centre, New Delhi.

Conditions for the Validity of Fire Safety Certificate

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 6. All comments / directions of licensing department shall always be permitted and followed.
- 7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.
- 9. Basement shall be used as per BBL.
- 10. No temporary shed is allowed on terrace.
- 11. The Fire Safety Certificate is only for Guest Rooms.
- 12. The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter- 7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-67 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/11940-55 dated 25.09.2019 in respect of existing building (copy enclosed) shall be implemented by 30.12.2019 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void.

INSPECTION REPORT

1. Name & address of the building

: M/s Surya International Guest House, 4/33, WEA, Karol

Bagh, Saraswati Marg, New Delhi- 110005

2. Type of Occupancy

: Lodging House

3. Type of Case

: Renewal

4. Details of previous NOC

: F.6/DFS/MS/GH/SZ/2016/1527 dated 18.10.2016

5. Fire Safety directives letter No

: Nil

6. Date of inspection

: 05-11-2016

7. Name of the Inspecting Officers

: Rajbir Kharb, ADO(SRd),

8. Name and designation of officers

from the building side :

: Mr. Sumit Gupta, Manager

9. Year of Construction

: 2001

10. Applicant's letter No.

: Form 'J' dated 11.10.2016

The said guest house is comprised of basement, ground plus three upper floors.

S. No.	Mi preve	inimum Standards on fire ention and fire safety U/R 33	Fire safety requirements as per NBC-IV/BBL	Provided at site	Remarks MR/NMR			
1	Access to building Of mts Provided MR							
	•	Road width	06 mts	Provided				
	•	Gate width	N/A	N/A	N/A			
	•	Width of internal road	N/A	N/A	N/A			
2	Number, Width, Type & Arrangement of Exits							
		nber of staircases	_	-	•			
		Upper Floors	01	01	MR being old case			
	•	Basements	01	01	MR being old case			
	b. Wid	Ith of staircases			-			
	•	Upper Floors	Old case.	1.21 mts	MR being old case			
	•	Basements	Old case	1.23 mts	MR being old case			
	c. Protection of exits		-	-	-			
	•	Fire check door	N/A	N/A	N/A			
	•	Pressurization	N/A	N/A	N/A			
	e. No.	of continuous staircases to terrace	01	01	MR			
	g. Wi	dth of Corridor	N/A	N/A	N/A			
	h. Door Size		1 mt.	1 mt	MR			
3	Com	partmentation.	57/1	NI/A	N/A			
	•	Fire check door	N/A	N/A	N/A			
	•	Sealing of electrical shafts	N/A	N/A	N/A			
4	•	Fire Rating of shaft door	N/A	N/A N/A	N/A			
	•	Water Curtain	N/A	N/A	N/A			
	•	11102	N/A	14/11				
	Smo	ke Management System.	30 a/c per hour	Exhaust fan provided	MR			
	•		12 a/c per hour					
	•	Upper floors	12 are per nour	Ivaturar v Chimation				
5	Fire	Extinguishers	0.0	08 M				
1		Total numbers	08) (D			
		Types	ABC & CO ₂ type ISI marked		MR			
	2	IS marking	151 Illaikeu	Provided	IVIIC			

		N-35		1000		
6	First-Aid Hose Reels.					
	Total numbers on each floor	01	Provided	MR		
	 Length of hose reel hose 	30 m	Provided	MR		
	Nozzle diameter	5 mm	Provided	MR		
7	Automatic fire detection and alarming		Tiovided	IVIK		
	Type of detectors	N/A	N/A	N/A		
	Location of Main Panel	N/A	N/A			
	Location of Repeater Panel	N/A	N/A	N/A		
	Alternate source of power	N/A		N/A		
	Hooters' Location	N/A	N/A	N/A		
8	MOEFA		N/A	N/A		
9		Required	Provided	MR		
10	Public Address System. Automatic Sprinkler System.	Required	Provided	MR		
10	Basement	D . 1	7			
	Upper Floor	Required	Provided	MR		
	Sprinkler above false ceiling	N/A	N/A	N/A		
11	Internal Hydrants	N/A	N/A	N/A		
	Size of riser/down-comer	NT/A	27/4			
	Number of hydrants per floor	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
12		N/A	N/A	N/A		
12	Yard Hydrants.					
	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13	Pumping Arrangements.					
	Ground Level					
	Discharge of main Pump	N/A	N/A	N/A		
	Head of Main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	Jockey Pump out put	N/A	N/A	N/A		
	Jockey pump head	N/A	N/A	N/A		
	Standby Pump out put	N/A	N/A	N/A		
	Standby Pump Head	N/A	N/A	N/A		
	 Auto Starting/ Manual stopping Pump House Access 	N/A	N/A	N/A		
	Pump House AccessTerrace level	N/A	N/A	N/A		
	A CALL COLORS WANTED A SOCIAL					
	Discharge of pumpHead of the pump	450 LPM	450 LPM	MR		
	Power Supply	40 mts	40 mts	MR		
	Auto Starting of pump	Required	Provided	MR		
4		Required	Provided	MR		
4	Captive Water Storage for fire fighting.					
	Underground tank capacity	N/A	N/A	N/A		
	> Draw-off connection	N/A	N/A	N/A		
	> Fire service inlet	N/A	N/A	N/A		
	> Access to tank	N/A	N/A	N/A		
1	Overhead Tank capacity	5,000 lts	Provided	MR		
5	Exit Signage.	Required	Provided	MR		
,	Provision of Lifts.	1	1 10 vided	IVIIV		
6	1 TOVISION OF LINES.					

			N-36				
,	•	Communication In lift Car	N/A	N/A	N/A		
	•	Fireman's Grounding Switch	N/A	N/A	N/A		
		Lift Signage	N/A	N/A	N/A		
17		by power supply	N/A	N/A	N/A		
18	Refuge Area.						
	>	Total Area	N/A	N/A	N/A		
	>	Location	N/A	N/A	N/A		
19	Fire Control Room						
		Detector System Panel	N/A	N/A	N/A		
		Flow Switch Panel	N/A	N/A	N/A		
		PA System Panel	N/A	N/A	N/A		
		Batter backup	N/A	N/A	N/A		
		Building Floor Plans	N/A	N/A	N/A		
20	Speci	al Fire Protection Systems for ction of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were checked and found functional at the time of inspection.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F.6/DFS/MS/GH/SZ/2016/1527 dated 18.10.2016, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

DO (SW)

15/11/2019

Rajbir Kharb Asstt. Div. Officer (S.Rd)

DCFo(gr)

991

o en Agriced

Sir,

FT letter 's put up for Signature please