

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI- 110001

NO. F6/DFS/MS/EH/2019/SZ/ 2233

Dated: 27/11/19

FIRE SAFETY CERTIFICATE

Certified that the Munde Distributors LLP (Restaurant) located at Ground Floor, RSM02, Plot No.1 Sector- 13 Dwarka, New Delhi, of a building comprised of Three basements, ground plus three upper floors, have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service rules 2010 and verified by the officer concerned of Fire Service on 11.11.2019 in presence of Sh. Ashish Sharma (Manager) and that the premises is fit for occupancy 'Assembly building' Group-D (Restaurant) with effect from 27/11/19.....for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, printed over leaf. The Reliance Ambit Trade Mall Where restaurant is located has already been a valid Fire Safety Certificate issued by this department vide letter no.F6/DFS/MS/Mercantile/2018/SZ/1222 dated 24.5.2018.

Issued on 27/11/19..... at New Delhi by

ae (Vipin kental)
Chief Fire Officer

Copy to:-

1. The DHO, Najafgarh Zone, SDMC Public Health Department, Room No. 408, Zonal Officer Building, Near Dhansa stand, New Delhi.
2. The Additional Commissioner of Police, Licensing Unit, 1st Floor, Police Station, Defense Colony, New Delhi,
3. The Authorized Signatory, the Munde Distributors LLP (Restaurant) at Ground Floor, RSM02, Plot No.1 Sector- 13 Dwarka, New Delhi

CONDITIONS

1. All the means of escape shall be kept free of all type of obstruction all the time.
2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.
4. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
6. All comments / directions of licensing Department shall always be permitted and followed.
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
8. The owner / occupier shall apply for renewal of this **Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37)** along with copy of the certificate, six months prior to its expiry.

INSPECTION REPORT

1	Name & address of the building	Munde Distributors LLP (Restaurant) at Ground Floor, RSM02, Plot No.1, Sector-13, Dwarka, New Delhi.
2	Type of Occupancy	Assembly D (Restaurant)
3	Type of case	New
4	Details of previous NOC	For Mall F6/DFS/MS/Mercantile/2018/SZ/1222 dated 24.5.2018
5	Fire safety directives letter No	UBBL/NBC
6	Date of inspection	11.11.2019
7	Name of the inspecting Officers :	Satpal Bhardwaj ADO (Dwarka)
8	Name and designation of officers from the building side	Sh. Ashish Sharma (Manager)
9	Year of construction	2015
10	Applicant's letter No.	Nil Dated 19.10.2019 & DHO/NGZ/2019 dated 17.10.2019

Building comprised of :Three Basements, Ground + Three upper Floors

S. NO.	Minimum Standards on fire prevention and fire safety U/R 33	UBBL/NBC Requirements	Provided at site	Remarks MR / NMR
1	Access to building	Mall Building		
	1) Road width	9 Mtrs.	20 Mtrs.	MR
	2) Gate width	6 Mtrs.	6 Mtrs.	MR
	3) Width of internal road	6 Mtrs.	Provided (As per Plan)	MR
2	Number, width Type & arrangement of exits			
	a. Number of staircases	N/A for Restaurant		
	1. Upper floors	N/A	3 Nos.	N/A
	2. basements	N/A	9 Nos.+ 1 Ramp	N/A
	b. Width of staircase			
	1. Upper floors	N/A	2 Mtrs.	N/A
	2. basements	N/A	2.00/1.8./1.50 Mtrs.+1 Ramp 7.5 Mtrs.(Two Way)	N/A
	c. Protection of exits			
	1. Fire check door	N/A	Provided	N/A
	2. Pressurization	N/A	Provided	N/A
	d. No. of continuous staircase to terrace	N/A	3 Nos. Ground to Terrace 1 No. Basement to Terrace	N/A
	e. Width of corridor	2.40 Mtrs.	2 to 5 Mtrs.	MR
	f. Door size	2 Mtrs. (2 Nos.)	Provided	MR
3	Compartmentation.			
	1. Fire check door	N/A	Provided	N/A
	2. Sealing of electrical shafts	N/A	Removed	N/A
	3. Fire Rating of shaft door	N/A	Provided	N/A
	4. water curtain	N/A	Provided	N/A
	5. Fire dampers	N/A	Provided	N/A
4	Smoke Management system.			
	basement	N/A	Provided	N/A
	upper floors	Required	Provided in Restaurant	MR
5	Fire Extinguishers			
	total numbers	3 Nos.	Provided	MR
	Types	CO2 & ABC	ABC & CO2	MR
	ISI marking	Required	Provided	MR

6	First-Aid Hose Reels.	Connected with main building's system		
	total numbers on each floor	One	Provided	MR
	Length of Hose reel hose	30 Mtrs.	Provided	MR
	Nozzle Diameter	5 mm	Provided	MR
7	Automatic fire detection and alarming system			
	Type of detectors	N/A	Provided	N/A
	location of Main Panel	N/A	Ground floor	N/A
	location of Repeater panel	N/A	Provided at ground floor	N/A
	Alternate source of power	N/A	Battery Backup	N/A
	hooter's location	N/A	Provided	N/A
8	MOEFA	Required	Provided	MR
9	Public Address System.	N/A	Provided	N/A
10	Automatic Sprinkler System.			
	basement	N/A	Provided	N/A
	upper floors	N/A	Provided	N/A
	sprinkler above false ceiling	N/A	Provided	N/A
11	Internal Hydrants			
	Size of riser/down-corner	150 mm	Provided	MR
	Number of Hydrants per floor	One for restaurant area	Provided	MR
	hose Box	Required	Provided	MR
12	Yard Hydrants.			
	total number of hydrants	N/A	12 Nos.	N/A
	hose box	N/A	Provided	N/A
13	Pumping arrangements			
	1. Ground level			
	a. Discharge of main Pump	2850 LPM	Provided	MR
	b. Head of main pump	70 M	Provided	MR
	c. Number of main pumps	2 Nos.	Provided	MR
	d. jockey pump out put	2 Nos. 280 LPM	Provided	MR
	e. jockey pump head	70 M	Provided	MR
	f. Standby Pump output	2850 LPM	Provided	MR
	g. Stanby Pump head	70 M	Provided	MR
	h. Auto Starting/Manual stopping	Required	Provided	MR
	i. pump house access	Required	Provided	MR
	2. Terrace level			
	a. Discharge of pump	N/A	N/A	N/A
	b. head of the pump	N/A	N/A	N/A
	c. Power supply	N/A	N/A	N/A
	d. Auto starting of pump	N/A	N/A	N/A
14	Captive water storage for fire fighting			
	1. Underground tank capacity	N/A	1,00,000 Ltrs.	N/A
	a. Draw-off connection	N/A	Provided	N/A
	b. fire service inlet	Required	Provided	MR
	c. Access to tank	N/A	Provided	N/A
	Over head tank Capacity	10 KL	20 KL	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of lifts.			
	a. Pressurization of lift shaft	N/A	Provided	N/A
	b. pressurization of lift lobby	N/A	Provided	N/A
	c. communication in lift car	N/A	Provided	N/A
	d. Fireman's grounding switch	N/A	Provided	N/A


N13

18		Refuge Area.		MR	
	total area	N/A	N/A	N/A	
	location	N/A	N/A	N/A	
19	Fire control room				
	a. Detector system Panel	N/A	Provided	N/A	
	b. Flow switch Panel	N/A	Provided	N/A	
	c. PA system Panel	N/A	Provided	N/A	
	d. Battery backup	N/A	Provided	N/A	
	e. Building floor plans	N/A	Provided	N/A	
20	Special Fire Protection System for Protection of special Risks, if any:		CO2 Fire extinguisher provided for electric panel.	Provided	MR

Fire protection systems provided in the building were checked & found functional at the time of inspection.

Keeping in view substantial compliance of the minimum standards on fire prevention and fire safety requirements under the rules, issuance of FSC is recommended under rule 35 of the Delhi Fire service Rules, 2010.

Accordingly DFA is put up for your approval and signature please.


 S.P. Bhardwaj
 ADO (Dwarka)

Done

dy
18/11/2013

DCO (S2)

420
18/11/13

Comp

19/11/13

cap

del
M. Scott
22/11/13

dir
22/11/13

FI AS CFO/H

Amulya

FI is put up for signature

