## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/NDZ/2019/2277

# Dated: 09/12/2019

### **FIRE SAFETY CERTIFICATE**

Certified that the M/S Hotel City Empire Dx. located at 3529 & 3467, Dariba Pan, Pahar Ganj, New Delhi comprised of Ground + 04 Upper floors, Ground floor (Reception + 01 office + 02 Shops + 03 guest rooms), 1<sup>st</sup> floor (07 guest rooms), 2<sup>nd</sup> floor (08 guest rooms), 3<sup>rd</sup> floor (08 guest rooms) and 4<sup>th</sup> floor 06 guest rooms) total 32 guest rooms was granted FSC by this department vide letter No.F6/DFS/MS/GH/2016/1779 dated 09/12/16. The premises was re-inspected by the officer concerned of this department on 27/11/19 in the presence of Sh. Girish. Owner/Occupier has also submitted an affidavit not to use above third floor for any purpose. Now the floor wise occupancy at Ground floor (Reception + 01 office + 02 Shops + 03 guest rooms), 1st floor (07 guest rooms), 2nd floor (08 guest rooms), 3rd floor (08 guest rooms), total 26 guest rooms and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class Residential, Sub Division-A-1 as above ground + 03 upper floor, 26 guest rooms only with effect from 94104 for period of three years in accordance with Rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued  $\frac{69-12-19}{2}$  at New Delhi by.

(Sunil Chaudhary)
Dy. Chief Fire Officer
Delhi Fire Service

#### Copy to:-

- 1. The Jt. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi.
- 2. The Manager,

M/S Hotel City Empire Dx. at 3529 & 3467, Dariba Pan, Pahar Ganj, New Delhi.

#### Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 9. Any flammable material for interior decoration is prohibited.
- 10. Owner/Occupier shall also ensure compliance of notification dated 27.05.19 and clarification dated 25.09.19 and there of in r/o guest houses.

1	Name & address of the building	ECTION REPOR		ted at 3529				
1.	Traine de dadress of the sameing		M/S Hotel City Empire Dx. located at 3529 & 3467, Dariba Pan, Pahar Ganj, New Delhi					
2	Type of occupancy:-		Residential, Sub Division-A-1					
۷.	Gr. + 04 Upper floors (total 26 Guest rooms)							
		Ground floo	r (Reception + 01 o	ffice + 02				
		guest rooms), 1st floor (07 guest						
		rooms), 2 <sup>nd</sup>	floor (08 guest roon	ns), 3 <sup>rd</sup> floor				
	(08 guest rooms)							
3.	Type of case:-		Renewal					
4.	Details of previous FSC:-	F6/DFS/MS/	GH/2016/1779 date	ed 09/12/16				
5.	Fire safety directives No	N/A						
	Date of inspection:- 27/11/19							
7.	Name of the inspecting officer:		Atwal DO (CD) &					
		Sh. Manoj K	umar Sharma (ADO	J/CC)				
8.	Name & designation of officer	Cl. Haman	Cinch (Ournar)					
_	From the building side:-		Singh (Owner)					
	Year of construction:-	2006-07 Nil dated 25/1	0/2010					
	Applicant's letter No:-	Requirement	Provided at site	Remarks				
S.No.	Minimum Standards on fire	BBL NBC	Flovided at site	MR/NMR				
	Prevention and fire safety	Part- IV		MICHAIN				
1	U/R 33	Part- IV						
1.	Access to Building	00	12 mtm	MR				
	1) Road width	09 mtr.	12 mtr. N/A	N/A				
	2) Gate width	N/A						
	3)Width of internal road	N/A	N/A	N/A				
2.	Number, Width Type & Arr	angement of Ex	tits					
	A. Number of staircases	_						
	1. Upper floors	01 No.	01 No.	MR				
	2. Basements	N/A	N/A	N/A				
	B. Width of staircase							
	1. Upper floors	1.5 mtr.	1.5 mtr.	MR				
	2. Basements	N/A	N/A	N/A				
	C. Protection of exits							
	1. Fire check door	N/A	N/A	N/A				
	2. Pressurization	N/A	N/A	N/A				
	D. No. of continuous	01	01	MR				
	staircase to terrace							
	E. Width of corridor	N/A	N/A	N/A				
	F. Door size	N/A	N/A	N/A				
3.	Compartmentation	Q		1				
ii.	1) Fire check door	N/A	N/A	N/A				
	2) Sealing of electrical shafts	N/A	N/A	N/A				
	3) Fire rating of shaft door	N/A	N/A	N/A				
	4) Water curtain	N/A	N/A	N/A				
	5) Fire Dampers	N/A	N/A	N/A				
4.	Smoke Management System		8					
	1) Basements	30 ACPH	N/A	N/A				
	2) Upper floors	12ACPH	Natural	MR				
5.	Fire Extinguishers							
	1) Total numbers	15	15	MR				
				3 650				
	2) Types	ABC & CO2	ABC & CO2	MR				



6.	First-Aid Hose Reel							
0.	1) Total number of eachfloor 01			01		N	IR .	
	2) Length of hose reel hose 30		m		) m	_	IR .	
	3) Nozzle diameter				05 mm		MR	
7.	Automatic Fire Detection &							
7.6	1) Type of detectors				/A	IN	/A	
	2) Location of main panel	N/			/A		/A	
	3) Location of repeater panel	N/			/A	N	/A	
	4) Alternate source of power	N/	A	N			N/A	
	5) Hooter's Location	N/		N/A		N/A		
8.	MOEFA	Re	Required Provided		ovided	MR		
9.	Public Address System		quired	6,000,000	ovided		íR	
10.	Automatic Sprinkler System		4				-	
	1) Basement		N/A		N/A		/A	
*	2) Upper floors	N/			/A		[/A	
	3) Sprinkler above false ceiling	N/A		N/A		N/A		
11.	Internal Hydrants	1 - "		-,	NO. 00. 00. 00. 00. 00. 00. 00. 00. 00. 0			
	1) Size of riser/down-comer	N/	A	N	/A		[/A	
	2) Number of hydrants per	N/			N/A		I/A	
	floor					1		
	3) Hose box	N/	A	N	/A	N	I/A	
12.	Yard Hydrants							
	1) Total number of hydrants	N/	A	N	/A	IN	I/A	
	2) Hose box	N/	A	N	/A	1	I/A	
13.	Pumping Arrangement				2			
	1) Ground level		N/A		N/A		N/A	
	a) Discharge of main		N/A		N/A		N/A	
	pump						-	
	b) Head of main pump		N/A		N/A		N/A	
	c) Number of main pu		N/A		N/A		N/A	
	d) Jockey pump out pu		N/A		N/A		N/A	
	e) Jockey pump head		N/A		N/A		N/A	
	f) Stand by pump outp	out	N/A		N/A		N/A	
	g) Stand by pump head	1	N/A		N/A	٠,	N/A	
	h) Auto starting/Manu	al	N/A		N/A	1	N/A	
	stopping		480					
	2) Terrace level							
	a) Discharge of pump		450 LPM		450 LPM		MR	
	b) Head of pump		30 mtr.		30 mtr.		MR	
	c) Power supply		Required		Provided		MR	
	d) Auto starting of pur	_	Required		Provided		MR	
14.	Captive Water Storage fo							
	Under ground tank capa		N/A		N/A		N/A	
	a) Draw-off connectio	n	N/A		N/A		N/A	
	b) Fire service inlet		N/A	N/A			N/A	
	c) Access to tank		N/A		N/A		N/A	
	d) Over head tank	10000 ltr			10000 ltr.		MR	
	capacity		5					
<b>15.</b>	Exit Signage.		Required		Provided		MR	

m

20.	Special Fire Protection System Risk, if any:	for Protection	on of special	NA
00	e) Building floor plan	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
-	c) PA system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
18.	Refuge Area	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
17	e) Lift signage	N/A	N/A	N/A
1	d) Fireman's switch	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	<ul><li>a) Pressurization of lift shaft</li></ul>	N/A	N/A	N/A
16.	Provision of Lifts.			

The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire measures as required under the rules the FSC issued vide letter no. safety F6/DFS/MS/GH/2016/1779 dated 09/12/16 renewal under rule 35 of the Delhi Fire Service rules 2010, is recommended.

Signature of the Inspecting Officer

Name: - Rajinder Atwal

Designation: - DO (CD)

Signature of the Inspecting Officer

Name:- M.K. Sharma

Designation: - ADO (CC)