GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110 001

No. F6/DFS/MS/School/2019/NDZ/ 2355

Dated: 20/12/19

FIRE SAFETY CERTIFICATE

Certified that the Govt. Girls Sec. School at Welcome Colony, Delhi-110053, comprised of ground plus first floor owned/occupied by Govt. Girls Sec. School have complied with the fire prevention and fire safety requirements in accordance with circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated-01/03/11 issued by the Director of Education and verified by the officers concerned of fire service on 04/12/2019 in presence of Ms. Bharti Kumari, Principal of the school and found that the school building is fit for occupancy class "B" 'Educational Building' for ground plus first floor with effect from ... 2011 []... for a period of three years, in accordance and further subject with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010 & also conditions printed overleaf.

Note:- This fire safety certificate does not cover new building blocks.

Issued on at New Delhi by

(Sunil Chawdhary)
Dy. Chief Fire Officer

To,

The Principal, Govt. Girls Sec. School, Welcome Colony, Delhi-110053

Copy:-

The Dy. Director of Education, B–Block, Yamuna Vihar, Delhi-110053

CONDITIONS

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry

INSPECTION REPORT

: Govt Girls Sec. School, 1. Name & address of the building

Welcome Colony, Delhi-110053

2. uilding is comprised of

: Ground plus first floor (old building) : Educational 3. Type of Occupancy Renewal 4. Type of Case

: F6/DFS/MS/School/2016/NDZ/1636 5. Details of Previous NOC letter dated 07/11/2016

: F6/Estate/CC/Fire Safety/2011/3298 to 3398 6. Fire Safety direction letter No.

dt-01/03/2011

: 04/12/2019 7. Date of Inspection

: ADO Nagender Singh 8. Name of the Inspecting officers

9. Name and designation of Officer : Ms. Bharti Kumari, Principal from the building side

10. Year of Construction : 1998

: GGSS/WC/2019/64 Dated- 06/11/2019 11. Applicant's letter No

Sr. No.	Minimum Standards on Fire Prevention and Fire Safety U/R33	Circular Requirement	Provided at Site	Remarks MR/NMF			
01	Access to Building						
	Road width	06m	06m	MR			
	Gate width	4m	4m	MR			
	 Width of internal road 	N/A	N/A	N/A			
02	Number, Width, Type and Arrangement of Exits						
	a. Number of Staircases						
	 Upper floor 	01 no.	02 nos.	MR			
	 Basement 	N/A	N/A	N/A			
	B. Width of Staircases						
	 Upper floor 	1.50m	1.60m & 1.13m	MR			
	 Basement 	N/A	N/A	N/A			
	c. Protection of Exits						
	Fire check door	N/A	N/A	N/A			
	 Pressurization 	N/A	N/A	N/A			
	d. No. of Continuous Staircases to Terrace	01 no.	01 no.	MR			
	e. Width of Corridor	1.50m	1.50m	MR			
	f. Door Size	01m	01m	MR			
03	Compartmentation.						
	Fire check door	N/A	N/A	N/A			
	 Sealing of electrical shafts 	N/A	N/A	N/A			
	 Fire rating of shaft door 	N/A	N/A	N/A			
	Water curtain	N/A	N/A	N/A			
	• Fire dampers	N/A	N/A	N/A			
04	Smoke Management System.						
	Basement	N/A	N/A	N/A			
	Upper floor	N/A	N/A	N/A			
05.	Fire Extinguishers						
	Total numbers	04 nos.	06 nos.	MR			
	• Types	ABC /CO ₂	ABC/CO ₂	MR			
	 IS marking 	ISI marked	ISI marked	MR			

10/12

	First-Aid-Hose Reels.	3.T/A	DT/A	% T / A			
	Total numbers on each floor	N/A	N/A	N/A			
	• Length of hose reel hose	N/A	N/A	N/A			
0.7	Nozzle diameter	N/A	N/A	N/A			
07	Automatic Fire Detection and Alarming System.						
	Type of detectors	N/A	N/A	N/A			
	Location of main panel	N/A	N/A	N/A			
	Location of repeater panel	N/A	N/A	N/A			
	Alternate source of power	N/A	N/A	N/A			
	Hooter	N/A	N/A	N/A			
08	MOEFA	N/A	N/A	N/A			
09	Public Address System.	N/A	N/A	N/A			
10	Automatic Sprinkler System.						
		NT/A	NI/A	N/A			
	• Basement	N/A	N/A				
	• upper floor	N/A	N/A	N/A			
1 1	sprinkler above false ceiling	N/A	N/A	N/A			
11	Internal Hydrants						
	• size of riser/down-comer	N/A	N/A	N/A			
	Number of hydrants per floor	N/A	N/A	N/A			
	Hose box	N/A	N/A	N/A			
12	Yard Hydrants.						
	Total number of hydrants	N/A	N/A	N/A			
	Hose box	N/A	N/A	N/A			
13	Pumping Arrangements.						
	> Ground Level						
	Discharge of main pump	N/A	N/A	N/A			
	Head of main pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	Jockey pump out put	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A	N/A			
	• Standby pump out put	N/A	N/A	N/A			
	Standby pump head	N/A	N/A	N/A			
	Auto starting /manual stopping	N/A	N/A	N/A			
	Pump house access	N/A	N/A	N/A			
	> Terrace Level						
	Discharge of numn	N/A	N/A	N/A			
	Discharge of pumpHead of the pump	N/A	N/A	N/A			
	Head of the pumpPower supply	N/A	N/A	N/A			
	11.	N/A	N/A	N/A			
	Auto starting of pump	14/17	11/71	IN/A			
14	Cantiva Water Starges for Eiro		<u>*</u>				
14	Captive Water Storage for Fire Fighting.						
	Underground tank capacity	N/A	N/A	N/A			
	Draw-off connection	N/A	N/A	N/A			
	Fire service inlet	N/A	N/A	N/A			
	Access to tank	N/A	N/A	N/A			
	 Overhead tank capacity 	N/A	N/A	N/A			

16	Provision of Lifts.						
	Pressurization of lift shaft	N/A	N/A	N/A			
	 Pressurization of lift lobby 	N/A	N/A	N/A			
-	 Communication in lift car 	N/A	N/A	N/A			
	 Firemen's grounding switch 	N/A	N/A	N/A			
	 Lift signage 	N/A	N/A	N/A			
17	Standby Power Supply	N/A	N/A	N/A			
18	Refuge Area.						
	Total area	N/A	N/A	N/A			
	• Location	N/A	N/A	N/A			
19	Fire Control Room						
	Detector system panel	N/A	N/A	N/A			
	Flow switch panel	N/A	N/A	N/A			
	PA system panel	N/A	N/A	N/A			
	Battery backup	N/A	N/A	N/A			
	Building floor plans	N/A	N/A	N/A			
20	Special Fire Protection Systems for Protection of Special Risks, if Any:	N/A	N/A	N/A			

Keeping in view of the compliance of the minimum standards of fire prevention and fire safety measures required as per circular No.F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated-01/03/11, it is recommended to grant Fire Safety Certificate.

(NAGENDER SINGH)

Assistant Divisional Officer (Shahdara)

DY. CFO/HOZ

£ 7

DAE

APOISWOTA

FT is put up for sign

OKD

18/12