

No. F6/DFS/MS/GH/SZ/2019/ 2350

FIRE SAFETY CERTIFICATE

Certified that M/s. Hotel Moments located at 7A/74, WEA, Karol Bagh, New Delhi-110005, was granted FSC by this department vide letter No. F.6/DFS/MS/GH/2015/SZ/1019 dated 18.06.2015 for using stilt as parking, hall & reception, ground, first, second & third floor each having 05 guest rooms respectively (total 20 guest rooms) and a staff room with pantry for staff in temporary shed on terrace. The guest house was re-inspected by the officer concerned of this department on 08.11.2019 in the presence of Sh. Ajay Sharma (owner) and observed that the guest house management has constructed fourth floor (sealed) & one room on terrace. Now the management has submitted an affidavit not to use any occupancy above third floor and found that the owner/occupier have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class residential (guest house) for 05 guest rooms at ground floor, 05 guest rooms at first floor, 05 guest rooms at second floor and 05 guest rooms at third floor (total 20 guest rooms) with effect from 26 12 20 19 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed overleaf.

Issued on 20/12/2019 at New Delhi by.

(Rajesh Panwar)

Dy. Chief Fire Officer (SZ)

Delhi Fire Service

Ph.- 011-26189168

Copy to:-

- 1. The Owner /Occupier, M/s. Hotel Moments 7A/74W.E.A., Karol Bagh New Delhi- 110005
- 2. The Additional C.P. (Lic.), Police Station Defence Colony, 1st floor, New Delhi.
- 3. Municipal Health officer, NDMC, Civic centre, New Delhi.

Conditions for the validity of Fire Safety Certificate: -



- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 6. All comments / directions of licensing department shall always be permitted and followed.
- 7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.
- 9. No temporary shed is allowed on terrace.
- 10. The Fire Safety Certificate is only for Guest Rooms.
- 11. The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter-7 by the Directorate of Local Bodies vide letter No. F.5(1897/AD/LB/2016/4053-67 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/11940-55 dated 25.09.2019 in respect of existing building (copy enclosed) shall be implemented by 30.12.2019 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void.

: M/s. Hotel Moments, 7A/74, WEA, Karol Bagh, New 1. Name & address of the building Delhi- 110005.

: Lodging House Type of Occupancy 2.

: Renewal 3. Type of Case

: F6/DFS/MS/GH/2015/SZ/1019 dated 18.06.2015 4. Details of previous NOC

5. Fire Safety directives letter No : Nil

: 08.11.2019 6. Date of inspection

: M.K. Chattopadhyay, DO(South West) Name of the Inspecting Officers

8. Name and designation of officers

: Sh. Ajay Sharma, Owner from the building side

: 2009-10 9. Year of Construction

: Form J dated nil 10. Applicant's letter No.

comprised of stilt, ground plus four upper floors.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Fire safety requirements as per NBC/BBL	Provided at site	Remarks MR/NMR	
	A was to building				
	• Road width	06 mts	Provided	MR	
	Gate width	Old case	1.80 mts	MR being old case	
	Width of internal road	N/A	N/A	N/A	
	Number, Width, Type & Arrangemen	t of Exits			
		-	-		
	a. Number of staircases	01	01	MR being old case	
	• Upper Floors	N/A	N/A	N/A	
	Basements	- 11111			
	b. Width of staircases	Old case	1.27 mts	MR	
	• Upper Floors	N/A	N/A	N/A	
	Basements	-	-	-	
	c. Protection of exits	N/A	N/A	N/A	
	• Fire check door	N/A	N/A	N/A	
	Pressurization e. No. of continuous staircases to terrace	01	01	MR	
		Old case	1.50 mts	MR	
	g. Width of Corridor	Old case	0.82 mt	MR	
	h. Door Size				
3	Compartmentation.	N/A	N/A	N/A	
	Fire check doorSealing of electrical shafts	N/A	Sealed		
	Fire Rating of shaft door	N/A	N/A	N/A	
	Water Curtain	N/A	N/A	N/A	
	• Fire Dampers	N/A	N/A	N/A	
4	Smoke Management System.				
7	D. A.	30 a/c per hour	N/A	N/A	
	11	12 a/c per hour	Natural Ventilation	MR	
	• Upper floors			X	

	Total numbers	20		
THE PERSON NAMED IN	• Types	20	Provided) N
	• IS marking	CO ₂ , ABC, WCO ₂ ISI marked	Provided	MR
6	First-Aid Hose Reels.	151 marked	Provided	MR
	Total nambers on each moor	01	Provided	MR
	Length of hose reel hoseNozzle diameter	30 m	Provided	MR
7		5 mm	Provided	MR
/	Automatic fire detection and alarming	system.		
	• Type of detectors	N/A	N/A	N/A
	Location of Main Panel Location of Panel	N/A	N/A	N/A
	Location of Repeater Panel Alternate source of powers	N/A	N/A	N/A
	Alternate source of powerHooters' Location	Required	Provided (D.G set 82.5 KVA)	MR
0		N/A	N/A	N/A
8	MOEFA	Required	Provided	MR
9	Public Address System.	Required	Provided	MR
10	Automatic Sprinkler System.			
	Basement	N/A	N/A	N/A
_	Upper Floor	N/A	N/A	
	Sprinkler above false ceiling	N/A	N/A	N/A N/A
11	Internal Hydrants	11/11	IN/A	IN/A
	Size of riser/down-comer	N/A	N/A	NI/A
	Number of hydrants per floor	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
12	Yard Hydrants.		IV/A	N/A
	Total number of hydrants	N/A	N/A	27/4
	Hose Box	N/A		N/A
13	Pumping Arrangements.	14/11	N/A	N/A
	Ground Level			
	Discharge of main Pump	N/A	- :	 DI/A
	Head of Main pump		N/A	N/A
	Number of main pumps	N/A N/A	N/A	N/A
	Jockey Pump out put		N/A	N/A
	Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	Auto Starting/ Manual stopping	N/A	N/A	N/A
	Pump House Access	N/A	N/A	N/A
	Terrace level	N/A	N/A	N/A
	Discharge of pump	450 7 70 6		
	Head of the pump	450 LPM	Provided	MR
	> Power Supply	30 mts	Provided	MR
	***	Required	Provided	MD

4	Captive Water Storage for fire fighting	g.				
0	Underground tank capacity	N/A	N/A	N/A		
	> Draw-off connection	N/A	N/A	N/A		
	Fire service inlet	N/A	N/A	N/A		
	Access to tank	N/A	N/A	N/A		
	Overhead Tank capacity	Old Case	5000 lts	MR being old case		
15	Exit Signage.	Required	Provided	MR		
16	Provision of Lifts.					
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	Required	Provided	MR		
	Fireman's Grounding Switch	Required	Provided	MR		
	Lift Signage	Required	Provided	MR		
17	Standby power supply	Required	Provided	MR		
18	Refuge Area.					
	> Total Area	N/A	N/A	N/A		
	Location	N/A	N/A	N/A		
19	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel	N/A	N/A	N/A		
	Battery backup	Required	Provided	MR		
	Building Floor Plans	N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	02 ABC type fire extinguishers found provided near elect. panel	d N/A		

The fire protection systems provided in the building were checked and found functional at the time of inspection.

Note: All the shortcomings pointed out by this department vide letter dated 06.09.2019, 03.01.2019 & 13.07.2018 have been complied with by the guest house management.

The guest house management has constructed one more upper floor i.e. fourth floor but now the same is sealed by the management and management has submitted an affidavit not to use any occupancy above third floor.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F6/DFS/MS/GH/2015/SZ/1019 dated 18.06.2015, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

Signature of the Inspecting Officer Name: Rajbir Kharb

Asstt. Div. Officer (SRD)

D.O. (SW)

9/12/2015

994

001