

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/EH/SZ/2019/10

Dated: 07/01/20

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & style of M/s **Lemon Drops** (A Unit of Shine Star Hospitality Pvt. Ltd) situated at T-314 & 315, Ambience Mall, Vasant Kunj, New Delhi-110070, comprised of two tiers basement, ground plus four upper floors but restaurant running at 3rd floor only have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officers concerned of this department on 11/12/2019 in the presence of Sh. Rahul Yadav and that the premises is fit for occupancy class **"Group-D Assembly"** with effect from the date of issue of this certificate for a period of **Three years** in accordance with rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 07/01/20 at New Delhi by

(Ajul Garg)
Director

Delhi Fire Service
Tel. 011-23414000

Copy to: -

1. The Dy. Health Officer, South Zone, South Delhi Municipal Corporation, Green Park, Aurobindo Marg, New Delhi-110016 (W.r.t. letter no. DHO/SZ/2019/D.1678 dated 27/11/2019)
2. The Authorised Signatory M/s **Lemon Drops** (A Unit of Shine Star Hospitality Pvt. Ltd) at T-314 & 315, Ambience Mall, Vasant Kunj,, New Delhi-110070

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of fire-fighting system.
4. The owner/occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

INSPECTION REPORT				
1	Name & Address of the Building	M/s Lemon Drops (A U/o Shine Star Hospitality Pvt. Ltd) at T-314 & 315, Ambience Mall, Vasant Kunj, New Delhi-110070		
2	Type of Occupancy	Assembly 'Group-D' (Restaurant at 3 rd Floor)		
3	Building comprised of	02 tiers Basement, Ground + 4 Upper Floors.		
4	Type of Case	New		
5	Details of Previous NOC	Nil		
6	Fire Safety Directives Letter No	Nil		
7	Date of Inspection	12-12-2019		
8	Name of the Inspecting Officers	S K Dua, DO (SD)		
9	Name & Designation of Officers from the building side	Sh. Rahul Yadav		
10	Year of construction	2013	FSC has been issued to Ambience Mall vide letter No. F.6/DFS/MS/Mix/SZ/2018/204 dt. 02-02-18	
11	Applicant letter No.	Outdoor Diary No. 24137 dated 05-11-2019		
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	BBL/NBC-2005 Requirement	Provided at Site	Remarks MR/NMR
1	Access to Building.	Provided & Maintained by Ambience Mall Mgmt		
	<ul style="list-style-type: none">Road widthGate widthWidth of internal road	Restt within Ambience Mall Vasant Kunj	As above As above As above	MR -NA- -NA-
2	Number, width, type & arrangement of exits	Provided & Maintained by Ambience Mall Mgmt		
	a. Number of Staircase	2 Nos	As above	MR
	<ul style="list-style-type: none">Upper floorsBasement floor	-NA-	As above	-NA-
	b. Width of Staircase	Provided & Maintained by Ambience Mall Mgmt		
	<ul style="list-style-type: none">Upper floorsBasement floor	1.5 mtr -NA-	As above As above	MR -NA-
	c. Protection of exits	Provided & Maintained by Ambience Mall Mgmt		
	<ul style="list-style-type: none">Fire check doorPressurization	Required -NA-	As above As above	MR -NA-
	d. No. of continuous staircase to terrace	Required	As above	MR
	e. Width of corridor	N/A	N/A	N/A
	f. Door size	2m/1m	2m & 1.5m	MR
3	Compartmentation.	Provided & Maintained by Ambience Mall Mgmt		
	<ul style="list-style-type: none">Fire check door.Sealing of electrical shafts.Fire rating of shaft door.Water curtainFire dampers.	Required Required -NA- -NA- -NA-	As above As above As above As above	MR MR -NA- -NA- -NA-
4	Smoke Management system.	Provided & Maintained by Ambience Mall Mgmt		
	<ul style="list-style-type: none">BasementUpper floors	30 ACPH 12 ACPH	N/A Provided	N/A MR
5	Fire Extinguishers.	Provided & Maintained by Ambience Mall Mgmt		
	<ul style="list-style-type: none">Total numbersTypesISI Marking	Required ABC / CO2 ISI marked	06 Nos ABC & Co2 Provided	MR MR MR
6	First Aid Hose Reels.	Provided & Maintained by Ambience Mall Mgmt		
	<ul style="list-style-type: none">Total numbers on each floor.Length of hose-reel hose.Nozzle Diameter	One (Near Restt) 30m 5mm	As above As above As above	NMR MR MR
7	Automatic fire detection & alarming system.	Provided & Maintained by Ambience Mall Mgmt		
	<ul style="list-style-type: none">Type of detectorsLocation of Main PanelLocation of Repeater PanelAlternate source of powerHoofer's location	Required Required N/A Required Required	As above As above As above As above As above	MR MR N/A MR MR

8	MOEFA	Required	Provided	MR
9	Public Address System	-NA-	Provided	-NA-
10	Automatic Sprinkler System	Provided & Maintained by Ambience Mall Mgmt		
	• Basement	-NA-	As above	-NA-
	• Upper floors	Required	As above	MR
	• Sprinkler above false ceiling	-NA-	As above	-NA-
11	Internal Hydrants.	Provided & Maintained by Ambience Mall Mgmt		
	• Size of Riser/Down-comer.	Required	As above	MR
	• Number of Hydrant per floor	Required	As above	MR
	• Hose box.	Required	As above	MR
12	Yard Hydrants.	Provided & Maintained by Ambience Mall Mgmt		
	• Total number of hydrants.	-NA-	As above	-NA-
	• Hose box.	-NA-	As above	-NA-
13	Pumping arrangements.	Pumping arrangements common for entire bldg.		
	• Ground Level	Provided & Maintained by Mall Management		
	➤ Discharge of main pump.	-NA-	4500 LPM	-NA-
	➤ Head of main pump.	-NA-	70 mtr	-NA-
	➤ Number of main pumps.	-NA-	Two	-NA-
	➤ Jockey Pump output.	-NA-	180 LPM	-NA-
	➤ Jockey Pump head.	-NA-	70 mtr	-NA-
	➤ Standby Pump output.	-NA-	4500 LPM	-NA-
	➤ Standby Pump head.	-NA-	Provided	-NA-
	➤ Auto Starting / Manual Stopping.	-NA-	Provided	-NA-
	➤ Pump House Access	-NA-	Provided	-NA-
	• Terrace Level	Pumping arrangements common for entire bldg.		
	➤ Discharge of pump.	450 LPM	As above	MR
	➤ Head of pump.	40m	As above	MR
	➤ Power supply.	Required	As above	MR
	➤ Auto starting of pump.	Required	As above	MR
14	Captive water storage for Fire Fighting.	Fire Safety Systems are common for entire bldg.		
	• Underground tank capacity.	-NA-	4,60,000 Ltr	-NA-
	➤ Draw-off connection.	-NA-	Provided	-NA-
	➤ Fire Service Inlet.	Required	Provided	MR
	➤ Access to tank.	-NA-	Provided	-NA-
	• Overhead tank capacity.	20,000 Ltr	30,000 Ltr	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.	Provided & Maintained by Ambience Mall Mgmt		
	• Pressurization of lift shaft.	-NA-	As above	-NA-
	• Pressurization of lift lobby.	-NA-	As above	-NA-
	• Communication in lift car.	-NA-	As above	-NA-
	• Fireman's switch.	-NA-	As above	-NA-
	• Lift signage.	-NA-	As above	-NA-
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area			
	• Total area	-NA-	-NA-	-NA-
	• Location	-NA-	-NA-	-NA-
19	Fire Control Room.	Provided & Maintained by Ambience Mall Mgmt		
	• Detector System Panel.	-NA-	As above	-NA-
	• Flow Switch Panel.	-NA-	As above	-NA-
	• PA system Panel.	-NA-	As above	-NA-
	• Battery backup	-NA-	As above	-NA-
	• Building floor plan	-NA-	As above	-NA-
20	Special Fire Protection System for the Protection of special Risk, if any :	-NA-	As above	-NA-

N15

M/s Lemon Drops (Shine Star Hospitality Pvt. Ltd), T-314 & 315, Ambience Mall, Vasant Kunj, New Delhi-110070
The Fire protection systems provided in the premises were test checked at random and found functional at the time of inspection.

Keeping in view the substantial satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, it is recommended to issue Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules, 2010.

Accordingly, DFA is put up for approval and signature please.

[Signature]
20/12

Signature of the Inspecting Officer
Name: S.K. Dua
Designation: DO (SD)

Dy. CFO (SZ)

[Signature]
24/12



[Signature]
24/12/19

FT P4

AO/ST

San. of S-5 Order put up for Signature blank

[Signature]
7/1/2020

[Signature]
7/1/20
AO/ST

[Signature]