## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F6/DFS/MS/EH/SZ/2010//2

Dated: 08/1/20

## FIRE SAFETY CERTIFICATE

Certified that the M/s. Nasheman Foods and Beverages LLP running at Ground Floor of a building comprised of basement, ground plus three upper floors located at C-48, GF, Community Centre, Industrial area, Phase-1, Naraina, New Delhi owned/occupied by M/s. Nasheman Foods and Beverages LLP was inspected by the officer concerned of this department on 14.12.2019 in presence of Sh. Pawan Gupta, Manager and found that the owner have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class assembly (restaurant) with effect from  $\frac{68}{1}$  for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed overleaf.

Issued on <u>8</u> / 1 26 at New Delhi by.

Director

Ph.: 011-23414250

Copy to:-

1. Sh. Pawan Gupta, Manager, M/s Nasheman Foods and Beverages LLP, C-48, GF, Community Centre, Industrial area, Phase-1, Naraina, New Delhi.

2. The Deputy Health Officer, North Delhi Municipal Corporation, Karol Bagh Zone, New Delhi- 110005.

## **CONDITIONS**

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non-functional of fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained firefighting staffs should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. All the means of escapes /exits shall not be locked/bolted/blocked at any time for safe evacuation of the occupants in case of any emergency.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [ sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>

INSPECTION REPORT 1. Name & address of the building : Nasheman Foods and Beverages LLP, C-48, GF, Community Centre, Naraina, New Delhi 2. Type of Occupancy : Assembly (Restaurant) 3. Type of Case : New Case 4. Details of previous NOC : N/A 5. Fire Safety directives letter No : N/A 6. Date of inspection : 14-12-2019 7. Name of the Inspecting Officers: Rajbir Kharb, Asstt. Divisional Officer (SRD) 8. Name and designation of officers from the building side : Sh. Promod Gupta, Manager 9. Year of Construction : 1987 10. Applicant's letter No. : No. 34526/Addl.CP/Lic./EH (DA-I) dated 24.09.2019 The said restaurant is running at ground floor of a building comprised of basement, ground plus three S. Minimum Standards on fire Requirement as per NBC part-IV/ No. prevention and fire safety U/R 33 Remarks Provided at site UBBL MR/NMR Access to building 1 Road width 06 mts Provided Gate width MR 4.5 mts Directly accessible Width of internal road from the road MR N/A N/A Number, Width, Type & Arrangement of Exits 2 N/A a. Number of staircases Upper Floors N/A Located at GF Basements N/A N/A b. Width of staircases N/A N/A Upper Floors \_ N/A N/A Basements N/A N/A N/A c. Protection of exits N/A Fire check door N/A N/A Pressurization N/A N/A N/A e. No. of continuous staircases to terrace N/A g. Width of Corridor N/A N/A h. Door Size N/A 2.0,1.0 mts 2.0 mts, 1.25 mts Compartmentation. MR Fire check door N/A N/A

3 Sealing of electrical shafts N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A N/A Fire Dampers N/A N/A N/A 4 Smoke Management System. N/A Basements 30 a/c per hour Upper floors (Restaurant at GF) N/A N/A 12 a/c per hour Provided 5 Fire Extinguishers MR Total numbers

	Types	CO <sub>2</sub> , ABC type	Provided	MR		
	IS marking	ISI marked	Provided	MR		
6	First-Aid Hose Reels.	1711				
	Total numbers on each floor	01	Provided in Restaurant	MR		
	<ul> <li>Length of hose reel hose</li> </ul>	30 m	Provided	MR		
	Nozzle diameter	5 mm	Provided	MR		
7	Automatic fire detection and alarming system.					
	• Type of detectors	N/A	N/A	NI/A		
	<ul> <li>Location of Main Panel</li> </ul>	N/A	N/A	N/A		
	• Location of Repeater Panel	N/A	N/A	N/A N/A		
	Alternate source of power	N/A	N/A	N/A		
	Hooters' Location	N/A	N/A	N/A		
8	MOEFA	Required	Provided	MR		
9	Public Address System.	N/A	N/A	N/A		
10	Automatic Sprinkler System.		i i			
	• Basement	N/A	N/A	N/A		
	Entire Restaurant	N/A	N/A	N/A		
	Sprinkler above false ceiling	N/A	N/A	N/A		
11	Internal Hydrants					
	Size of riser/down-comer	100 mm	Provided	MR		
	Number of hydrants per floor	01	Provided	-		
	Hose Box	01	Provided	MR		
12	Yard Hydrants.  MR					
	<ul> <li>Total number of hydrants</li> </ul>	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13	Pumping Arrangements.					
	Ground Level					
	Discharge of main Pump	N/A	N/A	N/A		
	Head of Main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	Jockey Pump out put	N/A	N/A	N/A		
	Jockey pump head	N/A	N/A	N/A		
	Standby Pump out put	N/A	N/A	N/A		
	Standby Pump Head	N/A	N/A	N/A		
	Auto Starting/ Manual stopping	N/A	N/A	N/A		
	Pump House Access	N/A	N/A	N/A		
	Terrace level			17/71		
	Discharge of pump	450 LPM	Drovid-1			
	Head of the pump	30 mts	Provided Provided	MR		
	> Power Supply	Required		MR MR		
	Auto Starting of pump	Required	Provided	MR		

	04.					
14	Captive Water Storage for fire fighting.					
	Underground tank capacity	N/A	N/A	N/A		
	> Draw-off connection	N/A	N/A	N/A		
	> Fire service inlet	N/A	N/A	N/A		
	> Access to tank	N/A	N/A	N/A		
	Overhead Tank capacity	20,000 lts	Provided	MR		
15	Exit Signage.	Required	Provided	MR		
16	Provision of Lifts.					
	Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of Lift lobby	N/A	N/A	N/A		
	Communication In lift Car	N/A	N/A	N/A		
	• Fireman's Grounding Switch	N/A	N/A	N/A		
	Lift Signage	N/A	N/A	N/A		
17	Standby power supply	Required	Provided	MR		
18	Refuge Area.					
	Total Area	N/A	N/A	N/A		
	Location	N/A	N/A	N/A		
19	Fire Control Room					
	Detector System Panel	N/A	N/A	N/A		
	Flow Switch Panel	N/A	N/A	N/A		
	PA System Panel	N/A	N/A	N/A		
	Batter backup Building Floor Plans	Required	Provided	MR		
		N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	Two ABC type fire extinguisher found provided near elect. panel	MR		

The fire protection systems provided in the building were checked and found functional at the time of inspection. The shortcomings pointed out by this department vide this department letter No. F.6/DFS/MS/2018/3983 dated 24-09-2018 have been complied by the management.

In view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules, it is recommended to grant fire safety certificate under Delhi Fire Service Act-2007 & Rules-2010. DFA is put up for approval & signature please.

Do (96)

21/12/219

Rajbir Kharb Asstt. Div. Officer (S.Rd)

973

21/12/19 Defo(\$2)

Lane