

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No. F 6/DFS/MS/EH/2020/ W2/23

Dated: 17/01/2020

FIRE SAFETY CERTIFICATE

Certified that the M/s Burger King (A unit of Burger King India Pvt. Ltd.) located at Ground Floor-29, Gourmet Hub, BG-1, BG-2, Paschim Vihar, Delhi - 110085 in a building comprised of Basement + Ground + 3 Upper Floors owned / occupied by M/s Burger King (A unit of Burger King India Ltd) have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of this department on 06/01/2020 in the presence of Mr. Avnish Sharma and found that the building/ premises is fit for occupancy class "Assembly" (Group-D)/ Eating House with effect from 17/01/2020 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 17/01/2020 at New Delhi

(Atul Garg)

Director

Ph:- 011-23414000

Copy to:-

1. Addl. Commissioner, Licensing Unit. 1st floor, Police Station Defence Colony, New Delhi.
2. Mr. Deepak Yadav M/s Burger King (A unit of Burger King India Pvt. Ltd), Ground Floor-29, Gourmet Hub, BG-1, BG-2, Paschim Vihar, Delhi - 85

Following fire safety directives must be adhered to:-

1. The FSC is valid for Ground floor only.
2. All the fire safety arrangements provided there-in shall be maintained in good working conditions at all times.
3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
4. The trained staff should be available round the clock
5. Any deviations w.r.t construction shall be verified by the concerned building sanctioning agency.
6. The certificate may not be treated in any case for the regularization of the unauthorized construction if any
7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
8. The owner/occupier shall submit a declaration every year in the form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.Delhigovt.nic.in

INSPECTION REPORT

41N

Covered area of the restaurant is 170m². As per NBC Part-IV) Seating capacity of the restaurant comes out to be 94 (170/1.8=94). Which is more than 50 hence covered under DFS Act 2007, Rules 2010. Subsequently inspection of Eating House is carried out as per NBC (Part-IV).

1. Name & address of the building: **M/s Burger King (A Unit of Burger King India Pvt. Ltd.), Ground Floor-29, Gourmet Hub, BG-1, BG-2, Paschim Vihar, Delhi-85.**
2. Type of Occupancy : **Assembly (E/H) /Ground Floor only**
3. Type of Case : **New**
4. Details of previous NOC : **Nil (FSC to Gourmet Hub Mall is issued by this department vide letter No. F6/DFS/MS/WZ/2019/1959 dated 15/10/2019.**
5. Fire Safety directives Letter No. : **NBC (Part-IV)**
6. Date of inspection : **06/01/2020**
7. Name of the Inspecting Officer : **A.D.O. (Jwp)**
8. Name and designation of Officer
from the building side : **Sh. Avnish Sharma**
9. Year of Construction : **2009-10**
10. Applicant's letter No. : **39159/Addl.CP/Lic./EH (DA-XI) dated 05/12/2019**

S No	Minimum standards on fire prevention and fire safety U/R 33	NBC Requirements	Provided at site	Remarks MR/NMR
1.	Access of building			
	• Road width	6 mtr	30 mtr	MR
	• Gate width	N/A	N/A	N/A
	• Width of internal road	N/A	N/A	N/A
2.	Number, width, Type & Arrangements of exits			
	a. Number of staircases			
	• Upper floors	N/A	N/A	N/A
	• Basements	N/A	N/A	N/A
	b. Width of staircases	N/A		
	• Upper floors	N/A	N/A	N/A
	• Basements	N/A	N/A	N/A
	c. Protection of exits	N/A		
	• Fire check door	N/A	N/A	N/A
	• Pressurization	N/A	N/A	N/A
	d. No of continuous staircase to terrace	N/A	N/A	N/A
	e. Width Of Corridor	N/A	N/A	N/A
	f. Door Size	2.00 mtr & 1.35 mtr	2.00 Mtr. x 2	MR
3.	Compartmentation			
	• Fire check door	N/A	N/A	N/A
	• Sealing of electrical shafts	N/A	N/A	N/A
	• Fire Rating of shaft door	N/A	N/A	N/A
	• Water Curtain	N/A	N/A	N/A
	• Fire Dampers	N/A	N/A	N/A
4.	Smoke managements System			
	• Basements	N/A	N/A	N/A
	• Upper floors	N/A	N/A	N/A
5.	Fire Extinguishers			
	• Total numbers	2	4	M/R
	• Types	ISI marked ABC/CO ₂	Provided	M/R
	• IS marking	Required	Provided	M/R

6.	First – Aid Hose Reels			
	• Total numbers on each floor	1	Common with Mall	MR
	• Length of hose reel hose	30 Mtr.	Common with Mall	MR
	• Nozzle diameter	5 mm	Common with Mall	MR
7.	Automatic fire detection and alarming system			
	• Type of detector	Required	Provided	MR
	• Location of Main Panel	Required	Provided	MR
	• Location of Repeater Panel	Required	Provided	MR
	• Alternate source of power	Required	Provided	MR
	• Hooters' Location	Required	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System			
	• Ground Floor	N/A	N/A	N/A
	• Upper Floor	N/A	N/A	N/A
	• Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	• Size of riser/down-comer	150 mm	Common With Mall	MR
	• Number of hydrants per floor	Required	Common With Mall	MR
	• Hose Box	Required	Common With Mall	MR
12.	Yard Hydrants			
	• Total number of hydrants	N/A	Common With Mall	N/A
	• Hose Box	N/A	Common With Mall	N/A
13.	Pumping Arrangements			
	• Ground Level			
	➤ Discharge of main pump	2280LPM	Common With Mall	MR
	➤ Head of main pump	70MH	Common With Mall	MR
	➤ Number of main pumps	1	Common With Mall	MR
	➤ Jockey pump out put	180LPM	Common With Mall	MR
	➤ Jockey pump head	70MH	Common With Mall	MR
	➤ Standby Pump out put	2280LPM	Common With Mall	MR
	➤ Standby Pump Head	70MH	Common With Mall	MR
	➤ Auto Staring/Manual stopping	Required	Common With Mall	MR
	➤ Pump House Access	Required	Provided	MR
	• Terrace level			
	➤ Discharge of pump	450 LPM	Common With Mall	MR
	➤ Head of the pump	40 MTR	Common With Mall	MR
	➤ Power supply	Required	Common With Mall	MR
	➤ Auto starting of pump	Required	Common With Mall	MR
14.	Captive water Storage for fire fighting			
	• Underground tank capacity	Required	Common with Mall	MR
	➤ Draw of connection	N/A	N/A	N/A
	➤ Fire service inlet	N/A	N/A	N/A

6/N

15.	Exit Signage	Required	Provided	MR
16.	Provision of Lifts			
	➤ Pressurization of Lift Shaft	N/A	N/A	N/A
	➤ Pressurization of lift lobby	N/A	N/A	N/A
	➤ Communication in lift Car	N/A	N/A	N/A
	➤ Fireman's Grounding Switch	N/A	N/A	N/A
	➤ Lift Signage	N/A	N/A	N/A
17.	Standby power supply	N/A	N/A	N/A
18.	Refuge Area	N/A	N/A	
	➤ Total area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
19.	Fire control room			
	➤ Detector system panel	N/A	N/A	N/A
	➤ Flow Switch Panel	N/A	N/A	N/A
	➤ PA System Panel	N/A	N/A	N/A
	➤ Batter backup	N/A	N/A	N/A
	➤ Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection Systems for Protection of special Risks, if any;	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards of fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

DO/WD

[Signature] 9/11/2020

[Signature] 8/11/2020

Signature of the Inspecting Officer
Name : Ashok Kumar Jaiswal
Designation : A.D.O. (Jwala Puri)

Dy. HO (W2)

[Signature] 10/11/2020

Cto ex clc
[Signature] 16/11/2020

DO/JA

FT letter is put up for sign bl
[Signature]

12/11/2020