GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/EH/SZ/2020/24

Dated: 17/01/2020

FIRE SAFETY CERTIFICATE

Issued on $\frac{12020}{12020}$ at New Delhi by.

Director Ph.: 011-23414250

5,611

Copy to:-

- Sh. Daljeet Singh (Owner),
 M/s. Reefuel Cafe (A DKS Hospitality Pvt. Ltd.)
 15A/59, W.E.A, Karol Bagh, New Delhi
- 2. The Deputy Health Officer,
 North Delhi Municipal Corporation,
 Karol Bagh Zone, New Delhi- 110005.
- 3. The Joint Commissioner of Police (Lic), 1st Floor, Police Station Defence Colony, New Delhi- 110024.

CONDITIONS

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non-functional of fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained firefighting staffs should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. All the means of escapes /exits shall not be locked/bolted/blocked at any time for safe evacuation of the occupants in case of any emergency.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in

1. Name & address of the building : M/s. Reefuel Cafe' (A unit of DKS hospitality Pvt. Ltd.), 15A/59, WEA, Karol Bagh, New Delhi- 110005.

2. Type of Occupancy : Assembly (Restaurant)

3. Type of Case : New Case

4. Details of previous NOC : N/A5. Fire Safety directives letter No : N/A.

6. Date of inspection : 19.12.2019

7. Name of the Inspecting Officers: Rajbir Kharb, ADO(SRd)

8. Name and designation of officers

from the building side : Sh. Daljeet Singh (Owner)

9. Year of Construction : 2004

10. Applicant's letter No. : Received Online vide application No. 2019121000864

The said restaurant is running at Ground Floor of a building comprised of basement, ground and three upper floors.

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement a UBBL / NBC-I	Provided at sit	e Remarks MR/NMR			
1	Access to building			WIR/NMR			
	• Road width	06 mts	Provided	MD			
	Gate width	4.5 mts	Provided	MR MR			
	• Width of internal road	N/A	N/A	N/A			
2	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases	_	_	-			
	Upper Floors	N/A	N/A	Restaurant runnin			
	Basements	N/A	N/A	at GF only			
	b. Width of staircases	-	- IN/A	N/A			
	Upper Floors Basements	N/A	N/A	Restaurant runnin			
		N/A		at GF only Restaurant running			
	c. Protection of exits	IN/A	N/A	at GF only			
	Fire check door	-	-	-			
	Pressurization e. No. of continuous staircases to terrace g. Width of Corridor h. Door Size	N/A	N/A	N/A			
		N/A	N/A	N/A			
9		N/A	N/A	N/A			
1		N/A	N/A	N/A			
		2.0 mts.	Provided (02 nos)	MR			
-	Compartmentation.						
	Fire check door	N/A	N/A	N/A			
	Sealing of electrical shafts	N/A	N/A	N/A			
	Fire Rating of shaft door	N/A	N/A	N/A			
	Water Curtain	N/A	N/A	N/A			
	• Fire Dampers	N/A	N/A	N/A			
S	Smoke Management System.						
	Basements	30 a/c per hour	N/A	Restaurant running			
	• ground floor	12 a/c per hour	Natural ventilation	at GF only MR			

5	Fire Extinguishers			
	Total numbers	07	Provided	MR
	• Types	CO ₂ , ABC type	Provided	MR
	IS marking	ISI marked	Provided	MR
6	First-Aid Hose Reels.			IVIIC
	 Total numbers on each floor 	01	Provided	MR
	• Length of hose reel hose	30 m	Provided	MR
	Nozzle diameter	5 mm	Provided	MR
7	Automatic fire detection and alarmin	ng system.		
	• Type of detectors	N/A	N/A	N/A
	Location of Main Panel Location of Panel	N/A	N/A	N/A
	Location of Repeater PanelAlternate source of power	N/A	N/A	N/A
	 Hooters' Location 	N/A	N/A	N/A
0	MOEFA	N/A	N/A	N/A
8		Required	Provided	MR
9	Public Address System.	N/A	N/A	N/A
10	Automatic Sprinkler System.			9
	BasementEntire Restaurant	N/A	N/A	N/A
	 Sprinkler above false ceiling 	N/A	N/A	N/A
11		N/A	N/A	N/A
11	Internal Hydrants • Size of riser/down-comer	100		
	 Number of hydrants per floor 	100 mm	Provided	MR
	Hose Box	01	Provided	MR
		01	Provided	MR
12	Yard Hydrants.			
	Total number of hydrants Uses Press	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13	Pumping Arrangements.			
	Ground Level			
	Discharge of main Pump	N/A	N/A	N/A
	Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	Jockey Pump out put	N/A	N/A	N/A
	Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	Auto Starting/ Manual stopping	N/A	N/A	N/A
*	> Pump House Access	N/A	N/A	N/A
	Terrace level			
	Discharge of pump	450 LPM	Provided	MR
	Head of the pump	30 mts	Provided	MR
	Power Supply	Required	Provided	MR
	Auto Starting of pump	Required	Provided	MR

1		11-3					
14	Captive Water Storage for fire figh	iting.					
	 Underground tank capacity 	N/A	N/A	N/A			
	Draw-off connection	N/A	N/A	N/A			
	Fire service inlet	N/A	N/A	N/A			
	Access to tank	N/A	N/A	N/A			
	Overhead Tank capacity	20,000	Provided	MR			
15	Exit Signage.	Required	Provided	MR			
16	Provision of Lifts.						
	Pressurization of Lift Shaft	N/A	N/A	N/A			
	Pressurization of Lift lobby Communication Lift lobby	N/A	N/A	N/A			
*	• Communication In lift Car	N/A	N/A	N/A			
	Fireman's Grounding SwitchLift Signage	N/A	N/A	N/A			
7		N/A	N/A	N/A			
8	Standby power supply	Required	Provided	MR			
	Refuge Area.						
	Total Area	N/A	N/A	N/A			
	Location	N/A	N/A	N/A			
)	Fire Control Room						
	Detector System Panel	N/A	N/A	N/A			
	Flow Switch Panel	N/A	N/A	N/A			
	PA System Panel Batter backup	N/A	N/A	N/A			
	Building Floor Plans	N/A	N/A	N/A			
	Special Fire Protection Systems for	N/A	N/A	N/A			
	Protection of special Risks, if any:	Required	Two ABC type fire extinguisher found provided near elect. panel	MR			

The fire protection systems provided in the building were checked and found functional at the time of inspection.

In view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules, it is recommended to grant fire safety certificate under Delhi Fire Service Act-2007 & Rules-2010. DFA is put up for approval & signature please.

Do Colo)

Rajbir Kharb
Asstt. Div. Officer (S.Rd)

Mat is the use of basement & upper floor?

A00(820)

23/12/19/18

Sin

Basement and upper floors are others proposed