GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No.F.6/DFS/MS/School/2020/SZ / 35

Dated: 31 1 20 20

FIRE SAFETY CERTIFICATE

Certified that the Nagar Nigam Prathmik Adarsh Bal Vidyalaya, Ghumanhera, New Delhi-110073, comprised of ground floor only, was issued Fire Safety Certificate by this department vide letter No F.6/DFS/MS/School/2016/SZ/1455 dated 28.09.2016 owned/occupied by S.D.M.C. was re-inspected by the officer concerned of this department on 08.01.2020 in the presence of Smt. Suman (Safai Karamchari) and found that the S.D.M.C Primary School have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed as under.

Issued on. 31 1 20 to at New Delhi.

(RAJESH PANWAR) Dy. CHIEF FIRE OFFICER SOUTH ZONE

Copy to:-

 The Principal, Nagar Nigam Prathmic Adarsh Bal Vidyalaya, Ghumanhera, New Delhi-110073

Director of Education,
 S.D.M.C, Civic Centre,
 Minto Road, New Delhi-110001.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

Ground Floor Only INSPECTION REPORT Nagar Nigam Prathmic Adarsh Bal Vidyalaya, Ghumanhera, New 1. Name & address of the building: Delhi-110073. Educational Type of Occupancy Type of Case 3. Renewal 4. Details of Previous NOC F.6/DFS/MS/School/2016/SZ/1455 dated 28.09.2016 5. Fire Safety directives letter No: Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 6. Date of inspection 08.01.2020 7. Name of Inspecting Officer A.D.O. Sandeep Duggal 8. Name and designation of officers From the building side Smt. Suman (Safai Karamchari) Year of Construction Before 2009 10. Applicant's letter No. : NG/GHUM/135 dated 24.09.2019 Minimum Standards on fire prevention and S. No. Dir. Of Edu. Provided at Remarks fire safety U/R 33 Circular dt. site MR/NMR 01.03.2011 1. Access to building Accessible 06 mtrs) Road width 06 mtrs M/R 4.5 mtrs. 3.07 mtrs M/R, being old case Gate width N/A N/A N/A Width of internal road 2. Number, Width, Type & Arrangement of Exits Number of staircases Upper Floors N/A N/A Ground floor only **Basements** N/A N/A N/A Width of staircases Upper Floor N/A N/A Ground floor only Basements N/A N/A N/A Protection of exits Fire check door Pressurization N/A N/A N/A N/A N/A N/A No. of continuous staircases to N/A N/A N/A terrace Width of Corridor N/A N/A N/A 100 cms 113 cms M/R Class room Door Size 3. Compartmentation N/A N/A N/A Fire check door Sealing of electrical shafts N/A N/A N/A Fire Rating of shaft door N/A N/A N/A Water Curtain N/A N/A N/A Fire Dampers N/A N/A N/A 4. **Smoke Management System** N/A N/A N/A **Basements** N/A N/A N/A Upper floors Fire Extinguishers 5. Total numbers 04 no's Provided M/R ABC/CO₂ type **Types** Provided M/R IS marking ISI marked M/R ISI marked First-Aid Hose Reels 6. Total numbers on each floor N/A N/A N/A N/A Length of hose reel hose N/A N/A N/A Nozzle diameter TT/A

1.	Automatic fire detection and alarming system				
	 Type of detectors 	N/A	N/A	N/A	
	 Location of Main Panel 	N/A	N/A	N/A	
	 Location of Repeater Panel 	N/A	N/A	N/A	
	 Alternate source of power 	N/A		N/A	
	Hooters' Location	N/A		N/A	
8.	MOEFA	N/A		N/A	
9.	Public Address System	N/A	N/A	N/A	
10.	Automatic Sprinkler System		/A N/A N/A <		
	 Basement 	N/A	N/A	N/A	
	Ground Floor	N/A	N/A	N/A	
	Sprinkler above false ceiling	N/A	N/A	N/A	
11.	Internal Hydrants				
	Size of riser/down-comer	N/A		N/A	
	Number of hydrants per floor	N/A		N/A	
	Hose Box	N/A	N/A	N/A	
12.	Yard Hydrants				
	 Total number of hydrants 	N/A		N/A	
	Hose Box	N/A	N/A	N/A	
13.	Pumping Arrangements			2	
	Ground Level		*		
	Discharge of main Pump	N/A	N/A	N/A	
	Head of Main pumpNumber of main pumps	N/A	N/A	N/A	
	> Jockey Pump out put	N/A	N/A	N/A	
	> Jockey pump head	N/A	N/A	N/A	
	Standby Pump out put	N/A		N/A	
	Standby Pump Head			N/A	
	Auto Starting/Manual Stopping				
		N/A		N/A	
		N/A		N/A	
	Pump House Access	N/A	N/A	N/A	
	Terrace level				
	Discharge of pump	N/A	N/A	N/A	
	➤ Head of the pump	N/A	N/A	N/A	
	Power Supply	N/A	N/A	N/A	
	> Auto Starting of pump	N/A	N/A	N/A	
14.	Captive Water Storage for fire fighting				
	Underground tank capacity	N/A	N/A	N/A	
	> Draw-off connection	N/A		N/A	
	> Fire service inlet				
	Access to tank	N/A		N/A	
	 Overhead Tank capacity 	N/A		N/A	
4.5	7.1.6	N/A		N/A	
15.	Exit Signage.	N/A	N/A	N/A	
16.	Provision of Lifts.	*	1	(No Lift)	
	Pressurization of Lift Shaft	N/A	N/A	N/A	
	Pressurization of Lift lobby	N/A	N/A	N/A	
	Communication In lift Car	N/A		N/A	
	 Fireman's Grounding Switch 	N/A		N/A	
	Lift Signage				
		N/A		N/A	
4.5		N/A	N/A	N/A	
17.	Standby power supply				
18.	Refuge Area.				
- 4	> Total Area	N/A	N/A	N/A	
	> Location	N/A	N/A	N/A	

Fire Control Room			
 Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans 	N/A	N/A	N/A
	N/A	N/A	N/A
Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A
	 Flow Switch Panel PA System Panel Battery backup Building Floor Plans Special Fire Protection System for Protection of	Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans Special Fire Protection System for Protection of N/A N/A N/A	Detector System Panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans N/A Special Fire Protection System for Protection of N/A N/A N/A N/A N/A N/A N/A N/

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F.6/DFS/MS/School/2016/SZ/1455 dated 28.09.2016 renewal in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation:- Asstt. Divisional Officer

Divisional Officer (South West)

16/1/2021

Diary N. 660
Dated 16/1/2/020

DCB (92)

Ser)

SERLICATION TO COMPANY THE OWNER OF THE OWNER OWNER OF THE OWNER OW

Do m

J20/1/200

ADO (JCP)

1 O A T. Wage.