## GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F.6/DFS/MS/School/2020/SZ/ 31

Dated: 29/61/2020

## FIRE SAFETY CERTIFICATE

Certified that the Ravindra Memorial Public School located at Mandi Road, Sultanpur, New Delhi-110030 comprised of Ground plus One upper floor was issued NOC by this department vide letter No. F6/DFS/MS/School/SZ/2016/1614 Dated 31/10/2016. The premises was re-inspection by officer concerned by this department on 10/01/2020 in the presence of Mr. Virender Khari (Manager) of the school and found that fire prevention and fire safety requirements have deemed complied in accordance with Circular No. 262-362 dated 17/01/2005 issued by Education Directorate, Govt. of NCT of Delhi, and that the premises fit for occupancy class Education Building, Group—B as above with effect from the date of issue of this certificate for period of three years subject to compliance of conditions mentioned below.

Issued on 29/1/202 at New Delhi by

(Rajesh Panwar) Dy. Chief Fire Officer Tel. 011-26189168

## Copy to: -

- 1. The Principal, Ravindra Memorial Public School, Mandi Road, Sultanpur, New Delhi-110030.
  - 2. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi.

## Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. This Certificate cannot be reated as regularization of unauthorized construction, if any.
- 5. The Owner/Occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.
- 6. The Owner/Occupier shall apply for renewal of this Fire Safety Certificate to the Director in the form 'J' [sub rule (1) of rule 37] along with copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in.

1		INSPE	CTION REPORT		N.		
1	Name	& Address of the Building			Road.		
1	Traine & Address of the Dullding		Ravindra Memorial Public School, Mandi Road, Sultanpur, New Delhi-110030				
2	Tuno	f Occupancy	A				
3		of Occupancy ng Comprised of	Educational "Group-B" (School) Ground plus One upper Floor				
-		of Case	Renewal				
5		of Previous NOC	F6/DFS/MS/School/SZ/2016/1614 Dated 31/10/2016				
					31/10/2010		
7		rfety Directives Letter No	DOE Circular No.262-362 dated 17/01/2005				
8		f Inspection of the Inspecting Officers	10/01/2020 Mahmaad ADQ (SD)				
9			Mehmood ADO (SJ) Mr. Virender Khari (Manager)				
9	Name & Designation of Officers from the building side		Wir. Virender Khari (Mahager)				
10		f construction	2000				
11		ant letter No.	R-63/RMPS/031219 dated 03/12/2019				
5.		um standards on Fire Prevention	As Per Old	Provided at Site	Remarks		
No	-	re Safety U/R 33	NOC	I IOVIGER AT SILE	MR/NMR		
1		to Building.	1				
	Access	Road width	Accessible	5m	MR		
,		Gate width	NA	4m	NA		
N.		Width of internal road	N/A	N/A	NA		
2		er, width, type & arrangement of exits	1777.2				
, feet		mber of Staircase					
		Upper floors	One	One	MR		
	ł	Basement floor	N/A	N/A	N/A		
		dth of Staircase	14771	11//1	11111		
		Upper floors	1.50m	1.50m	MR		
	-	Basement floor	N/A	N/A	. N/A		
		otection of exits	27/4		D 1 / A		
	1		N/A	N/A	N/A		
	1	Pressurization	N/A	N/A	N/A		
	d) No	of continuous staircase to terrace	01no	Provided	MR		
	e) W	idth of corridor	N/A	N/A	N/A		
	h Do	or size	1 mtr	1 mtr	MR		
3		ertmentation.			8		
	. 0	Fire check door.	N/A	N/A	N/A		
		Sealing of electrical shafts.	N/A	N/A	N/A		
	, e	Fire rating of shaft door.	N/A	N/A	N/A		
		Water curtain	N/A	N/A	N/A		
× ×		Fire dampers.	NA	NA	NA		
4.	Smoke	Management system.					
-	9	Basement	30 ACPH	NA	MR		
	9	Upper floors	12 ACPH	Open Corridor	N/A		
5.		xtinguishers.		The section			
J.	rire E	Total numbers	06 No's	06No's	MR		
			ABC / CO2	ABC & CO2	MR		
	9	Types					
	9	ISI Marking	ISI marked	Provided	MR		
6.	First A	Aid Hose Reels.					
	9	Total numbers on each floor.	01no	Provided	MR		
		Length of hose-reel hose.	30m	Provided	MR		
		Nozzle Diameter	5mm	Provided	MR		

7 Automatic	five detection 0	l .				
Automatic	Automatic fire detection & alarming system					
	pe of detectors	N/A	N/A	N/A		
	ocation of Main Panel	N/A	N/A	N/A		
	cation of Repeater Panel	N/A	N/A	N/A		
	ternate source of power ooter's location	N/A	N/A	N/A		
8. MOEFA	ooter's location	N/A	N/A	N/A		
		NA	NA	NA		
	dress System	N/A	NA	N/A		
	Sprinkler System			14/14		
	sement	N/A	N/A	N/A		
	per floors	N/A	N/A	N/A		
• Sp	rinkler above false ceiling	N/A	N/A	N/A		
11. Internal H	A		The second secon	14/71		
	e of Riser/Down-comer	N/A	N/A	N/A		
. • Nu	mber of Hydrant per floor	N/A	N/A	N/A		
THE RESERVE OF THE PARTY OF THE	se box.	N/A	N/A			
12. Yard Hydi	ants.		1 4/1 %	N/A		
	al number of hydrants.	N/A	N/A	NI/A		
THE REAL PROPERTY AND ADDRESS OF THE PARTY AND	se box.	N/A	N/A	N/A		
13. Pumping a	rrangements.	4	IV/A	N/A		
• Ground	Level					
Dise	charge of main pump.	N/A	N/A			
> Hea	d of main pump.	N/A	N/A N/A	N/A		
> Nur	nber of main pumps.	N/A	THE RESIDENCE OF THE PARTY OF T	N/A		
> Jock	key Pump output.	N/A	N/A N/A	N/A		
> Jock	key Pump head.	N/A	N/A N/A	N/A		
> Star	dby Pump output.	N/A		N/A		
Star	dby pump head.	N/A	N/A N/A	N/A		
Auto	Starting/Manual Stopping.	N/A	N/A	N/A		
• Terrace	Terrace Level		IN/A	N/A		
> Disc	harge of pump.	220LPM	220LPM	MD		
	d of pump.	40m		MR		
1	er supply.		Provided	MR		
	starting of pump.	Required	Provided	MR		
		Required	Provided	MR		
- Captive wat	Captive water storage for Fire Fighting.					
Undergre	ound tank capacity.	N/A	N/A	N/A		
Drav	v-off connection. Service Inlet.	N/A	N/A	N/A		
1110	ess to tank.	N/A	N/A	N/A		
		N/A	N/A	N/A		
The same of the sa	I tank capacity.	2,500liter	Provided	MR		
5. Exit Signage		Required	Provided	MR		
6. Provisions o				1.117		
	urization of lift shaft.	N/A	N/A	N/A		
	urization of lift lobby.	N/A	N/A	N/A		
	nunication in lift car.	N/A	N/A	N/A		
	nan's switch.	N/A	N/A	N/A		
	ignage.	N/A	N/A	N/A		
17 Standby Pow	er Supply	N/A	N/A			
8. Refuge Area		•	1 1/ / 1	N/A		
Total	area	N/A	N/A	N/A		
• • Locat	ion	N/A				
		1 1/1 k	N/A	N/A		

- (%)	1			27.14	NY/ 8
	6	Detector System Panel.	N/A	N/A	N/A
		0 1 1 0 1	N/A	N/A	N/A
		PA system Panel.	N/A	N/A	N/A
		Battery backup	N/A	N/A	N/A
		Building floor plan	N/A	N/A	N/A
0.	Special Fire Protection System for the Protection of special Risk, if any.				

The fire protection system provided in the building / premises were test checked at random and found functional at the time of inspection.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire measures as required under the DOE circular FSC issued vide letter No F6/DFS/MS/School/SZ/2016/1614 Dated 31/10/2016 renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Mehmood Designation: ADO (SJ)

14/01/2020

A. G.- T Lehr port up for Signestrust. Dend (82)