GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI – 110001

No. F6/DFS/MS/GH/NDZ/2020/58

FIRE SAFETY CERTIFICATE

Dated: /2/02/2020

Certified that the Hotel Wall City situated at 287, Fatehpuri, Delhi-06, comprised of ground + 02 upper floors, ground floor – (commercial use and other's property), 1st floor- (reception + 14 guest rooms), 2nd floor – (15 guest rooms), Terrace floor – (02 store room + 02 staff rooms + dining hall). The guest house was granted FSC by this department vide letter no. F6/DFS/MS/GH/2017/949 dated 04.07.2017 for 29 guest rooms. The premises was re-inspected by the officer concerned of this department on 07.02.2020 in presence of manager and found that the building has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010 and the premises is fit for occupancy of class Residential, sub division A-1, having 29 guest rooms up to third floor only, with effect from A-2 and a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to conditions under rule 38 of Delhi Fire service Rules, 2010 printed below.

Issued on 12/02/3020 at New Delhi by

(Sunil Chawdhary)

Dy. Chief Fire Officer

Delhi Fire Service

Tel: 011-23414262

Copy to:-

- 1. The Addl. Commissioner of Police (Lic), First Floor, P.S. Defence Colony New Delhi
- Hotel Wall City situated at 287, Fatehpuri, Delhi-06.

Condition for the validity of fire safety certificate

- 1. This clearance/FSC shall stand cancelled if guest house owner/occupier fails to comply all other conditions by 31.03.2020 as mentioned in the notification dated 27.05.2019 and any violation of clarification issued on 27.12.2019.
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 3. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

 Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.

INSPECTION REPORT

1.		nd address of the building:	Hotel Wall City s Delhi-06			
2.	Type of occupancy with details of floors:		Residential Group A-1(Ground + 02 upper floors)			
			Ground Fl' – (commercial use, other property)			
		= #		Second Fl'- (15 guest rooms)		
			Terrace floor-(02 store room + 02 staff			
	·		rooms + dining hall)			
3.	Type of		RENEWAL (old ca			
4.	Details of previous FSC:		No. F6/DFS/MS/	GH/2017/949 da	ted	
	_		04.07.2017		2 2	
5.		ety directives no.:	NA	3	N II	
6.		inspection:	07.02.2020	Cl. III		
7.		of the inspecting officer:	ADO Rajesh Kum	ar Shukla		
8.		nd designation of the officer from the				
	building side: Year of construction:		- Manager			
9.	2000 Sept. 2000		1960	20010101255 da	tod	
10.	Referen	ce letter no.: Online ID no. 2020010101255. dated 20.01.2020				
S,No	Minimu	m standard of Fire Prevention and	Requirements	Provide at	Remarks	
	Fire Safe	ety U/R 33	(Existing Fire &	site	MR/NMR	
			Safety Measures)	(PSS)		
1	Access t	to Building				
	А	Road width	06 m	06 m	MR	
	В	Gate width	NA	NA	NA	
	С	Width of internal roads	NA	NA	NA	
2	Numbe	r, Width, Type & Arrangement of Exits	5			
	A	No. Of Staircase:				
		a) Upper Floor	01 no.	01 no.	MR	
		b) Basements	NA	NA	NA	
	B Width of the Staircase:					
		a) Upper floors	80 cms	110 cms	MR	
		b) Basements	NA	NA	NA	
	С	Protection of Exits		4.5		
		a) Fire Check Door	NA	NA	NA	
		b) Pressurization	NA	NA	NA	
	D	No. Of continuous staircase to	NA	NA	NA	
		terrace:			,	
	Е	Width of the corridor	NA	NA	NA	
	F	Door size	1 mtr	1 mtr	MR	
3	Compar	tmentation:				
	Α	Fire Check doors	NA	NA	NA	
	В	Sealing of Electrical Shafts	NA	NA	NA	
	С	Fire rating of shaft Doors	NA _	NA	NA	
	D	Water curtain	NA	NA	NA	
	U	Fire dampers	NA NA	NA	NA	
4	Smoke	management System:		1	2 2	
7	A	Basements	30 ACPH	NA	NA	
	В	Upper floors	12 ACPH	Natural	MR	
-			-6			
5	A A	tinguishers Total numbers	06 no.	06 no.	MR	
	В	Types	CO2 , ABC	CO2, ABC	MR	
	С	ISI marking	Required	Provided	MR	
		131 IIIai Kilig	neganea			

। एस सा सा (इाडया) लिमिटेड

14/17

5	First Aid Hose reel						
	Α	Total no. at each floor	01 No	01 No	MR		
	В	Length of Hose Reel	30 mtrs	30 mtrs	MR		
	С	Nozzle diameter	5 mm	5 mm	MR		
7	Automatic Fire Detection and Alarm System (ADAS)						
	Α	Type of Detectors	NA	NA	NA		
	В	Location of main Panel	NA	NA	NA		
	С	Location of Repeater Panel	NA	NA	NA		
	D	Alternate power Source	NA	NA	NA		
	E	Hooter's location	NA	NA	NA		
8	MOEFA		NA	NA	NA		
9	Public A	Address System	Required	Provided	MR		
10	Automa	Automatic Sprinkler System					
	Α	Basement	NA	NA	NA		
	В	Upper Floor	NA	NA	NA		
Ì	С	Sprinklers above false ceiling	NA	NA	NA		
11	Internal	hydrants					
	Α	Size of the riser/down comer	NA	NA	NA		
	В	No. Of hydrants per floor	NA	NA	NA		
	С	Hose box	NA	NA	NA		
12	Yard Hy	drants					
-	Α	Total no. of hydrants	NA	NA	NA		
	В	Hose box	NA	NA	NA		
13	Pumping arrangements						
	Α	Ground Level					
		a) Discharge of main pump	NA	NA	NA		
		b) Head of main pump	NA	NA	NA		
		c) Number of main pump	NA	NA	NA		
		d) Discharge of jockey pump	NA	NA	NA		
		e) Head of jockey pump	NA	NA	NA		
		f) Discharge of Standby pump	NA	NA	NA		
		g) Head of Standby pump	NA	NA	NA		
		h) Auto starting/ manual	NA	NA	NA		
		stopping					
	B Terrace Level						
	В		225 LPM	225 LPM	MR		
			40 mtrs	40 mtrs	MR		
		b) Head of terrace pump	Required	Provided	MR		
		c) Alternate power supply	Required	Provided	MR		
		d) Auto starting of pump	Required	FTOVIded	1411		
14		Water Storage for Fire Fighting	NA	NA	NA		
	A	Underground tank capacity	NA NA	NA NA	NA NA		
	В	Draw off connection	NA	NA NA	NA		
	С	Fire Service Inlet	NA NA	NA NA	NA NA		
	E	Access to tank	5000 ltrs	5000 ltrs	MR		
	D Overhead tank capacity			Provided	MR		
15	Exit Sign		Required	Provided	IVIR		
16	Provision of lift		l NI A	NIA	NA		
	Α	Pressurization of lift shaft	NA	NA NA			
	В	Pressurization of lift lobby	NA	NA NA	NA		
	С	Communication in lift car	NA	NA NA	NA		
No.	D	Fireman switch	NA	NA	NA		
	E	Lift signage	NA	NA Remided	NA		
17	Standb	y Power Supply	Required	Provided	MR		

18	Refuge Area						
	Α	location	NA	NA	NA		
	В	Total area	NA -	NA	NA		
19	Fire Control Room						
	Α	Fire Detection System panel	NA	NA	NA		
	В	Flow switch panel	NA	NA	NA		
	С	P A system panel	NA	NA	NA		
	D	Battery backup	NA	NA	NA		
	Е	Building floor plan	NA	NA	NA		
20	O Special Fire Protection for special risk if any						

The fire protection system was randomly checked and tested and was found functional at the time of inspection. Pantry on terrace has been removed and has been converted into dining area for occupants of the guest house 02 store and 02 staff rooms were found on terrace along with lift room.

In view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter No. F6/DFS/MS/GH/2017/949 dated 04.07.2017 is recommended to be renewed under Rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name

Rajesh Kumar Shukla

Designation ADO (SPM)

DO (CC)

ycho Cyo 2)

M.S. cell