## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS:DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/EH/WZ/2020/4/

Dated: 14/02/2020

FIRE SAFETY CERTIFICATE

Certified that the Metro Grill Eating House, Unit no. 415 City Centre, Plot No. 1 B-3 Twin District Centre, Sector-10, Robini, Delhi-85 comprised of 03 Basment, Ground + four Upper floors in mall & Restaurant is running at 4th Floor on mall owned/occupied by Metro Grill Eating House, have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of fire service on 21.01.2020 and that the premise is fit for occupancy of class Group-Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the DelhizFire 2/2020 Service Rules, 2010.

Issued on 14/02/2020 at New Delhi by

Tel: 011-23414000

Copy to :-

- (1) Sh. Manish Goyal M/s Metro Grill Eating House, Unit no. 415 City Centre, Plot No. 1 B-3 Twin District Centre, Sector-10, Rohini, Delhi-85.
- (2) Dv. Commissioner of Police, Rohini District.

## Conditions for validity of Fire Safety Certificate;

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the of the management. responsibility
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director on Form'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form "K"is available on

http://www.delhi.gov.in/wps/wem/connect/doit\_fire/FIRE/Home/Fire+Safets+Acts+and+ Rules/

http://www.delhi.gov.in/wps/wcm/connect/doit\_fire/FIRE/Home/Forms

INSPECTION REPORT 1. Name & address of the building: Metro Grill Eating House, Unit no. 415 City Centre, Plot No. 1 B-3 Twin District Centre, Sector-10, Rohini, Delhi-85 :Group D Assembly Building (Eating House) Type of Occupancy : New (Restaurant is running at 4th Floor only) 3. Type of Case 4. Details of Previous NOC : NA 5. Fire Safety directives letter No: F6/DFS/MS/BP/2007/1595 dated 14/06/2007 : 21/01/2020 6. Date of inspection 7. Name of Inspecting Officer : A.K. Sharma 8. Name and designation of officers : Mr. Parmod Kumar (Manager) : 2010 [3 Basement, Ground & 4 Upper Floors] year of conversion taken as on date From the building side : DHO/RZ/2019/904 dated 03/10/19 [O.D-21777, dated 03/10/2019 9. Year of Construction 10. Applicant's letter No. Remarks Provided at site UBBL/NBC Minimum Standards on fire prevention MR/NMR Requirement Access to building[Shopping Mall complex issued FSC vide letter No. F6/DFS/MS/2017/WZ/1073 dated and fire safety U/R 33 No. The second 21/07/20171 MR As Above Restaurant within Road width Mall Gate width Width of internal road Number, Width, Type & Arrangement of Exits[Provided & Maintained by Mall management] 2. a. Number of staircases NA As Above Restaurant within Mall Upper Floors NA As Above Restaurant within Mall Basements b. Width of staircases NA As Above Restaurant within Mall Upper Floor NA Restaurant within Mall As Above Basement c. Protection of exits NA Restaurant within Mall As Above Fire check door NA As Above Restaurant within Mall Pressurization NA As Above Restaurant within Mall d. No. of continuous staircases to terrace NA Restaurant within Mall As Above Width of Corridor NA As Above Restaurant within Mall f. Door Size MR Provided 2m/1.9m m Compartmentation 3. NA Restaurant within Mall As Above Fire check door NA Restaurant within Mall As Above Sealing of electrical shafts NA Restaurant within Mall As Above Fire Rating of shaft door NA As Above Restaurant within Mall Water Curtain NA Restaurant within Mall As Above Fire Dampers Smoke Management System[Provided & Maintained by Mall management] 4. NA As Above 30 ACPH Basements MR As Above 12 ACPH Upper floors Fire Extinguishers MR 5. 5Nos 5 No's Total numbers MR 5/-/-No's ABC/CO<sub>2</sub>/W.CO<sub>2</sub> Types MR ISI marked Provided IS marking First-Aid Hose Reels[Provided & Maintained by Mall management] MR As Above 6. One (Near to Restaurant) Total numbers on each floor MR As Above 30 m Length of hose reel hose MR As Above 5 mm Nozzle diameter Automatic fire detection and alarming system[Provided & Maintained by Mall management] NA 7. As Above NA Type of detectors NA As Above NA Location of Main Panel NA NA As Above Location of Repeater Panel NA NA As Above Alternate source of power

मिन मिन (महिमा) सिमा

एच एस सी सी (डांड्या) लिमिटेड

The fire protection systems provided in the building were tested, checked at random and found in working competition.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

A.K Sharma
ADO (Rohini)

DO (NW)

fuhiputh NOC/FSC of the Mall.

Angle

Sin, The Copy of the

the FSC is placed at Gy

127/2

DOLDOW

Dilash 27/1/20

De 00 we) Link offices

28)1/2020

CF.N

pr speech

BCROW Splen

ecutat 29/1