GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6 / DFS / MS / School/2020/ 7 9

Dated: 1/62/2020

FIRE SAFETY CERTIFICATE

Certified that Grand Amar Public School located at Kh. No. 178, Budhanpur Majra Dabas, Delhi-81 comprised of one block- Ground +One Upper Floor owned/occupied by Grand Amar Public School was issued FSC by this department vide letter no. F6/DFS/MS/2016/School/WZ/1739 dated 01.12.2016. The premises was re-inspected by the officer concerned of this department on 07.02.2020 in presence of Sh. Ajay Dabas, Manager and observed that all the fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education vide letter no 3298-3398 dated 01.03.2011 and the building/ premise is fit for occupancy class Group B Educational with effect from ... It to whom for a period of three years, subject to compliance of the conditions mentioned below:

Issued on ... I was not new Delhi by

(Dharampat Bhardwaj) Dy.Chief Fire Officer Ph.-011-25104544

Copy to: -

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi – 54.

2. The Principal, Grand Amar Public School, Kh. No. 178, Budhanpur Majra Dabas, Delhi-81.

Conditions for the validity of Fire Safety Certificate:

All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of firefighting system.

4 The owner / occupier shall submit a declaration every year in Form "K" provided in the first form is The 2010. Rules schedule of Delhi Fire Service http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.

This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if

6 "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

arts

INSPECTION REPORT

1. Name & address of the building

2. Type of Occupancy

: Grand Amar Public School, Kh. No. 178, Budhanpur Majra Dabas, Delhi-81.

:Educational

3. Type of Case

:Renewal (Ground+1)

4. Details of previous NOC

:F6/DFS/MS/2016/School/WZ/1739

Dated: 01.12.2016

5. Fire Safety directives letter No

: Director of Education Circular no. 3298-3398 dated 01.03.2011

6. Date of inspection

: 07.02.2020

7. Name of the Inspecting Officers

: ADO (RN)

8. Name and designation of officers

from the building side

: Mr. Ajay Dabas

9. Year of Construction

: 2011

10. Applicant's letter No.

: Nil Dairy No. 26064 dated: 26.11.2019

	Minimum Standards on fire prevention and fire safety U/R 33	Director of education	Provided at site	Remarks MR/NMR	
1	Access to building				
	Road width	Accessible	Accessible	MR	
	Gate width	Accessible	Accessible	MR	
	Width of internal road	NA	NA	NA	
2	Number, Width, Type & Arrangement of Exits				
	a. Number of staircases				
	Upper Floors	01	02	MR	
	Basements	NA	NA		
	b. Width of staircases	IVA	NA	NA	
	Upper Floors	1.50mtr	1.50 & 1.20mtr	MR	
	Basements	NA	NA	NA	
	c. Protection of exits				
	• Fire check door	NA	NA	NA	
	Pressurization	NA	NA	NA	
	d. No. of continuous staircases to terrace	NA	NA	NA	
	e. Width of Corridor	NA	NA	MR	
	f. Door Size	1.00 m	1.00m .	MR	
3	Compartmentation.				
	Fire check door	NA	NA	NA	
	Sealing of electrical shafts	NA	NA	NA	
	Fire Rating of shaft door	NA	NA	NA	

all

	Water Curtain	NA	NA	NA	
	Fire Dampers	NA	NA	NA	
4	Smoke Management System.				
	• Basements	30 a/c per hour	NA	NA	
	Upper floors	12 a/c per hour	NA	NA	
5	Fire Extinguishers				
	Total numbers	05	06	MR	
	• Types	ABC	ABC-06	MR	
	ISI marking	ISI Marked	Provided	MR	
6	First-Aid Hose Reels.		riovided	IVIIC	
	Total numbers on each floor	NA	NA	NA	
	 Length of hose reel hose 	NA	NA	NA	
	Nozzle diameter	NA			
7	Automatic fire detection and alarming syst		NA	NA	
	Type of detectors	NA	NA	NA	
	 Location of Main Panel 	NA	NA	NA	
	 Location of Repeater Panel 	NA	NA	NA	
	Alternate source of power	NA	NA	NA	
	Hooters' Location	NA	NA	NA	
8	MOEFA	NA	NA	NA NA	
9	Public Address System.	1111	IVA .	INA	
10	Automatic Sprinkler System.				
	Basement	NA	NA	NA NA	
	Upper Floor	NA	NA	NA	
	Sprinkler above false ceiling	NA	NA	NA	
11	Internal Hydrants				
	Size of riser/down-comer	NA	NA	NA	
	Number of hydrants per floorHose Box	NA	NA	NA	
		NA	NA	NA	
12	Yard Hydrants.				
	Total number of hydrants	NA	NA	NA	
	Hose Box	NA	NA	NA	
3	Pumping Arrangements.				
	• Crowd I				
	• Ground Level		4		
	Discharge of main Pump	N/A	N/A	N/A	



MZ

	➤ Head of Main pump	N/A	N/A	N/A	
	> Number of main pumps	N/A	N/A	N/A	
	> Jockey Pump out put	NA	NA	NA	
	> Jockey pump head	NA	NA	NA	
	Standby Pump out put	N/A	N/A	N/A	
	Standby Pump HeadAuto Starting/ Manual stopping	N/A	N/A	N/A	
	Pump House Access				
		N/A	N/A	N/A	
	Terrace level				
	Discharge of pump	NA	NA	NA	
	Head of the pump	NA	NA	NA	
	➤ Power Supply	NA	NA	NA	
	Auto Starting of pump	NA	NA	NA	
14	Captive Water Storage for fire fighting.				
	Underground tank capacity	NA	NA	NA	
	> Draw-off connection	NA	NA	NA	
	Fire service inlet	NA	NA	NA	
	➤ Access to tank	NA	NA	NA	
	Overhead Tank capacity	NA	NA	NA	
15	Exit Signage.	NA	NA	NA	
16	Provision of Lifts.				
	Pressurization of Lift Shaft	N/A	N/A	N/A	
	Pressurization of Lift lobby	N/A	N/A	N/A	
	Communication In lift Car	N/A	N/A	N/A	
	Fireman's Grounding Switch	N/A	N/A	N/A	
	Lift Signage				
		N/A	N/A	N/A	
17	Standby power supply	N/A	N/A	N/A	
18	Refuge Area.				
	> Total Area	N/A	N/A	N/A	
	Location	N/A	N/A	N/A	
19	Fire Control Room				
	Detector System Panel	N/A	N/A	N/A	
	Flow Switch Panel	N/A	N/A	N/A	
	PA System Panel	N/A	N/A	N/A	
	Batter backup	N/A	N/A	N/A	
		IN/A	IN/A	IN/A	

078

 Building Floor Plans 	N/A	N/A	N/A
Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in director of education Circular dated 01.03.2011, it is recommended to renewal of fire safety certificate issued vide this department letter of even no.1739 dated 01.12.2016.

Signature of the Inspecting Officer

Name :- Rajesh Kumar Designation:- ADO/RN

wel ...

ADOJR.N. F.T.

AS opposed, C.g. retter in fontup to

Jan syndys Pl