GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/GH/SZ/2020/ 7 8

Dated: 25/2/2010

FIRE SAFETY CERTIFICATE

Certified that M/s Hotel Clark International Guest house located at 5/47, Saraswati Marg, W.E.A, Karol Bagh, New Delhi-110005 comprised of basement, ground plus five upper floors, was granted FSC by this department vide letter No.F6/DFS/MS/GH/2017/SZ/185 dated 10.02.2017 for using basement (other's property), ground floor (reception, dining, pantry & shops), first to third floor (08 guest rooms each), fourth & fifth floor (sealed). The owner of the guest house has submitted affidavit for not to use any occupancy above third floor. The premises was re-inspected by the officer concerned of this department on 30/01/2020 in presence of Mr. Sandeep Khurana, owner of the guest house and found that the said guest house have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class residential (guest house) for First Floor (08 guest rooms), Second Floor (08 guest rooms) and Third Floor (08 guest rooms) (total 24 guest rooms only) up to third floor with effect from for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010, printed overleaf.

Issued ______ at New Delhi by.

(SS Tuli)
Dy. Chief Fire Officer (SZ)
Delhi Fire Service

Copy to:-

- 1. The Owner/Occupier, M/s Hotel Clark International Guest house, 5/47, Saraswati Marg, W.E.A, Karol Bagh, New Delhi-110005.
- 2. The Additional C.P.(Lic.), Police Station, Defence Colony, 1st floor, New Delhi.
- 3. Municipal Health Officer, NDMC, Karol Bagh Zone, Anand Parbat, New Delhi- 110005.

Conditions for the validity of Fire Safety Certificate: -

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 6. All comments / directions of licensing department shall always be permitted and followed.
- 7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.
- 9. Basement shall be used as per BBL.
- 10. No temporary shed is allowed on terrace.
- 11. The Fire Safety Certificate is only for Guest Rooms.
- 12. The Gazette Notification of UBBL-2016 amendment inserted as clause No. 7.31 of Chapter-7 by the Directorate of Local **Bodies** vide letter 5(189)/AD/LB/2016/4053-67 dated 27.05.2019 and letter No. F.5(189)/AD/LB/2016/11940-55 dated 25.09.2019 & Letter (189)/AD/LB/2016/171-186 dated 27-12-2019 in respect of existing building (Copy enclosed) shall be implemented by 31.03.2020 under intimation to Delhi Fire Service and if the provisions are not made within the stipulated time then the FSC shall stand null & void.

ADESRO

1. Name & address of the building

: Hotel Clark International Guest house, 5/47, Saraswati

Marg, W.E.A, Karol Bagh, New Delhi- 05

2. Type of Occupancy

: Residential (Guest House)

3. Type of Case

: Renewal

4. Details of previous NOC

: F6/DFS/MS/GH/2017/SZ/185 dated 10.02.2017

5. Fire Safety directives letter No

: Nil

6. Date of inspection

: 30.01.2020

7. Name of the Inspecting Officers

: Rajbir Kharb, ADO (SRD)

8. Name and designation of officers from the building side

: Mr. Sandeep Khurana

9. Year of Construction

: Before 2005

10. Applicant's letter No.

: 443/Joint. CP/Lic(H) dated, New Delhi, the 16.01.2020

The said guest house is comprised of basement (other's property), ground to third floor (08 guest rooms each), fourth & fifth floor (Sealed).

S. No.		Iinimum Standards on fire ention and fire safety U/R 33	Fire Safety Requirements as per NBC/BBL	Provided at site	Remarks MR/NMR			
1	Access to building							
AND THE PROPERTY OF THE PROPER	•	Road width	06 mts	06 mts	MR			
	•	Gate width	4.5 mts	Directly accessible	MR			
	•	Width of internal road	N/A	N/A	N/A			
2	Numb	er, Width, Type & Arrangemen	nt of Exits		e 2			
10		nber of staircases	-	-	3 -			
	•	Upper Floors	01	01	MR			
	•	Basements	01	01	MR			
	b. Wic	th of staircases	-	-	-			
	•	Upper Floors	1.25 mts	1.25 mts	MR being old case			
	•	Basements	1.25 mts	1.50 mts	MR being old case			
	c. Prot	ection of exits	-	-	-			
	•	Fire check door	N/A	N/A	N/A			
	•	Pressurization	N/A	N/A	N/A			
	e. No. o	of continuous staircases to terrace	01	01	MR			
	g. Wic	t <mark>h</mark> of Corridor	1.25 mts	1.25 mts	MR being old case			
	h. Doo	o <mark>r Size</mark>	Old case	0.80 mt.	MR being old case			
3 .	Comp	artmentation.						
12	•	Fire check door	N/A	N/A	N/A			
	•	Sealing of electrical shafts	N/A	N/A	N/A			
	•	Fire Rating of shaft door	N/A	N/A	N/A			
		Water Curtain	N/A	N/A	N/A			
	•	Fire Dampers	N/A	N/A	N/A			

4	Smoke Management System.						
-	Basements	30 a/c per hour	Exhaust fan provided		MR 🔊		
	Upper floors	12 a/c per hour	Natural Ventilation		MR		
5	Fire Extinguishers		1 2	-			
	Total numbers				MR		
	• Types	CO ₂ , ABC, WCO ₂	Provided	,	MR		
	IS marking	ISI marked	Provided		MR		
6	First-Aid Hose Reels.		1101144		17110		
	Total numbers on each floor	01	Provided		MR		
	 Length of hose reel hose 	30 m	Provided		MR		
	Nozzle diameter	5 mm	Provided		MR		
7	Automatic fire detection and alarming	g system.	Trovided		IVIIC		
	Type of detectors	N/A			N/A		
	 Location of Main Panel 	N/A	N/A	Service Service	N/A		
	 Location of Repeater Panel 	N/A	N/A	- Aller Co.	N/A		
	Alternate source of power	N/A	N/A		N/A		
	 Hooters' Location 	N/A	N/A		N/A		
8	MOEFA	Required	Provided		MR		
9	Public Address System.	Required	Provided		MR		
10	Automatic Sprinkler System.			a processor of the contraction o			
	Basement	Required	Provided		MR		
	Upper Floor	N/A	N/A	and the same of th	N/A		
	Sprinkler above false ceiling	N/A	N/A		N/A		
11	Internal Hydrants						
10	Size of riser/down-comer	100 mm	Provided	de de	MR		
	Number of hydrants per floor	01	01		MR		
	Hose Box	01	01		MR		
12	Yard Hydrants.						
	Total number of hydrants	N/A	N/A		N/A		
	Hose Box	N/A	N/A		N/A		
13	Pumping Arrangements.						
	Ground Level						
	Discharge of main Pump	N/A	N/A		N/A		
	Head of Main pump	N/A	N/A		N/A		
	Number of main pumps	N/A	N/A		N/A		
	> Jockey Pump out put	N/A	N/A	The state of the s	N/A		
	Jockey pump head	N/A	N/A	The second second	N/A		
	Standby Pump out put	N/A	N/A	and the same of th	N/A		
	Standby Pump Head	N/A	N/A		N/A		
	Auto Starting/ Manual stopping Pump House Access	N/A	N/A		N/A		
	Pump House Access Terrace level	N/A	N/A		N/A		
	Discharge of pump						
	Head of the pump	450 LPM	450 LPM	The state of the s	MR		
	Power Supply	30 mts	30 mts		MR		
	Auto Starting of pump	Required	Provided		MR		
		Daguirad	Duaridad		MD		

14	Captiv	ve Water Storage for fire fightin	g.				
	•	Underground tank capacity	N/A	N/A	N/A		
	>	Draw-off connection	N/A	N/A	N/A		
	>	Fire service inlet	N/A	N/A	N/A		
	>	Access to tank	N/A	N/A	N/A		
	•	Overhead Tank capacity	10,000 lts	10,000 lts	MR		
15	Exit S	ignage.	Required	Provided	MR		
16	Provision of Lifts.						
	•	Pressurization of Lift Shaft	N/A	N/A	N/A		
	•	Pressurization of Lift lobby	N/A	N/A	N/A		
	•	Communication In lift Car	N/A	N/A	N/A		
	•	Fireman's Grounding Switch	Required	Provided	MR		
	•	Lift Signage	Required	Provided	MR		
17	Stand	by power supply	Required	Provided	MR		
18	Refuge Area.						
	>	Total Area	N/A	N/A	N/A		
	>	Location	N/A	N/A	N/A		
19	Fire Control Room						
	•	Detector System Panel	N/A	N/A	N/A		
	•	Flow Switch Panel	N/A	N/A	N/A		
	•		N/A	N/A	N/A		
	•	2 detter outsing	N/A	N/A	N/A		
	•	Building Floor Plans	N/A	N/A	N/A		
20	_	Fire Protection Systems for tion of special Risks, if any:	Required	Two ABC type fire extinguisher found provided near elect. panel	MR		

The fire protection systems provided in the building were checked and found functional at the time of inspection.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the NOC issued vide letter No. F6/DFS/MS/GH/2017/SZ/185 dated 10.02.2017, renewal under rule 35 of the Delhi Fire Service rules 2010 is recommended.

DFA is put up for approval & signature please.

Signature of the Inspecting Officer Name RAJBIR KHARAB

Asstt. Div. Officer (S. Road)

Whether you checked the CD for the floor plans as per the "building Structure?

and formed as ber the plan