

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001

No. F.6 DFS/MS/School/2020/SZ /81

Dated: 26/02/2020

FIRE SAFETY CERTIFICATE

Certified that N. H. Public school located at A-272, Aali Vihar, Aali Village, New Delhi-110076 was granted FSC by this department vide letter No. F.6/DFS/MS/School/SZ/2016/1562 dated 24/10/2016 for ground floor only. The premises was re-inspected by officer concerned by this department on 31/12/2019 in presence of Mr. Jitender Mohan (Manager) of the school and found that the school management have added one upper floor and known the school building is comprised of ground plus one upper floor and complied with the fire prevention and fire safety arrangements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class "Educational Building" Group-B as above with effect from 2020 for a period of **Three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 26/02/2020 at New Delhi by



(S.S Tuli)

Dy. Chief Fire Officer

Tel. 011-26189168



Copy to: -

1. The Manager, N.H.Public School, A-272, Aali Vihar, Aali Village, New Delhi-110076.
2. The Directorate of Education, Old Secretariat, GNCT of Delhi, New Delhi.

Conditions for the validity of Fire Safety Certificate

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of firefighting system.
4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

INSPECTION REPORT

1	Name & Address of the Building	N.H.Public school located at A-272, Aali Vihar, Aali Village, New Delhi-110076		
2	Type of Occupancy	Educational Building Group-B (School)		
3	Building Comprised of	Ground + 01 upper floors (old building is ground floor only. School management constructed one upper floors now the building is comprised of ground plus one upper floors.		
4	Type of Case	Renewal/Addition of one floor		
5	Details of Previous NOC	F6/DFS/MS/School/2016/SZ/1562 dated 24/10/2016 for ground floor		
6	Fire Safety Directives Letter No	Nil		
7	Date of Inspection	31/12/2019		
8	Name of the Inspecting Officers	ADO Avtar Singh		
9	Name & Designation of Officers from the building side	Mr. Jitender Mohan (Manager)		
10	Year of construction	2007 & 2017		
11	Applicant letter No.	Outdoor Diary no 20397 dated 16/09/2019		
S. No	Minimum standards on Fire Prevention and Fire Safety U/R 33	School Circular	Provided at Site	Remarks MR/NMR
1	Access to Building.			
	<ul style="list-style-type: none"> Road width Gate width Width of internal road 	Accessible -N/A- -N/A-	9 m 6 m -N/A-	MR -N/A- -N/A-
2	Number, width, type & arrangement of exits.			
	a) Number of Staircase			
	➤ First floors	Two	Three	MR
	➤ Second floor	-N/A-	-N/A-	-N/A-
	b) Width of Staircase			
	➤ First floors	1.5 m	1.68m, 1.70m & 0.98m	MR
	➤ Second floor	-N/A-	-N/A-	-N/A-
	c) Protection of exits			
	➤ Fire check door	-N/A-	-N/A-	-N/A-
	➤ Pressurization	-N/A-	-N/A-	-N/A-
	d) No. of continuous staircase to terrace	One	Two	MR
	e) Width of corridor	-N/A-	-N/A-	-N/A-
	f) Door size	Old blk - 1m New blk- 1.2 m	Provided	MR
3	Compartmentation.			
	<ul style="list-style-type: none"> Fire check door. Sealing of electrical shafts. Fire rating of shaft door. Water curtain Fire dampers. 	-N/A- -N/A- -N/A- -N/A- -N/A-	-N/A- -N/A- -N/A- -N/A- -N/A-	-N/A- -N/A- -N/A- -N/A- -N/A-
4	Smoke Management system.			
	<ul style="list-style-type: none"> Basement Upper floors 	-N/A- -N/A-	-N/A- -N/A-	-N/A- -N/A-
5	Fire Extinguishers.			
	<ul style="list-style-type: none"> Total numbers Types ISI Marking 	07 nos ABC/CO ₂ ISI Marked	07 nos ABC/CO ₂ Provided	MR MR MR

6.	First Aid Hose Reels.			
	• Total numbers on each floor	-N/A-	-N/A-	-N/A-
	• Length of hose-reel hose. • Nozzle Diameter	-N/A-	-N/A-	-N/A-
7	Automatic fire detection & alarming system.			
	• Type of detectors	-N/A-	-N/A-	-N/A-
	• Location of Main Panel	-N/A-	-N/A-	-N/A-
	• Location of Repeater Panel	-N/A-	-N/A-	-N/A-
	• Alternate source of power	-N/A-	-N/A-	-N/A-
	• Hooter's location	-N/A-	-N/A-	-N/A-
8.	MOEFA	-N/A-	-N/A-	-N/A-
9.	Public Address System	-N/A-	-N/A-	-N/A-
10.	Automatic Sprinkler System			
	• Basement.	-N/A-	-N/A-	-N/A-
	• Upper floors	-N/A-	-N/A-	-N/A-
	• Sprinkler above false ceiling	-N/A-	-N/A-	-N/A-
11.	Internal Hydrants.			
	• Size of Riser / Down-comer	-N/A-	-N/A-	-N/A-
	• Number of Hydrant per floor	-N/A-	-N/A-	-N/A-
	• Hose box.	-N/A-	-N/A-	-N/A-
12.	Yard Hydrants.			
	• Total number of hydrants.	-NA-	-NA-	-NA-
	• Hose box.	-NA-	-NA-	-NA-
13.	Pumping arrangements.			
	• Ground Level			
	Discharge of main pump.	-N/A-	-N/A-	-N/A-
	➤ Head of main pump.	-N/A-	-N/A-	-N/A-
	➤ Number of main pumps.	-N/A-	-N/A-	-N/A-
	➤ Jockey Pump output.	-N/A-	-N/A-	-N/A-
	➤ Jockey Pump head.	-N/A-	-N/A-	-N/A-
	➤ Standby Pump output.	-N/A-	-N/A-	-N/A-
	➤ Standby Pump head.	-N/A-	-N/A-	-N/A-
	➤ Auto Starting/Manual stopping.	-N/A-	-N/A-	-N/A-
	➤ Pump house access.	-N/A-	-N/A-	-N/A-
	• Terrace Level			
	➤ Discharge of pump.	-N/A-	-N/A-	-N/A-
	➤ Head of pump.	-N/A-	-N/A-	-N/A-
➤ Power supply.	-N/A-	-N/A-	-N/A-	
➤ Auto starting of pump.	-N/A-	-N/A-	-N/A-	
14.	Captive water storage for firefighting.			
	• Underground tank capacity.	-N/A-	-N/A-	-N/A-
	➤ Draw-off connection.	-N/A-	-N/A-	-N/A-
	➤ Fire Service Inlet.	-N/A-	-N/A-	-N/A-
	➤ Access to tank.	-N/A-	-N/A-	-N/A-
	• Overhead tank capacity.	-N/A-	-N/A-	-N/A-
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	• Pressurization of lift shaft.	-N/A-	-N/A-	-N/A-
	• Pressurization of lift lobby.	-N/A-	-N/A-	-N/A-

- N/11 -

	• Communication in lift car.	-N/A-	-N/A-	-N/A-
	• Fireman's switch.	-N/A-	-N/A-	-N/A-
	• Lift signage.	-N/A-	-N/A-	-N/A-
17	Standby Power Supply	-N/A-	-N/A-	-N/A-
18.	Refuge Area			
	• Total area	-N/A-	-N/A-	-N/A-
	• Location	-N/A-	-N/A-	-N/A-
19.	Fire Control Room.			
	• Detector System Panel.	-N/A-	-N/A-	-N/A-
	• Flow Switch Panel.	-N/A-	-N/A-	-N/A-
	• PA system Panel.	-N/A-	-N/A-	-N/A-
	• Battery backup	-N/A-	-N/A-	-N/A-
	• Building floor plan	-N/A-	-N/A-	-N/A-
20.	Special Fire Protection System for the Protection of special Risk, if any.			-N/A-

The management has constructed/added one upper floor and now the building is comprised of ground plus one upper floor. Earlier the school building was granted FSC vide letter no. F6/DFS/MS/School/SZ/2016/1562 dated 24/10/2016 for ground floor only and drawing submitted at C-15.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Accordingly DFA is put up for approval and signature please.


03/01/2020

Signature of the Inspecting Officer
Name : Avtar Singh
Designation: ADO (M.RD)

DO (SD)

It is a case of addition of one upper floor hence am the applicant to come through concerned bldg. sanctioning authority.

06/01/2020

ADO (M.RD.) Sir, The area falls under a taluqa village, therefore plans are not approved by the MCD.
However, School management has submitted as build plan from registered Architect.
Re submitted please



