GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE

NEW DELHI-110 001.

No.F.6/DFS/MS/School/2020/SZ

FIRE SAFETY CERTIFICATE

Dated: 01/03/2020

Certified that the Nav Shiv Shakti Public School, Satyam Vihar, Chanchal Park, New Delhi-110043, comprised of Ground floor plus one upper floor, having total 19 rooms (including Class rooms, Office, Comp. room, Staff room, Library & Store etc.) was issued FSC for by this department vide letter no. F6/DFS/MS/School/2016/SZ/1199 dated 24.11.2016 owned/occupied by the Nav Shiv Shakti Public School. The school was re-inspected by the officer concerned of this department on 10.02.2020 in the presence of Sh. Bhim Singh (Driver) and found that the Nav Shiv Shakti Public School have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" for a period of three years, subject to compliance of the conditions printed as under.

(S.S.TULI) Dy. CHIEF FIRE OFFICER

Copy to:-

- The Manager, Nav Shiv Shakti Public School, Satyam Vihar, Chanchal Park, New Delhi-110043
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

Nav Shiv Shakti Public School, Satyam Vihar, Chanchal Park, New 1. Name & address of the building: Delhi-110043

Educational 2. Type of Occupancy 3. Type of Case Renewal

F6/DFS/MS/School/2016/SZ/1199 dated 24.11.2016

4. Details of Previous NOC5. Fire Safety directives letter No Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011

6. Date of inspection 10.02.2020

7. Name of Inspecting Officer A.D.O. Sandeep Duggal

8. Name and designation of officers

From the building side Sh. Bhim Singh (Driver)

9. Year of Construction Before 2006

S. No.	Minimum fire safety	Standards on fire prevention and U/R 33	Dir. of Edu. Circular Dt. 01.03.2011	Provided at site	Remarks MR/NMR			
1.	Access to building							
	• Ro	ad width	Accessible (06 mtrs)	06 mtrs	M/R			
		te width	Old Case	2.5 mtrs	M/R, being old case			
		dth of internal road	N/A	N/A	N/A			
2.	Number, Width, Type & Arrangement of Exits							
	a. Number	of staircases						
	• U ₁	oper Floors	02 No.'s	02 No.'s	MR			
	• Ba	asements	N/A	N/A	N/A			
	b. Width o	f staircases			1			
		pper Floor	150 cms/additional	125 & 90 cms	M/R			
	• Ba	asements	staircase of 75 cms if less than 150 cms	125 66 90 61115	TVII X			
	c. Protection	on of exits	N/A	·N/A	N/A			
	• Fi	re check door						
	• Pr	essurization	N/A	N/A	N/A			
			N/A	N/A	N/A			
		continuous staircases to	14/71	14/11	1771			
	terrace	of Counidan	NT/A	N/A	N/A			
		of Corridor oom Door Size	N/A		The same of the sa			
	I. Class I	bolli Door Size	N/A	N/A	N/A			
			Old Case	93 cms	M/R, being old case			
3.	Compartmentation							
	• Fir	e check door	N/A	N/A	N/A			
	• Sea	aling of electrical shafts	N/A	N/A	N/A			
	• Fir	e Rating of shaft door	N/A	N/A	N/A			
	• Wa	nter Curtain						
	• Fir	e Dampers	N/A N/A	N/A N/A	N/A N/A			
1.	Smoke Ma	nagement System	IN/A	IN/A	IN/A			
			DI/A	NI/A	N/A			
	• Ba	sement	N/A	N/A				
	• Up	per floors	Required	Natural ventilation	MR			
5.	Fire Extinguishers							
		tal numbers	05 no's	Provided	MR			
		pes	ABC type	Provided	MR			
	• IS	marking	ISI marked	Provided	MR			
5.	First-Aid Hose Reels							
8	• To	tal numbers on each floor	N/A	01 no. Provided	N/A			
	• Le	ngth of hose reel hose	N/A	Provided	N/A			
		ozzle diameter			N/A			

, •	Type of detectors	N/A	N/A	N/A		
	Location of Main Panel	N/A	N/A	N/A		
	Location of Repeater Panel	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
	Hooters' Location	N/A	N/A	N/A		
3.	MOEFA	N/A	N/A	N/A		
9.	Public Address System	N/A	N/A	N/A		
10.	Automatic Sprinkler System					
	Basement	N/A	N/A	. N/A		
	 Ground Floor 	N/A	N/A	N/A		
	Sprinkler above false ceiling	N/A	N/A	N/A		
11.	Internal Hydrants	27/4	27/4	27/4		
	Size of riser/down-comer Number of bardwards and floor	N/A N/A	N/A N/A	N/A N/A		
	Number of hydrants per floorHose Box	N/A	N/A	N/A		
12.	Yard Hydrants	IN/A	IN/A	IN/A		
12.	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13.	Pumping Arrangements	14/11	14/71	14/11		
	Ground Level					
	Discharge of main Pump	N/A	N/A	N/A		
	Head of Main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	Jockey Pump out put	N/A	N/A	N/A		
	Jockey pump head	N/A	N/A	N/A		
	Standby Pump out put	N/A	N/A	N/A		
48	Standby Pump Head	N/A	N/A	N/A		
1	Auto Starting/Manual Stopping	N/A	N/A	N/A		
	Pump House Access	N/A	N/A	N/A		
	Terrace level	14/11	10/11	17/11		
	Discharge of pump	N/A	N/A	N/A		
	> Head of the pump	N/A	N/A	N/A		
* -	Power Supply	N/A	N/A	N/A		
	Auto Starting of pump	N/A	N/A	N/A		
14.	Captive Water Storage for fire fighting					
17.		N/A	N/A	N/A		
	 Underground tank capacity Draw-off connection 		N/A N/A	N/A		
	Fire service inlet	N/A				
	> Access to tank	N/A	N/A	N/A		
	 Overhead Tank capacity 	N/A	N/A	N/A		
		N/A	N/A	N/A		
15.	Evit Signage	N/A	N/A	N/A		
16.	Exit Signage. Provision of Lifts.					
	D	N/A	N/A	N/A		
	Pressurization of Lift ShaftPressurization of Lift lobby					
	Pressurization of Lift lobby Communication In lift Car	N/A	N/A	N/A		
	Fireman's Grounding Switch	N/A	N/A	N/A		
	Lift Signage	N/A	N/A	N/A		
		N/A	N/A	N/A		
17.	Standby power supply	N/A	N/A	N/A		
18.	Refuge Area					
		1		37/		
	Total AreaLocation	N/A	N/A	N/A		
The second secon	Location	N/A	N/A	N/A		

19.	Fir	Fire Control Room			
		Detector System Panel	N/A	N/A	N/A
		Flow Switch Panel	N/A	N/A	N/A
		PA System Panel	N/A	N/A	N/A
		Battery backup	N/A	N/A	N/A
		Building Floor Plans	N/A	N/A	N/A
20.		ecial Fire Protection System for Protection special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter number F6/DFS/MS/School/2016/SZ/1199 dated 24.11.2016 renewal in accordance with the Circular No. F. 6/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education is recommended.

Signature of Inspecting Officer

Name:- Sandeep Duggal

Designation: - Asstt. Divisional Officer