GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

No. F6/DFS/MS/Hotel/2020/NDZ/ 197

Dated: 11/03/2020

FIRE SAFETY CERTIFICATE

(Atul Garg)
Director
Delhi Fire Service

745

To.

M/s Holiday Inn , Plot No. 13-A, Distt. Centre, Mayur Vihar, Delhi.

Copy to:-

The Joint Commissioner of Police (Lic.) 1st Floor, Police Station Defence Colony, New Delhi.

CONDITIONS:

- 1. All the means of escape shall be kept free of all the type of obstruction all the time.
- All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- 5. This Fire Safety Certificate can not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 6. All comments/ directions of the Licensing Department shall always be permitted and followed.
- 7. The owner /occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry"
- 8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT : Holiday Inn (Hotel Eros Plaza) Located at Plot 13 A, Name & address of the building Distt Centre Mayur Vihar, Delhi. : Three basements +Ground +Fourteen upper floors 2. Building is comprised of (Including service floor) : Residential (A-5 Hotel building) 3. Type of Occupancy : Renewal : F.6/DFS/MS/Hotel/2017/NDZ/607 dated-28/04/17 Type of Case 5. Details of Previous FSC : F.6/DFS/MS/Hotel/2011/546/dated-25/03/2011 6. Fire Safety direction letter No : 21/02/2020 8. Name of the Inspecting Officers: : DYCFO Sunil Chawdhary, DO F.Brown & ADO R.K.Yadav 7. Date of Inspection 9. Name of the designation of Officer : Sh. Vipin Kumar (Project Manager) from the building side : 2009-10 10. Year of Construction : Nil Dated 04/02/2020 11. Applicant's letter No Remarks Provided at Site **BBL** Requirement Minimum Standards on fire MR/NMR prevention and fire safety U/R 33 Access to building 1 MR 18 Mtrs. 12 Mtrs Road width MR 6 Mtrs. 4.5 Mtrs. Gate width MR 06 Mtrs. 06 Mtrs. Width of internal road Number, Width, Type and Arrangement of Exits. 2 a. Number of Staircases MR 7 Nos. + two 7 Nos. **Basement** ramps Upper Floor MR 3 Nos. 3 Nos. B. Width of Staircases Basement 1.35 m to 1.5 m MR 1.25 mtrs Ground to 1st Floor MR 2 Nos. of 1.8 M 1.25 & 1.5 Mtrs 3 Nos. of 1.5 M **Upper Floors** MR 1.5 Mtrs each 1.25 Mtrs c. Protection of exits Fire check door MR Provided Required Pressurization MR Provided Required e. No. of continuous staircases to MR 3 Nos. 3 Nos. terrace g. Width of Corridor MR 1.5 to 1.7 M 1.5 M h. Door Size MR 1.1 M 1.0 M Compartmentation. 3 MR Provided Required Fire check door MR Sealed Required Sealing of electrical shafts MR 2 hrs. 2 hrs. Fire rating of shaft door MR Provided Water curtain Required Provided MR Fire Dampers Required Smoke Management System. 4 MR 30 a/c per hour 30 a/c per hour Basement MR 12 a/c per hour 12 a/c per hour Upper floor Fire Extinguisher 5. MR 161 Nos. 80 Nos. Total numbers MIR ABC & Co2 ABC & Co2 types MR ISI marked ISI marked IS marking

N128

5	First-aid-Hose Reels. Total numbers of each floors	04	Nos.	6 Nos.	MR			
	> Basement		Nos.	6 Nos.	MR			
	> Upper Floor		Nos.	3 Nos.	MR			
	Length of hose reel hose	30) m	30 m	MR			
	Nozzle diameter		mm	6 mm	MR			
7	Automatic fire detection and alarming system.							
,	Type of detectors		at or Smoke	Smoke	MR			
			ntrol room	Provided	MR			
	Location of repeater panel Alternate source of power Hooter's location		ception	Provided	MR			
			quired	Provided	MR			
			Corridor	Provided	MR			
			ear Staircases					
8	MOEFA	Req		Provided	MR			
9	Public address System.		equired	Provided	MR			
10	Automatic Sprinkler System.							
10	Basement		Required	Provided	MR			
			Required	Provided	MR			
	Upper floor sprinkler above false ceiling		Required	Provided	MR			
		(cquired						
11	Internal Hydrants		L50 mm	150 mm	MR			
	Size of riser/down-comer		l Nos.	6 Nos.	MR			
	Number of hydrants per floor > Basement		1 Nos.	6 Nos.	MR			
	BasementUpper Floors		3 Nos.	3 Nos.	MR			
	Hose box		Required	Provided	MR			
			Required	1101100				
12	Yard Hydrants.		06 Nos.	07 Nos.	MR			
	Total number of hydrants			07 Nos.	MR			
	Hose Box	06 Nos.	07 1403.					
13	Pumping Arrangements.		Required	Provided	MR			
	Ground Level			2850 LPM	MR			
	Discharge of main Pump		2850 LPM	108 Mtrs	MR			
	> Head of Main Pump		108 Mtrs	02 Nos.	MR			
	> Number of main pumps		2 Nos.	180 LPM	MR			
	> Jockey pump out put		180 LPM 108 Mtrs	108 Mtrs	MR			
		> Jockey pump head		2850 LPM	MR			
		> Standby pump out put			MR			
				108 Mtrs Provided	MR			
		> Auto Starting /Manual		Flovided	1411			
	stopping		Required	Provided	MR			
	Pump House AccessTerrace Level		Required	Provided	12			
			900 LPM	900 LPM	MR			
	Discharge of pump		35 mtrs.	35 mtrs.	MR			
	Head of the PumpPower supply		Required	Provided	MR			
	Power supplyAuto Starting of pump		Required	Provided	MR			



14	Captive Water Storage for Fire Fighting.						
	Underground tank capacity	2,00,000Ltrs.	2,00,000Ltrs.	MR			
	Draw-off connection	Required	Provided	MR			
	Fire service inlet	Required	Provided	MR			
	Access to tank	Required	Provided	MR			
	Overhead Tank capacity	20,000 Liters	20,000 Liters	MR			
15	Exit Signage.	Required	Provided	MR			
16	Provision of Lifts.						
	Pressurization of Lift Shaft	Required	Provided	MR			
	Pressurization of Lift lobby	Required	Provided	MR			
	Communication in lift car	Required Provided		MR			
	Firemen's grounding switch	Required	Provided	MR			
	Lift Signage	Required	Provided	MR			
17	Standby power supply	Required	Provided	MR			
18	Refuge Area.						
	Total area	65 sqr M	6 5 sqr M	MR			
	Location	5 th ,7 th & 9 th	Provided	MR			
		floors					
19	Fire Control Room						
	Detector system panel	Required	Provided	MR			
	Flow switch panel	Required	Provided	MR			
	PA system panel	Required	Provided	MR			
	Batter backup	Required	Provided	MR			
	Building Floor Plans	Required	Provided	MR			
20	Special Fire Protection systems for	Required	Provided	MR			
	protection of special Risks, if any:		, a				

The fire protection systems provided in the building were tested checked found functional at the time of inspection.

Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the rules. The fire safety certificate issued vide letter no. F6/DFS/MS/Hotel2017/NDZ/607 dated 28/04/17 it is recommended to renew Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

Signature of the Inspecting Officer

Name

: R.K.Yadav

Designation

: ADO (LN)

Signature of the Inspecting Officer

: F.Brown

Designation : DO (East)

Signature of the Inspecting Officer

: Sunil Chawdhary

Designation : DYCFO (NDZ)