GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/GH/2020/SZ/ 107

Dated: 18./3/.1020

FIRE SAFETY CERTIFICATE

Certified that Aryan Guest House, 33, Nangli Razapur, Nizamuddin East, New Delhi110013, comprised of Ground floor (Rec. & 01 guest room), 1st floor (02 guest rooms), 2nd floor
(02 guest rooms), 3rd & 4th floor sealed by owner & affidavit submitted was issued FSC by this
department vide letter No. F6/DFS/MS/GH/2016/SZ/1169 dated 19/07/2016. The Guest House
was inspected by officer concerned of this department on 25/02/2020 in the presence of Mr.
Sunil (Manager) and found that the guest house building have deemed complied with the fire
prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules,
2010 and that premises is fit for occupancy class "Residential & Lodging Building, Group- A"
Ground floor (Rec. + 01 guest room), 1st floor (02 guest rooms), 2nd floor- (02 guest rooms),
total 05 guest rooms, 3rd & 4th floor sealed by the owner with effect from 18/13/14 for a period
of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled
under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire
Service Rules, 2010.

Issued 18/3/20 at New Delhi by

(S.S. Tuli) Dy.Chief Fire Officer Delhi Fire Service

Copy to: -

- 1. Manager M/s Aryan Guest House, 33, Nangli Razapur, Nizamuddin East, New Delhi-110013
- 2. Addl Commissioner of Police, Licensing Branch, 1st floor P.S. Defence Colony, New Delhi.

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the firefighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- **4.** Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- **5.** The fire safety certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- **6.** All comments / directions of licensing department shall always be permitted and followed.
- 7. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rule of 2010. The form is available on www.dfs.delhigovt.nic.in.

Continue.....

		M/s. Aryan Guest House 33 N			House 33 Nangli	D			
	2 Type of Occupancy			M/s. Aryan Guest House, 33, Nangli Razapur, Nizamuddin East, New Delhi-110013					
	3 Building Comprised of				Residential, Lodging, Group-A (Guest House)				
	4 Type of Case				Ground + 4 upper floors				
	5 Details of Previous NOC				Renewal				
	6 Fire Safety Directives Letter No			-	F6/DFS/MS/GH/SZ/2016/1169 Dated 19/07/2016				
	7 Date of Inspection			O ———	INII				
	8 Name of the Inspecting Officers			25/02/2020					
	9 Name & Designation of Officers			ADO Avtar Singh					
	10	from the building side			Mr. Sunil (Manager)				
	10	Year of construction			Before	s n			
					05/02/2007	(02 G	froms) 2 nd Floor	01 G/room), 1 st Floor	
	11	11 Applicant letter No.			N/A	(02 G/rooms), 2 nd Floor (02 G/rooms), 3 rd & 4 th Floor sealed by owner, Total- 5 G/Rooms			
	S.	S. Minimum standards on Five			Outdoor Diar				
	No	No Prevention and Fire Safety U/R 33		2 33	Requirements		Provided at Si	te Remarks	
,	1	Acce	ess to Building.		A			MR/NMR	
		•	Road width		Ac in				
		•	Gate width	}	9m Accessib	le	6m approx	MR(old case)	
		•	Width of internal road	-	-N/A-		-N/A-	-N/A-	
	2	Num	ber, width, type & arrange	ment	-N/A-		-N/A-	-N/A-	
		a) IVI	imber of Staircase		or cares.				
			Upper floors		01 No				
		A	Basement floor		-N/A-		01 No	MR	
			idth of Staircase		1 1/71-		-N/A-	-N/A-	
			Upper floors		1.25 m		0.00		
	_		Basement floor		-N/A-		0.90 m	MR(old case)	
	C		tection of exits		1 1/11		-N/A-	-N/A-	
			Fire check door		-N/A-		3 7/4		
			Pressurization		-N/A-		-N/A-	-N/A-	
	d)No. o rrace	f continuous staircase to				-N/A-	-N/A-	
			th of corridor		01 No.		Provided	MR	
		Door			-N/A-		-N/A-	-N/A-	
3			tmentation.		1 m		1m (final exit)	MR	
			Fire check door.				/	TAIL	
		• S	ealing of electrical shafts		-N/A-		-N/A	-N/A-	
		• F	ire rating of shaft door		-N/A-		-N/A-	-N/A-	
		• //	ater curtain		-N/A-		-N/A-	-N/A-	
		FI	re dampers.		-N/A-	*	-N/A-	-N/A-	
4.	Sm	oke M	lanagement system.		-N/A-		-N/A-	-N/A-	
	1	• Ba	asement system.		20 A ODER				
		1	pper floors		30 ACPH		-N/A-	-N/A-	
5.	Fire	ire Extinguishers.			2 ACPH	Nat	tural Ventilation	MR	
			tal numbers	-	06 No 's				
	•	-			C / W.Co2		08 No's	MR	
	•		Marking			AI	BC & W.CO ₂	MR	
6.	First	t Aid	Hose Reels.	10.	I Marked		Provided	MR	
	•	Tot	al numbers on each floor		-N/A-				
MAN					11//1-		01 No's	27/1	

	Nozzle Diameter	-N/A-	5mm	-N)-
7	Automatic fire detection & alarming s			
	Type of detectors	-N/A-	-N/A-	-N/A-
	Location of Main Panel	-N/A-	-N/A-	-N/A-
	• Location of Repeater Panel	-N/A-	-N/A-	-N/A-
	Alternate source of powerHooter's location	-N/A-	-N/A-	-N/A-
	1100ter's location	-N/A-	-N/A-	-N/A-
8.	MOEFA	-N/A-	Provided	-N/A-
9.	Public Address System	-N/A-	-N/A-	-N/A-
10.	Automatic Sprinkler System			
	Basement.	-N/A-	-N/A-	-N/A-
	• Upper floors	-N/A-	-N/A-	-N/A-
	Sprinkler above false ceiling	-N/A-	-N/A-	-N/A-
11.	Internal Hydrants.			
	Size of Riser / Down-comer	-N/A-	-N/A-	-N/A-
	Number of Hydrant per floor	-N/A-	-N/A-	-N/A-
	Hose box.	-N/A-	-N/A-	-N/A-
12.	Yard Hydrants.	I	1	
	Total number of hydrants.	-NA-	-NA-	-NA-
	Hose box.	-NA-	-NA-	-NA-
13.	Pumping arrangements.		-	
	Ground Level			
	Disclares of main many	-N/A-	-N/A-	-N/A
	Discharge of main pump.Head of main pump.	-N/A-	-N/A-	-N/A-
	Number of main pumps.	-N/A-	-N/A-	-N/A-
	Jockey Pump output.	-N/A-	-N/A-	-N/A-
	> Jockey Pump head.	-N/A-	-N/A-	-N/A-
	Standby Pump output.Standby Pump head.	-N/A-	-N/A-	-N/A-
	> Auto Starting/Manual	-N/A-	-N/A-	-N/A-
	Stopping.	-N/A-	-N/A-	-N/A-
	Pump house access.	-N/A-	-N/A	-N/A-
	Terrace Level			
	Discharge of pump.	-N/A-	450 LPM	-N/A-
	> Head of pump.	-N/A-	40 m	-N/A-
	Power supply.Auto starting of pump.	-N/A-	Provided	-N/A-
1.4		-N/A-	Provided .	-N/A- /
14.	Captive water storage for firefighting.		NT/A	™ T/A
	• Underground tank capacity.	-N/A-	-N/A-	-N/A-
	> Draw-off connection.	-N/A-	-N/A-	-N/A-
	Fire Service Inlet.	-N/A-	-N/A-	-N/A-
	Access to tank.	-N/A-	-N/A-	-N/A-
	Overhead tank capacity.	-N/A-	4,000 ltrs	-N/A-
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	Pressurization of lift shaft.	-N/A-	-N/A-	-N/A-
4	Pressurization of lift lobby.	-N/A-	-N/A-	-N/A-
	Communication in lift car.Fireman's switch.	-N/A-	-N/A-	-N/A-
	THEMAILS SWITCH.	-N/A-	-N/A-	-N/A-

	• I	ift signage.	-N/A-	-N/A-	-N/A-		
1	Standby	Power Supply	-N/A-	Provided	-N/A-		
18.	Refuge	ge Area					
	• 7	Total area	-N/A-	-N/A-	-N/A-		
	• I	Location	-N/A-	-N/A-	-N/A-		
19.	Fire Control Room.						
	• I	Detector System Panel.	-N/A-	-N/A-	-N/A-		
	• F	low Switch Panel.	-N/A-	-N/A-	-N/A-		
		A system Panel.	-N/A-	-N/A-	-N/A-		
		Battery backup Building floor plan	-N/A-	-N/A-	-N/A-		
	•		-N/A-	-N/A-	-N/A-		
20.	Specia	l Fire Protection System for	-N/A-	-N/A-	-N/A-		
	the Protection of special Risk, if any.						

The Fire protection systems provided in the premises were checked / operated at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter no. F.6/DFS/MS/GH/2016/SZ/1169 dated 19/07/2016, renewal under rule 37 of the Delhi Fire Service rule 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

M. add greatle notification w. 22/09/3030

Signature of the Inspecting Officer
Name: Avtar Singh
Designation: ADO (M.Rd)

Gazzette Notification no. Bonditions es added in the DFA.

Resubmitted please