

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001

No. F6/DFS/MS/2017/774

Dated: 30.05.17

FIRE SAFETY CERTIFICATE

Certified that the Garg Hospital at 8-9, A.G.C.R Enclave (Opp. Karkardooma Court), Delhi 110092, comprised of basement, ground plus three upper floors only owned/occupied by Garg Hospital was issued NOC vide letter No. F6/DFS/MS/Hospital/2013/NDZ/1122 dated 23/10/13. The hospital building was re-inspected by a the officer concerned of this department on 23/05/17 in the presence of Dr. Siddarth, Administrative officer of the hospital and found that the hospital have deemed complied with the fire prevention and fire safety requirements in accordance with rules 33 of the Delhi Fire Service Rules, 2010 and observed that the building is fit for occupancy class "C" 'Institutional Building' with effect from 30.05.17... for a period of **three** years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, printed overleaf.

Issued on.....30.05.17.....at New Delhi by

W 29/5
(Vipin Kental)
Chief Fire Officer

To,
The Director
M/s Garg Hospital
8-9, A.G.C.R Enclave (Opp. Karkardooma Court),
Delhi 110092

Copy:-
The Directorate of Health Services
M.O. I/C Nursing Home Cell,
Govt. of NCT of Delhi,
F-17, Karkardooma
Delhi-110032

CONDITIONS

1. All the means of escape shall be kept free of all type of obstruction all the time.
2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
5. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction /unauthorized use of land if any.
6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.
7. The owner / occupier shall apply for renewal of this Fire Safety Certificate of the Director in Form 'J' [sub rule (1) of rule (37)] along with a copy of this Certificate, Six Months prior to its expiry.

1. Name & address of the building : Garg Hospital at 8-9, A.G.C.R Enclave
(Opp. Karkardooma Court), Delhi 92
2. Building is comprised of : B + G + 3 upper floors
3. Type of Occupancy : Institutional (Hospital Building)
4. Type of Case : Renewal
5. Details of Previous NOC letter : F6/DFS/MS/Hospital/2013/NDZ/1122 dated 23/10/13
(for B + G + 2 only)
6. Fire Safety directive letter No : Delhi Fire Service Act, 2007 and Rules 2010
7. Date of Inspection : 23/05/2017
8. Name of the Inspecting officers : ADO V. B. Yadav
9. Name and designation of officer from the building side : Dr. Siddarth (Administrative Officer)
10. Year of construction : 1993
11. Applicant's letter No : 22/05/2017

Sr. No.	Minimum Standards on Fire Prevention and Fire Safety U/R33	NBC Part-IV Requirements	Provided at Site	Remarks MR/NMR
01	Access to Building.			
	• Road width	06 mtr.	18 mtr.	MR
	• Gate width	N/A	N/A	N/A
	• Width of internal road	N/A	N/A	N/A
02	Number, Width, Type and Arrangement of Exits.			
	a. Number of Staircases			
	• Upper floor	01 nos.	03 nos.	MR
	• Basement	01 nos.	02 nos.	MR
	B. Width of Staircases			
	• Upper floor	02 mtr.	02 mtr. & 02 Nos of 1.10 mtrs each	MR
	• Basement	1.25 mtr.	1.10 mtrs & 1.10 mtrs	MR _(Old accepted)
	c. Protection of Exits			
	• Fire check door	N/A	N/A	N/A _(Old accepted)
	• Pressurization	N/A	N/A	N/A
	d. No. of Continuous Staircases to Terrace	01 no.	01 no.	MR
	e. Width of Corridor	N/A	N/A	N/A _(Old accepted)
	f. Door Size	01 mtr.	01 mtr.	MR
03	Compartmentation.			
	• Fire check door	N/A	N/A	N/A _(Old accepted)
	• Sealing of electrical shafts	Required	Provided	MR
	• Fire rating of shaft door	Required	Provided	MR
	• Water curtain	N/A	N/A	N/A
	• Fire dampers	N/A	N/A	N/A
04	Smoke Management System.			
	• Basement	Required	Ventilated	MR
	• Upper floor	Required	Ventilated	MR
05.	Fire Extinguishers.			
	• Total numbers	20 nos.	24 nos.	MR
	• Types	ABC /CO ₂	ABC /CO ₂	MR
	• IS marking	ISI marked	ISI marked	MR

06	First-Aid-Hose Reels.			
	• Total numbers on each floor	1 no.	1 no.	MR
	• Length of hose reel hose	30 mtrs	30 mtrs	MR
	• Nozzle diameter	05 mm	05 mm	MR
07	Automatic Fire Detection and Alarming System.			
	• Type of detectors	Smoke & Heat	Provided	MR
	• Location of main panel	Required	Provided	MR
	• Location of repeater panel	Required	Provided	MR
	• Alternate source of power	Required	Provided	MR
	• Hooter's location	Required	Provided	MR
08	MOEFA	Required	Provided	MR
09	Public Address System.	Required	Provided	MR
10	Automatic Sprinkler System.			
	• Basement	Required	Provided	MR
	• upper floor	N/A	N/A	N/A
	• sprinkler above false ceiling.	N/A	N/A	N/A
11	Internal Hydrants			
	• size of riser/down-comer	100 mm	100 mm	MR
	• Number of hydrants per floor	01 no.	01 no.	MR
	• Hose box	01 no.	01 no.	MR
12	Yard Hydrants.			
	• Total number of hydrants	N/A	N/A	N/A
	• Hose box	N/A	N/A	N/A
13	Pumping Arrangements.			
	➤ Ground Level			
	• Discharge of main pump	N/A	N/A	N/A
	• Head of main pump	N/A	N/A	N/A
	• Number of main pumps	N/A	N/A	N/A
	• Jockey pump out put	N/A	N/A	N/A
	• Jockey pump head	N/A	N/A	N/A
	• Standby pump out put	N/A	N/A	N/A
	• Standby pump head	N/A	N/A	N/A
	• Auto starting /manual stopping	N/A	N/A	N/A
	• Pump house access	N/A	N/A	N/A
	➤ Terrace Level			
	• Discharge of pump	1620 lpm	1620 lpm X 2	MR
	• Head of the pump	54 M	54 M	MR
	• Power supply	Required	Provided	MR
	• Auto starting of pump	Required	Provided	MR
14	Captive Water Storage for Fire Fighting.			
	• Underground tank capacity	N/A	N/A	N/A
	• Draw-off connection	N/A	N/A	N/A
	• Fire service inlet	N/A	N/A	N/A
	• Access to tank	N/A	N/A	N/A
	• Overhead tank capacity	50,000 Ltr.	50,000 Ltr.	MR
15	Exit Signage.	Required	Provided	MR

16	Provision of Lifts			
	• Pressurization of lift shaft	Required	Provided	MR
	• Pressurization of lift lobby	N/A	N/A	N/A
	• Communication in lift car	Required	Provided	MR
	• Firemen's grounding switch	Required	Provided	MR
	• Lift signage	Required	Provided	MR
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area.			
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A
19	Fire Control Room			
	• Detector system panel	N/A	N/A	N/A
	• Flow switch panel	N/A	N/A	N/A
	• PA system panel	N/A	N/A	N/A
	• Battery backup	N/A	N/A	N/A
	• Building floor plans	N/A	N/A	N/A
20	Special Fire Protection systems for protection of special Risks, if Any:	N/A	N/A	N/A

The hospital building was issued FSC vide letter No. F6/DFS/MS/Hospital/2013/NDZ/1122 dated 23/10/13 (for B+G+2 only). The management has provided 50, 000 liters over head tank with two terrace pump of capacity 1620 lpm which is accepted as a old case.

Keeping in view the deemed compliance of the minimum standards on fire prevention and fire safety required under the rules, it is recommended to issue Fire Safety Certificate.

[Handwritten Signature]
23/5/17

Signature of the Inspecting Officer
Name :- V. B. Yadav
Designation :- A.D.O (T.Pur)

01/10/17

[Handwritten Signature]
24/5

173/CFM/12
26/5-29/5

C.F.O. M. Seel *FTM.*
26/5/17

As approved FT letter is put up for signature please.

eFO(NDZ) *M. Seel* *29/5*

[Handwritten Signature]
29/5/17