GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F6/DFS/MS/SZ/Hospital/2020/ 4 60

Dated: 05/10/20

FIRE SAFETY CERTIFICATE

Certified that the Burn & Plastic Unit located at All India Institute for Medical Science (AIIMS), New Delhi-110029 comprised of 3basement, ground plus eight upper floors. The premises was inspected by the officers concerned by this department on 25/09/2020 in the presence of Mr. Anil Ahluwalia and found that the building have compiled with the fire prevention and fire safety arrangements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy Group C "Institutional Building" (Hospital) with effect from or sooner cancelled under rule 40 and subject to compliance of the condition under rule 38 of the Delhi Fire Service Rules, 2010, subject to condition mentioned below.

Issued on <u>o5/(o/20</u> at New Delhi by

Director Delhi Fire Service

Copy to: -

1. Executive Engineer (Bldg.), New Delhi Muncipal Council, Palika Kendra, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. This Certificate cannot be treated as regularization of unauthorized construction, if any.
- 5. The Owner/Occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available on www.dfs.delhigovt.nic.in.
- 6. The Owner/Occupier shall apply for renewal of this Fire Safety Certificate to the Director in the form 'J' [sub rule (1) of rule 37] along with copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in.

	INS	PECTION REPORT			
1	Name & Address of the Building	Burn & Plastic Unit at ALLMS Near Trauma Centre, New Delhi			
2	Type of Occupancy	Institutional Building, "C" (Hospital)			
3	Building Comprised of	Three, Basement, Ground Plus Eight upper floors			
4	Type of Case	New			
5	Details of Previous NOC	Nil			
6	Fire Safety Directives Letter No	F6/DFS/MS/BP/2016/Hospital/26 dated 09/02/2016			
7	Date of Inspection	25/09/2020			
8	Name of the Inspecting Officers	S.S. Tuli, Dy. Cfo (SZ),D.B. Mukherjee, DO (SD)			
9	Name & Designation of Officers	Mr. Anil Ahluwalia			
,	from the building side				
10	Year of construction	2020			
11	Applicant letter No.	Email dated 16/09/2020			
S.	Minimum standards on Fire	BBL/NBC	Provided at Site	Remarks	
No.	Prevention and Fire Safety U/R33	Requirements	,	MR/NMR	
1	Access to Building.			MD	
	Road width	9m	Provided	MR	
	Gate width	6m	Provided	MR	
	Width of internal road	6m	Provided	MR	
2	Number, width, type & arrangement	of exits.			
2 10	a) Number of Staircase				
		03Nos	03Nos up to 2 nd Floor	MR	
	> Upper floors.	USINOS	02Nos upto terrace	7	
	> Basement floor.	04Nos + 02 Ramps	Provided	MR	
	b) Width of Staircase	7.1.10.20		27	
	b) Width of Staircase > Upper floors	02m	2m, 2m & 2.09m	MR	
	Basement floor	02m	2m X 2,2.12m,& 2.32m	MR	
	0 1				
		Required	Provided	MR	
		Required	Provided	MR	
	> Pressurization	Required			
	d) No. of continuous staircase to	Two	Two	MR	
	terrace	3.4	2.4m	MR	
	e) Width of corridor	2.4m	Provided	MR	
	f) Door size	2m & 1.5m	Trovided		
3	Compartmentation.	D :-1	Provided	MR	
	Fire check door.	Required	Provided	MR	
	 Sealing of electrical shafts. 	Required	Provided	MR	
	 Fire rating of shaft door. 	Required	Provided	MR	
	Water curtain	Required	Provided	MR	
	• Fire dampers.	Required	Trovided		
4.	Smoke Management system.	10 / 1	Provided	MR	
	Basement	12 a/c per hour	Provided	MR	
	 Upper floors 	12 a/c per hour	Tiovided	TYLL	
5.	Fire Extinguishers.		14037	MR	
	Total numbers	Required	110Nos		
	Types	ABC / CO2	ABC & Co2	MR	
		ISI marked	Provided	MR	
	ISI Marking	A.V. A. A. A. A. A. V.		:	
6.		Di 1 0021	Provided	MR	
	 Total numbers on each floor. 	Required 02Nos		MR	
1	I a second	30m	30m	IVIIX	
	 Length of hose-reel hose. 	50111	5mm	MR	

	7 Automatic fire detection & alarming	system.		<u> </u>
	 Type of detectors 	Smoke & Heat	Smales 6- II	1.00
	 Location of Main Panel 	Ground Floor	Smoke & Heat	MR
	 Location of Repeater Panel 	Required	Ground Floor	MR
	Alternate source of power	Required	Provided	MR
	Hooter's location	On Each Floor	Provided	MR
8			Provided	MR
9	. Public Address System	Required	Provided	MR
10	. Automatic Sprinkler System	Required	Provided	MR
	Basement	D		
	Upper floors	Required	Provided	MR
		Required	Provided	MR
11	 Sprinkler above false ceiling Internal Hydrants. 	Required	Provided	MR
**				
	Size of Riser/Down-comer	150mm	Provided	MR
	 Number of Hydrant per floor 	02nos	Provided	MR
13	Hose box.	02nos	Provided	MR
12.	- J			IVIIV
	 Total number of hydrants. 	08 no	Provided	MR
10	Hose box.	08 no	Provided	
13.	- Burrangements.		TTOVICE	MR
	Ground Level			1 1
	Discharge of main pump.	2850LPM	Provided	
	Head of main pump.	90m		MR
	Number of main pumps.	03nos (one for W/Curtain)	Provided	MR
	Jockey Pump output.	180LPM X 2	Provided	MR
	Jockey Pump head.	90m	Provided	MR
	Standby Pump output.	2850LPM X 2	Provided	MR
	Standby Pump head.	90m	Provided	MR
	Auto Starting / Manual Stopping.	Required	Provided	MR
	Pump house access.		Provided	MR
	Terrace Level	Required	Provided	MP
	Discharge of pump.	NIA		3
	Head of pump.	-NA-	900LPM	-NA-
	Power supply.	-NA-	25m	-NA-
	Auto starting of pump.	-NA-	Provided	-NA-
14.	Captive water storage for firefighting.	-NA-	Provided	-NA-
	Underground tank capacity.	2.00		
	Draw-off connection.	2,00,000litr	2,00,000litr	MR
	Fire Service Inlet.	Required	Provided	MR
	Access to tank.	Required	Provided	MR
	Overhead tank capacity.	Required	Provided	MR
5.	Exit Signage.	20,000 ltr	20,000liter	MR
6.	Provision of Lifts.	Required	Provided	MR
	Pressurization of lift shaft.		X	
		Required	Provided	MR
The state of the state of	Pressurization of lift lobby.	Required	Provided	MR
	• Communication in lift car.	Required	Provided	MR
	• Fireman's switch.	Required	Provided	MR
7	• Lift signage.	Required	Provided	MR
7.	Standby Power Supply	Required	Provided DG Set	
			TOTIGOU DO SEL	MR
3.	Refuge Area			
	Total area	57.89m2	Dravid 1	100
	 Location 	6 th Floor	Provided	MR
	Location	641 171000	Provided	MR

19.	Fire Control Room.			
170	 Detector system panel. Flow switch panel. PA system panel. Battery backup. Building floor plan. 	Required	Provided	MR
		Required	Provided	MR
		Required	Provided	MR
		Required	Provided	MR
		Required	Provided	MR
20.	Special Fire Protection System for the	Co2 gas flooding provided		MR
	Protection of special Risk, if any.			

The Fire protection systems provided in the building were test checked at random and found functional at the time of inspection.

The shortcoming issued by the department vide letter No.F6/DFS/MS/SZ/Hospital/2020/2036 dated 11/08/2020 have been rectified.

Keeping in view of the substantial satisfactory compliance of the minimum standards on fire prevention and fire safety measures as required under the rule, it is recommended to issue Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules, 2010.

Accordingly DFA is put up for approval and signature please.

Signature of the inspecting Officer

Name: S.S. Tuli

Designation: Dy. Cfo (SZ)

Signature of the inspecting Officer

Name: D. B. Mukherjee Designation: DO (SD)

.CFO (SZ)

80/26

Jan 1 10 202

f T D/

Fine Ont

F.T. letter is mur up

m/01/10/2020