GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110 001.** Dated: 06 10 2020

No.F.6/DFS/MS/School/2020/SZ/ 399

FIRE SAFETY CERTIFICATE

Certified that the Govt. Girls Sr. Sec. School, SPS Block, Hastsal, New Delhi-110059 comprised of ground floor plus three upper floors, having total 24 rooms (including Class rooms, lab, Staff room etc.) owned/occupied by Govt. of NCT of Delhi was issued FSC by this department wide letter no. F.6/DFS/MS/School/2017/SZ/1608 dated 10.11.2017. The school building was re-inspected by the officer concerned of this department on 04.09.2020 in the presence of Sh. Raghvendra Prashad (Estate Manager) and found that the Govt. Girls Sr. Sec. School have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed as below. This department has already issued FSC to two blocks comprised of ground plus one upper floor vide letter dated 23.04.15.

Issued on... 06 10 2020 at New Delhi.

(S.S. TULI) Dy. CHIEF FIRE OFFICER SOUTH ZONE

Copy to:-

- The Principal, Govt. Girls Sr. Sec. School, Hastsal, SPS Block, New Delhi-110059.
- Director of Education, 2. Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

Comprised of Three blocks namely two Pucca Blocks (Old Block & New Block each naving Block Having Ground plus three upper floors and MP Hall Block New case (GF only).

INSPECTION REPORT

Govt. Girls Sr. Sec. School, Hastsal, SPS Block, New Delhi-110059. 1. Name & address of the building:

Assembly Building 2. Type of Occupancy

New 3. Type of Case 4. Details of Previous NOC N/A 5. Fire Safety directives letter No : N/A 04.09.2020 6. Date of inspection

: A.D.O. Sandeep Duggal 7. Name of Inspecting Officer

8. Name and designation of officers

: Sh. Raghvendra Prashad (Estate Manager) From the building side

2017 9. Year of Construction

GGSSS/H/2020/136 dated 21.08.2020 & Form "I" 10. Applicant's letter No.

S. No:	Minimum Standards on fire prevention and fire safety U/R 33	NBC requirements	Provided at site	Remarks MR/NMR			
•	Access to building						
. •		11.06	00	M/R			
	Road width	Accessible 06 mtrs 4.5 mtrs	09 mtrs	MR			
	Gate width	N/A	05 mtrs N/A	N/A			
	Width of internal road	200	IN/A	14/11			
2.	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases	. 1		D			
	Upper Floors	N/A	N/A	N/A			
	Basements	N/A	N/A	N/A			
	b. Width of staircases	. 19/74	11/12	9 2			
	Upper Floor	27/4	DI/A	N/A			
	Basements	N/A	N/A				
		N/A	N/A	N/A			
	c. Protection of exits						
,	 Fire check door 	N/A	N/A	N/A			
	 Pressurization 	N/A	N/A	N/A			
				. ×			
	d. No. of continuous staircases to	N/A	N/A	N/A			
	terrace	N/A	N/A	N/A			
	e. Width of Corridor		*				
	f. MP Hall Door Size	200 cms	170, 132, 110 & 180 cms	NMR			
3.	Compartmentation						
	Fire check door	N/A	N/A	N/A			
	Sealing of electrical shafts	N/A	N/A	N/A			
	Fire Rating of shaft door		N/A	N/A			
	Water Curtain	N/A					
		N/A	N/A	N/A			
	Fire Dampers	N/A	N/A	N/A			
4.	Smoke Management System						
	Dto	N/A	N/A	N/A			
	Basements	Required	Not Provided	NMR			
	Ground Floor	Required					
5.	Fire Extinguishers						
	Total numbers	04 no's	Provided	M/R			
		ABC/CO ₂ type	Provided	M/R			
	Types IS marking	ISI marked	Provided	M/R			
6.	First-Aid Hose Reels			NAME			
0.	Total numbers on each floor	One	Not Provided	NMR			
		30 mtrs	Not Provided	NMR			
1	 Length of hose reel hose 	5 mm	Not Provided	NMR			

	• Type of detectors	N/A	N/A	N/A
	 Location of Main Panel 	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location	N/A	N/A	N/A
8.	MOEFA	N/A	N/A	N/A
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System		*	
	Basement	N/A	N/A	N/A
	Ground Floor	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	Size of riser/down-comer	N/A	N/A	N/A
	Number of hydrants per floor	N/A	N/A	N/A
10	Hose Box	N/A	N/A	N/A
12.	Yard Hydrants	*		- A
	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements			
	• Ground Level			
	Discharge of main Pump	N/A	N/A	N/A
	Head of Main pumpNumber of main pumps	N/A	N/A	N/A
	Jockey Pump out put	· N/A	N/A	N/A
	> Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
×	Auto Starting/Manual Stopping	1117 MOSTERIA		
	N.	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
	Pump House Access			* 1
	Terrace level	450 LPM	Provided but not connected	NMR
	Discharge of pump	30 mtrs	Provided but not	NMR
	Head of the pumpPower Supply		connected	Work Address (Services)
	> Auto Starting of pump	Required	Provided but not connected	NMR
	Trate Starting of pump	Required	Provided but not	NMR
		Troquito a	connected	1117414
14.	Captive Water Storage for fire fighting			* *
		N/A	NI/A	NI/A
	 Underground tank capacity Draw-off connection 		N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	N/A	N/A
		5000 ltrs	Provided but not	NMR
15.	Illuminated Exit Signage.	Required	Not Provided	NMR
16.	Provision of Lifts.	resquired	No Lift	TATATI
10.				
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car Signature Communication Society	N/A	N/A	N/A
	• Fireman's Grounding Switch	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
17	Standby navior and		75 3345 33	
17.	Standby power supply	N/A	N/A	N/A
18.	Refuge Area.			
- Living	> Total Area	N/A	N/A	N/A
	> Location	N/A	N/A	N/A
		NI/A	NI/A	N1//

19.	Fire Control Room			
	 Detector System Panel Flow Switch Panel PA System Panel 	N/A	N/A	N/A
		N/A	N/A	N/A
8	Battery backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
		N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found not functional at the time of inspection.

Keeping in view of the above non compliance of the minimum standards of fire prevention and fire safety measures under rule 35 of the Delhi Fire Service Rules 2010 it is not recommended to grant Fire Safety Certificate and issue shortcomings as noted at serial no. 02 (f), 04, 06, 13, 14 & 15.

Note:- Comprised of Three blocks namely two Pucca Blocks (Old Block & New Block each having G+I) was issued FSC vide leter no. F.6/DFS/MS/School/2018/SZ/433 dated 16.03.2018, SPS Block Having Ground plus three upper floors issued FSC vide letter no. F.6/DFS/MS/School/2017/SZ/1608 dated 10.11.2017 and MP Hall Block New case which is under consideration (GF only).

Signature of Inspecting Officer

Name: - Sandeep Duggal

Designation: - Asstt. Divisional Officer

Divisional Officer (South West)

FT. Lefer is put up for signature please