GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6 DFS/MS/2020/SZ/

Dated:7//0/20

FIRE SAFETY CERTIFICATE

Certified that NBCC Centre located at Plot No.2, Community Centre, Okhla PH-I, New Delhi-110020 comprised of 3 basement, ground and eight upper floors was granted FSC by this department vide letter No. F.6/DFS/MS/2014/SZ/898 dated 22/07/2014. The said premises was reinspected by officer concerned of this department on 23/09/2020 in presence of Mr. Sanjay Jain (DGM, Engg.) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rule 2010 and that is fit for Mixed Occupancy (Mercantile & Business) with effect the building/premises from. 7./10/26. for a period of 3(Three) Years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire service Rules,2010.

Issued on 7/10/20 at New Delhi by

Director

Delhi Fire Service

Copy to: -

- 1. The General Manager, NBCC Centre located at Plot No.2, Community Centre, Okhla PH-I, New Delhi-110020.
- 2. The Jt. Director (Bldg.), DDA, Building Section, INA, Vikas Sadan, New Delhi.

Conditions for the validity of Fire Safety Certificate

- 1. That FSC shall stand Null and Void if shortcomings of point no. 8 &14 are not rectified within six months counted from the date of issuance of renewed FSC.
- 2. All the means of escape/entry/exit shall be kept free from any obstruction.
- 3. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 4. All the staff members must know the correct method of operation of firefighting system.
- 5. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

		ON REPORT	No.2.Community Centre,	Okhla			
	Name & Address of the Burning	NBCC Centre, Plot No.2, Community Centre, Okhla PH-I, New Delhi-110020					
		Class Mixed (E & F) (Mixed Occupancy (mercantile					
)	Type of Occupancy	Q. Duciness)					
		3 Basement, Ground plus Eight upper floors.					
	Building Comprised of	Renewal					
1	Type of Case	F.6/DFS/MS/2014/SZ/898 dated 22/07/2014					
5	Details of Previous NOC	F.6/DFS/MS/2014/32/898 dated 22/6/12/898 dated 22/6/12/898 dated 18/11/2008 &					
5	Fire Safety Directives Letter No	F6/DFS/MS/2016/2681 dated 17/11/2016					
		23/09/2020					
7	Date of Inspection	D.B. Mukherjee DO (SD)					
8	Name of the Inspecting Officers	Mr. A.K.Jain					
9	Name & Designation of Officers	TVIII. 7 X.1 Z.10 dollar	R 6				
	from the building side	2013					
10	Year of construction	Email Dated 10/09	/2020				
11	Applicant letter No.	NBC/BBL Provided at Site		Remarks			
No	Minimum standards on Fire Prevention	Requirements		MR/NMR			
	and Fire Safety U/R 33			. (5			
1	Access to Building.	09m	Provided	MR			
	Road width	4.5m	4.5m	-N/A-			
	Gate width		Provided	MR			
	Width of internal road	6m	1101100				
2	Number, width, type & arrangement of exits.						
	a) Number of Staircase		06Nos	MR			
	> Upper floors	06Nos	The same of the sa	MR			
	> Basement floor	08Nos	08Nos	IVIIC			
	CC4-i		515150				
	b) Width of Starrease > Upper floors.	*1.25m	1.47,1.48,1.5,1.5,1.5 &	MR			
	Opper Hoors.	1.25111	1.47m	-			
			1.25,1.47,1.48,1.5,1.5	MR			
		1.25m	1.5,1.47,1.25m				
	Basement floor						
	c) Protection of exits	Required	Provided	MR			
	> Fire check door		Provided	MR			
	> Pressurization	Required	Provided	MR			
	d) No. of continuous staircase to terrace	e 06no		MR			
	'dow	1.5m	Provided	MR			
	- /	1 m	Provided	IVIIC			
2	f) Door size Compartmentation.		Davidad	MR			
3	Fire check door.	Required	Provided	MR			
	 Sealing of electrical shafts. 	Required	Provided				
	D' of shaft door	Required	Provided	MR			
	IV.	Required	Provided	MR			
	T2' 1 2 m2	Required	Provided	MR			
		Required					
4.	Smoke Management system.	30 a/c per hour	Provided	MF			
	Basement		n '1 1	MF			
	Upper floors	12 a/c per hour	TTOVIGOG				
•••				MI			
			Descrided				
5.	Fire Extinguishers.	70No 's	Provided				
		70No 's ABC / Co2	ABC/C02/WCo2 Provided	MI			

. 1	First Aid Hose Reels.	<u> </u>	Provided	MR
5. I	Total numbers on each floor.	03Nos	Provided	MR
	the flore reel hose	30m		MR
	Nozzle Diameter	5mm Provided		IVIIX
7	Automatic fire detection & alarming system.		Provided	MR
	Type of detectors	Smoke & Heat	Provided	MR
	Location of Main Panel	Required	Provided	MR
	 Location of Repeater Panel 	Required	Provided	MR
	Alternate source of power	Required	Provided	MR
	Hooter's location	Required	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Tioriada	
10.	Automatic Sprinkler System	D 1.1	Provided	MR
10.	Basement.	Required	Provided	MR
	Upper floors	Required	Provided	MR
	Sprinkler above false ceiling	Required	TTOVIGOG	a n
11	Internal Hydrants.		Provided	MR
11.	Size of Riser / Down-comer	150mm	Tiovided	
	Size of the	Basement -04 no	Provided	MR
	 Number of Hydrant per floor 	Upper Floor-03no	11011000	
	Trumos of Try	Terrace-02no		
	 Hose box. 	Basement -04 no	Provided	MR
	Trose com	Upper Floor-03no	110114	n
		Terrace-02no		
12.	Yard Hydrants.	05nos	Provided	MR
12.	Total number of hydrants.	05nos	Provided	MR
	Hose box.	031108	051108	
13.	Pumping arrangements.		V	
	Cround Level	2850LPM	Provided	MR
	Discharge of main pump.	60m	Provided	MR
	▶ Head of main pump.	Two	Provided	MR
	Number of main pumps.	180 LPM X 2	Provided	MR MR
	Jockey Pump output.	60m	100 Li Wi A 2	
	> Jockey Pump head.	2850LPM	Provided	MR
	Standby Pump output.	60m	Provided	MR
	Standby Pump head.		Provided	MR
	Auto Starting/Manual stopping	Required	Provided	MR
	Pump house access.	Required	110,144	
	Terrace Level	21/4	900LPM X 2	-N/A-
	Discharge of pump.	-N/A-	40 m	-N/A-
	> Head of pump.	-N/A-	Provided	-N/A-
	> Power supply.	-N/A-	Provided	-N/A-
	> Auto starting of pump.	-N/A-	1101100	
14	Captive water storage for firefighting.	0.00.0001:40	Provided	MR
14	 Underground tank capacity. 	2,00,000liter	Provided	MR
	> Draw-off connection.	Required	Provided	MR
	Fire Service Inlet.	Reduited		MR
	Access to tank.		Required	
	 Overhead tank capacity. 	20,000liter Required	Provided	MR MR
	•	Required	IIUVICC	7

16.	Provision of Lifts.			D 11.1	MD
	 Pressurization of lift shaft. 	Requir		Provided	MR
	 Pressurization of lift lobby. 	Required Required Required Required Required		Provided Provided	MR MR
	• Communication in lift car.				
	• Fireman's switch.			Provided	MR
	Lift signage.			Provided	MR
17	Standby Power Supply			Provided	MR
18.	Refuge Area				1.69
	Total area	65m2 7 th Floor		55m2 Provided	MR
					Old Case
	• Location				MR
19.	Fire Control Room.				
17.	Detector System Panel.	-N/A-		-N/A-	-N/A-
	Flow Switch Panel.	-N/A-		-N/A-	-N/A-
	PA system Panel.	-N/A-		-N/A-	-N/A-
	Battery backup	-N/A-		-N/A-	-N/A-
	Building floor plan	-N/A-		-N/A-	-N/A-
20.	Special Fire Protection System for	Manual Co2		Provided	MR
	the Protection of special Risk, if any.	+ 2Nos DCP			
		Extinguishe			
		for Ht/LT Panels			
				/ operated at rando	1.0

The Fire protection systems provided in the premises were checked / operated at random and found functional at the time of inspection. The shortcomings issued vide letter no.F.6/DFS/MS/2019/SZ/649 Dated: 03/03/2020 have been rectified except point no. 8 and 14.However a letter no.NSL/CEO/Okhla/607 dt. 25/09/2020 from Dy.Gen. Manager(Engg.) NBCC, in which they have assured to rectify these shortcomings within six month.

Keeping in view of above it is recommended to renew the FSC for six month subject to condition that FSC shall stand Null and Void if above shortcomings are not rectified within six months counted from the date of issuance of renewed FSC. Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer
Name : D.B. Mukherjee

Designation: DO (SD)

DY.CFO (SZ)

161x 161x FIPS

DW F.T. letter is morns for lign bl.