GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F6/DFS/MS/School/WZ/2020/ 411

Dated: 08/10/106

FIRE SAFETY CERTIFICATE

Issued on Alpho at New Delhi by

DIRECTOR
Ph; 011-23414000

Copy to:

- 1. The Principal, Hans Raj International School located at Gol Market Pratap Vihar, Part-I, Kirari, Delhi-110086.
- 2. The Director of Education, Old Secretariat, Delhi

Conditions for validity of Fire Safety Certificate;

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form's' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form "K"is available on http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/

INSPECTION REPORT Previous building-Gr.+02 upper floors Present building-Gr.+03 upper floors 1. Name & address of the building One lab on 3rd floor : Hans Raj International School, Gol Market Pratap Vihar, Part-I, Kirari, Delhi-86. 2. Type of Occupancy : Educational (G+03 Floors) 3. Type of Case : New Case (Addition / Alleration) 4. Details of previous NOC : NA 5. Fire Safety directives letter No : NBC Part-4 6. Date of inspection : 31.07.2020 7. Name of the Inspecting Officers : ADO (Rohini) 8. Name and designation of officers from the building side : Mrs. Aruna / Manager 9. Year of Construction : 2006,2012 & 2019 10. Applicant's letter No. : Nil dated 12.06.2020, O.D No.5783 dated 12.06.2020 Minimum Standards on fire **NBC** Provided at site prevention and fire safety U/R 33 Remarks Requirement 1 Access to building MR/NMR Road width 6m 6m MR Gate width 4.5m 4.5m MR Width of internal road NA NA NA Number, Width, Type & Arrangement of Exits 2 a. Number of staircases Upper Floors 02 02 MR Basements NA NA b. Width of staircases NA Upper Floors 1.50m 1.5m & 1.6m MR Basements NA NA NA c. Protection of exits Fire check door NA NA NA Pressurization NA NA NA d. No. of continuous staircases to terrace 01 01 MR e. Width of Corridor NA NA NA f. Door Size 1 m 1 m MR 3 Compartmentation. Fire check door NA NA NA Sealing of electrical shafts NA NA NA Fire Rating of shaft door NA NA NA Water Curtain NA NA NA Fire Dampers NA NA NA 4 Smoke Management System. Basements 30 a/c per hour NA NA Upper floors 12 a/c per hour Natural Ventilated MID

	Bwoner			
	Total numbers	07nos	09nos	MR
	Types	ABC/CO2	ABC—09	MR
	ISI marking	ISI Marked	Yes	MR
6	First-Aid Hose Reels.			
	 Total numbers on each floor 	01	01each floor	MR
	 Length of hose reel hose 	30m	30m	MR
And the same of th	Nozzle diameter	05mm	05mm	MR
7	Automatic fire detection and alarmin	1111		
O Company of the Comp	• Type of detectors	NA NA	NA	
Annual Property of the Control of th	 Location of Main Panel 	NA	NA NA	NA
		NA	NA NA	NA
	Bootation of Repeater Faller	NA		NA
	Alternate source of power		NA	NA
	 Hooters' Location 	NA	NA	NA
8	MOEFA	NA	NA	NA
9	Public Address System.	NA	NA	NA
10	Automatic Sprinkler System.			
	Basement	NA	NA	N.T.A.
	 Upper Floor 	NA	NA NA	NA
		X		NA
11	Sprinkler above raise centing	NA	NA	NA
1. 1.	Internal Hydrants		12	
	Size of riser/down-comer	NA	NA	NA
	Number of hydrants per floorHose Box	NA	NA	NA
12	Yard Hydrants.	NA	NA	NA
	AND CONTRACTOR OF THE LIGHT AND ADDRESS OF THE			
	Total number of hydrants	. NA	NA	NA
	Hose Box	NA	NA	NA
13	Pumping Arrangements.			-
	Ground Level			
TO THE MAD A POPP I TAKEN	Discharge of main Pump	N/A	N/A	N/A
	Head of Main pumpNumber of main pumps	N/A	N/A	N/A
	Number of main pumpsJockey Pump out put	N/A	N/A	N/A
	Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
***************************************	Auto Starting/ Manual	N/A	N/A	N/A
	stopping Pump House Access	N/A	N/A	N/A
a	Terrace level			
W. Peres / M. S. completed for the	Discharge of pump	450 lpm	450 lpm	MR
Annual Section (Section)	Head of the pump	40m	40m	MR
	Power Supply Auto Starting of pure	Required	Provided	MR
	Auto Starting of pump	Required	Provided	MR

12-73

	Captive Water Storage for fire fighting			
	onderground tank capacity	NA	NA	NA
	Draw-off connection	NA	NA	NA
	Fire service inlet	NA	NA	ŇA
The second secon	Access to tank	NA	NA	NA
	Overhead Tank capacity	10,000 ltr	10,000 ltr	MR
5	Exit Signage.	Required	Provided	MR
5	Provision of Lifts.			IVIK
The second secon	 Pressurization of Lift Shaft 	N/A	N/A	NT/A
	 Pressurization of Lift lobby 	N/A	N/A	N/A N/A
	• Communication In lift Car	N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
	Standby power supply	N/A	N/A	
I	Refuge Area.		11/21	N/A
	> Total Area	N/A	N/A	
	> Location	N/A	N/A	N/A
F	ire Control Room		IN/A	N/A
	Detector System Panel	77/4		
	• Flow Switch Panel	N/A	N/A	N/A
		N/A	N/A	N/A
The second secon	PA System Panel	N/A	N/A	N/A
	Batter backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
Sp Pr	pecial Fire Protection Systems for otection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010/ issue shortcoming as noted at serial no....nil...

Signature of the Inspecting Officer

Name Ajay Kumar Sharma

Designation ADO(Rohini)

DO (NW)

What about the Compliance of

C-32

6 ols