

GOVERNMENT OF NATION CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001

No F.6/DFS/MS/School/2020/SZ/ 400

Dated: 06/10/2020

FIRE SAFETY CERTIFICATE

Certified that the Sarvodaya Kanya Vidyalaya located at Delhi Cantt., 110010 building is comprised of ground plus three upper floors was inspected by officer concerned of this department on 24/09/2020 in the presence of Mrs. Ruchi Tondon (HOS) of the school and found that said school building have complied with the fire prevention and fire safety arrangements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class "Educational Building, Group-B" as above with effect from 06/10/2020 for a period of Three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the condition under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 06/10/2020 at New Delhi by


(Atul Garg)
Director
Delhi Fire Service

Copy to: -

1. The Principal, Sarvodaya Kanya Vidyalaya, Delhi Cantt-110010.
2. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi.

Conditions for the validity of Fire Safety Certificate

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
3. All the staff members must know the correct method of operation of firefighting system.
4. This Certificate cannot be treated as regularization of unauthorized construction, if any.
5. The Owner/Occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules, 2010. The form is available on www.dfs.delhigovt.nic.in.
6. The Owner/Occupier shall apply for renewal of this Fire Safety Certificate to the Director in the form 'J' [sub rule (1) of rule 37] along with copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in.

P 116

INSPECTION REPORT

1	Name & Address of the Building	Sarvodaya Kanya Vidyalaya Delhi Cantt.,110010		
2	Type of Occupancy	Educational, Group-B (School)		
3	Building Comprised of	Ground Plus Three Upper Floors		
4	Type of Case	New		
5	Details of Previous NOC	Nil		
6	Fire Safety Directives Letter No	Nil		
7	Date of Inspection	24/09/2019		
8	Name of the Inspecting Officers	D.B. Mukherjee, DO (SD)		
9	Name & Designation of Officers from the building side	Mrs. Ruchi Tondon (HOS)		
10	Year of construction	2019-2020		
11	Applicant letter No.	54(SPSSchool)/PWD Edu. Sub-Divn M1-1(N)2020-21/30 Dated 01/08/2020		
S. No	Minimum standards on Fire Prevention and Fire Safety U/R 33	UBBL-16 Requirements	Provided at Site	Remarks MR/NMR
1	Access to Building.			
	<ul style="list-style-type: none"> • Road width • Gate width • Width of internal road 	6m -NA- -NA-	Provided -NA- -NA-	MR -NA- -NA-
2	Number, width, type & arrangement of exits.			
	a) Number of Staircase			
	➤ Upper floors.	02 Nos	02 Nos	MR
	➤ Basement floor.	-NA-	-NA-	-NA-
	b) Width of Staircase			
	➤ Upper floors	1.50m	1.75m & 1.77m	MR
	➤ Basement floor	-NA-	-NA-	-NA-
	c) Protection of exits			
	➤ Fire check door	-NA-	-NA-	-NA-
	➤ Basement	-NA-	-NA-	-NA-
	d) No. of continuous staircase to terrace	01no	Provided	MR
	e) Width of corridor	1.5m	1.5m	MR
	f) Door size	Required	1.20m	MR
3	Compartmentation.			
	<ul style="list-style-type: none"> • Fire check door. • Sealing of electrical shafts. • Fire rating of shaft door. • Water curtain • Fire dampers. 	-NA- -NA- -NA- -NA- -NA-	-NA- -NA- -NA- -NA- -NA-	-NA- -NA- -NA- -NA- -NA-
4.	Smoke Management system.			
	<ul style="list-style-type: none"> • Basement • Upper floors 	30 ACPH 12 ACPH	-NA- -NA-	-NA- -NA-
5.	Fire Extinguishers.			
	<ul style="list-style-type: none"> • Total numbers • Types • ISI Marking 	12Nos ABC/CO2 ISI mark	12Nos Provided Provided	MR MR MR

16. Provision of Lifts.			
• Pressurization of lift shaft.	-NA-	-NA-	-NA-
• Pressurization of lift lobby.	-NA-	-NA-	-NA-
• Communication in lift car.	-NA-	-NA-	-NA-
• Fireman's switch.	-NA-	-NA-	-NA-
• Lift signage.	-NA-	-NA-	-NA-
17. Standby Power Supply	-NA-	-NA-	-NA-
18. Refuge Area			
• Total area	-NA-	-NA-	-NA-
• Location	-NA-	-NA-	-NA-
19. Fire Control Room.			
• Detector system panel.	-NA-	-NA-	-NA-
• Flow switch panel.	-NA-	-NA-	-NA-
• PA system panel.	-NA-	-NA-	-NA-
• Battery backup.	-NA-	-NA-	-NA-
• Building floor plan.	-NA-	-NA-	-NA-
20. Special Fire Protection System for the Protection of special Risk, if any.			-NA-

The Fire protection systems provided in the premises were checked / operated at random and found nonfunctional at the time of inspection.

The school management submitted undertaking for school construction proof at C-35.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety as required under the rules, it is recommended to grant fire safety certificate under Rule 35 of the Delhi Fire Service Rules 2010.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: D.B. Mukherjee

Designation: DO (SD)

25/09/2020
 Name: D.B. Mukherjee
 Designation: DO (SD)

Dy. CEO (S)

25/09

CF

3/9/20

1/10/20

FTP

DU SD / FAN

F.T. letter is put up for signature pl.



25/09/2020