GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6 / DFS / MS / 2020 / W2 / EH / 144 FIRE SAFETY CERTIFICATE

Dated: /5/ /o /2020

Certified that the M/s Food Sixteen located at U.G.F(upper ground floor) at A-16, Adarsh Nagar, Delhi-110033 in the building comprised of basement, stilt, upper ground and 03 upper floors owned/ occupied by Rinyra Hospitality have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officer concerned of Fire Service on 06.10.2020 in the presence of Sh. Anuj Ahuja, Owner and that the building/ premise is fit for occupancy Class Assembly restarant at upper ground floor only with effect from 15 10 2020 for a period of 03 (Three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Ph-011-23414000

Dur.

Copy to:-

1. M/s Food Sixteen, A-16, U.G.F, Adarsh, Nagar, Delhi-110033.

- 2. The Dy. Health Officer, NDMC, Public Health Department City S.P.Zone, Old Hindu College, Kashmere Gate, Delhi.
- 3. Addl. CP/Lic. Defence Colony, Delhi(The information provided to this department vide your letter dated 23.07.19(overleaf)

Conditions for the validity of Fire Safety Certificate:

- 1 All the means of escape/entry/exit shall be kept free from any obstruction.
- 2 All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3 All the staff members must know the correct method of operation of firefighting system.
- 4 The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.
- 5 This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6 "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in **Form 'J'** [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT

1. Name & address of the building

:M/s Food Sixteen (A unit of Rinyra Hospitaliity), A-16, Upper Ground

Floor, Adrash Nagar, Delhi-110033.

2. Type of Occupancy

: Restaurant (Assembly) (Restaurant- U.G.F only)B+stilt+UG & 03 upper

Floor only)

3. Type of Case

: New case

4. Details of previous NOC

: Nil

5. Fire Safety directives letter No

: UBBL-2016/ NBC Part -IV

6. Date of inspection

: 06/10/2020

7. Name of the Inspecting Officers

: Rajesh Kumar ADO (RN)

8. Name and designation of officers

from the building side

: Sh Anuj Ahuja, Owner

9. Year of Construction

: 2015-16

10. Applicant's letter No.

: Email I D No. 2020090206583 Dated: 03.09.2020

	Minimum Standards on fire prevention and fire safety U/R 33	UBBL/NBC Requirement	Provided at site	Remarks MR/NMR	
	Access to building			8	
	Road width	6m	06m	MR	
	• Gate width	NA	Directly Accessible	NA	
	Width of internal road	NA	NA	NA	
2	Number, Width, Type & Arrangement of Exits				
	a. Number of staircases				
	• Upper Floors	02	03	MR	
	Basements	NA	NA	NA	
	b. Width of staircases				
	• Upper Floors	2.00m & 1.5m	2.00m, 1.50m &1.50m iron s/c	MR	
	Basements	NA	NA	NA	
	c. Protection of exits				
	Fire check door	Required	Provided	MR	
	Pressurization	NA	NA	NA	
	d. No. of continuous staircases to terrace	NA	NA	NA	
	e. Width of Corridor	· NA	NA	NA	
				MR	

WIN

Y	ard Hydrants.	V I	01	MR
	Hose Box	01		MR
	Number of hydrants per floor Hose Poy	01	01	MR
	Size of riser/down-comer	Required	Provided	MD
4.1				*
1.	nternal Hydrants	NA	NA	NA
	Sprinkler above false ceiling	NA	Provided	NA
	Upper Floor (upper ground floor)	NA	NA	NA
	Basement	NIA		Pi
1	Automatic Sprinkler System.	IVA	NA	NA
	Public Address System.	Required NA	Provided	MR
	MOEFA	Dan's I		NA.
	 Hooters' Location 	NA	UGF	NA
	 Alternate source of power 	NA	Provided	NA
	 Location of Repeater Panel 	NA	UGF	
	 Location of Main Panel 	NA	UGF	NA NA
	• Type of detectors	NA	Provided	NA
	Automatic fire detection and alarming system	1.	211111	MR
		5mm	5mm	X
	Nozzle diameter	, 30m	30m	MR
	Length of hose reel hose	01	Provided	MR
	Total numbers on each floor	0.1		
	First-Aid Hose Reels.	Yes	Yes	MR
	ISI marking		ABC- 08	MR
	• Types	ABC & Co2	08 nos	MR
	Total numbers	06nos	0.0	
5	Fire Extinguishers			MR
	• Upper floors	12 a/c per hour	Natural Ventilated	
	• Basements	30 a/c per hour	NA(other property)	. NA
4	Smoke Management System.		INA	NA
4		NA	NA	
	Fire Dampers	NA	NA	NA
	Water Curtain	NA	NA	NA
	Fire Rating of shaft door	NA	NA	NA
	Sealing of electrical shafts	Required	Provided	MF
	Fire check door	n .		

Y



	Total number of hydrants	NA	NA	NA	
	Hose Box	NA	NA ·	NA	
		INA	IN/A	INA	
3	Pumping Arrangements.				
	Ground Level				
	Discharge of main Pump	N/A	N/A	N/A	
	Head of Main pump	N/A	N/A	N/A	
	Number of main pumps	NA	NA	NA	
	Jockey Pump out put	NA	NA	NA	
	Jockey pump head	N/A	N/A	N/A	
	Standby Pump out put	N/A	N/A	N/A	
	Standby Pump Head	N/A	N/A	N/A	
	Auto Starting/ Manual stoppingPump House Access	N/A	N/A	N/A	
	Terrace level				
	Discharge of pump	450 lpm	900 lpm	MR	
	Head of the pump	40m	40m	MR	
	Power Supply	NA	NA	NA	
	Auto Starting of pump	Required	Provided	MR	
14	Captive Water Storage for fire fighting. Underground tank capacity	NA	. NA	NA	
	Draw-off connection	NA	NA	NA	
	Fire service inlet	Required	Provided	MR	
	Access to tank	Required	Provided	MR	
	Overhead Tank capacity				
		20,000 ltr.	25,000 ltr.	MR	
15	Exit Signage.	Required	Provided	MR	
16	Provision of Lifts.				
	Pressurization of Lift Shaft	N/A	N/A	N/A	
	Pressurization of Lift lobby	N/A	N/A	N/A	
	Communication In lift Car	NA	NA NA	NA NA	
	Fireman's Grounding Switch	NA	1.37:1		
	Lift Signage	NA	NA	NA	
17	Standby power supply	Required	Provided	MR	
18	Refuge Area.				
	Total Area	N/A	N/A	N/A	



N/n

Fire Control Room	Fire Control Room			
Detector System Panel	N/A	N/A	N/A	
Flow Switch Panel	N/A	N/A	N/A	
PA System Panel	N/A	N/A	N/A	
Batter backup	N/A	N.A	N/A	
Building Floor Plans			N/A	
Building	NA	NA	NA	
O Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA .	14,71	

The fire protection systems provided in the building were tested/ checked and found some in working order at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer
Name: - Rajesh Kumar
Designation: - ADO/RN