GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110 001

No.F.6/DFS/MS/School/2020/NDZ/ 438

Dated: 20 10 2020

FIRE SAFETY CERTIFICATE

Certified that the Govt. Girls. Sr. Sechool No. 3 at Bholanath Nagar, Shahdara, Delhi - 110032, comprised of Ground plus one and Ground plus three upper floors owned / occupied by Govt. Girls. Sr. Sechool No. 3 was issued FSC vide letter No. F6/DFS/MS/School/2013/721 Dated: 19/08/2013. The school building was have complied with the fire safety requirements in accordance with the NBC Part-IV and verified by the officers concerned of this department on 28/09/2020 in the presence of Mr. R. Ravi Shankar, Principal of the school and found that the school building is fit for occupancy class "B" 'Educational Building' for ground plus three upper floors with effect from 20.10. 20.20 for a period three year, in accordance and further subject with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010 also conditions printed overleaf.

Issued on 20/10/2020 at New Delhi by

(Sunil Chawdhary)
Dy.Chief Fire Officer

To,

The Principal Govt. Girls Sr. Sec. School No.-3, Bholanath Nagar, Shahdara, Delhi-110032.

Copy to:-

The Joint Director of Education B-Bloc, Yamuna Vihar, Delhi - 110053.

- Conditions -

- 1 All the means of escape shall be kept free of all type of obstruction all the time.
- 2 All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in good working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- 5. This Fire Safety certificate can not be treated in any case for regularizations of unauthorized construction if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. "The owner /occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form'J'[sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry"

Nath Nagar, Shahdara, Delhi-32 : G+1, Ground plus three upper floors only 2. Building is comprised of Educational 3. Type of Occupancy : Renewal 4. Type of Case 5. Details of Previous NOC letter : F6/DFS/MS/School/2013/721 dated 19/08/2013 : NBC Part - IV 6. Fire Safety direction letter No. : 28/09/2020 7. Date of Inspection 8. Name of the Inspecting officers : ADO Nagender Singh 9. Name and designation of Officer : Ms. R. Ravishankar from the building side : 1968 & 2011 10. Year of Construction : vikas.arya91@gmail.com Dt- 10/09/2020 11. Applicant's Mail ID Provided at Site Remarks **NBC** Minimum Standards on Fire Sr. MR/NMR Prevention and Fire Safety U/R33 Requirement No. Access to Building 01 MR 10m 06m Road width N/A N/A N/A Gate width N/A N/A N/A Width of internal road Number, Width, Type and Arrangement of Exits 02 a. Number of Staircases MR Upper floor(G+3) 01 no. 01 nos. Accepted 02nos. 02nos. Upper floor(G+1) Earlier N/A N/A N/A Basement B. Width of Staircases MR 2m 2m Upper floor(G+3) 1.50m.each MR 1.50m Upper floor(G+1) N/A N/A N/A Basement c. Protection of Exits N/A N/A N/A Fire check door N/A N/A N/A Pressurization d. No. of Continuous Staircases 01 no. 01 no. MR to Terrace 2.20m & 1.5m 2.20m & MR e. Width of Corridor 1.50m 01m MR 01m f. Door Size Compartmentation. 03 N/A N/A N/A Fire check door N/A N/A N/A Sealing of electrical shafts N/A N/A N/A Fire rating of shaft door N/A N/A N/A Water curtain N/A N/A N/A Fire dampers Smoke Management System. 04 N/A N/A N/A Basement N/A N/A N/A Upper floor 05. Fire Extinguishers 12 nos. 20 nos. MR Total numbers ABC/CO₂ ABC/CO2 MR Types ISI marked ISI marked MR IS marking

INSPECTION REPORT

1. Name & address of the building

: Govt. Girls Sr. Sec. School No.3, Bhola

06	First-Aid-Hose Reels.						
	Total numbers on each floor	01 no.	01 no.	MR			
	 Length of hose reel hose 	30 m	30 m	MR			
	Nozzle diameter	05 mm	05 mm	MR			
07	Automatic Fire Detection and Alarming System.						
	Type of detectors	N/A	N/A	N/A			
	 Location of main panel 	N/A	N/A	N/A			
	Location of repeater panel	N/A	N/A	N/A			
	Alternate source of power	N/A	N/A	N/A			
	Hooter	N/A	N/A	N/A			
08	MOEFA	N/A	N/A	N/A			
09	Public Address System.	N/A	Provided	MR			
10	Automatic Sprinkler System.						
	P	N/A	N/A	N/A			
	Basementupper floor	N/A	N/A	N/A			
	upper froofsprinkler above false ceiling	N/A	N/A	N/A			
11	Internal Hydrants			3			
	size of riser/down-comer	N/A	N/A	N/A			
	 Number of hydrants per floor 	N/A	N/A	N/A			
	Hose box	N/A	N/A	N/A			
12	Yard Hydrants.		100000000000000000000000000000000000000				
	* · · · · · · · · · · · · · · · · · · ·	N/A	N/A	N/A			
	Total number of hydrantsHose box	N/A	N/A	N/A			
13	Pumping Arrangements.						
+	➤ Ground Level						
-	Discharge of main pump	N/A	N/A	N/A			
	Head of main pump	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	Jockey pump out put	N/A	N/A	N/A			
	Jockey pump head	N/A	N/A	N/A			
	Standby pump out put	N/A	N/A	N/A			
	Standby pump head	N/A	N/A	N/A			
	 Auto starting /manual stopping 	N/A	N/A	N/A			
	 Pump house access 	N/A	N/A	N/A			
	> Terrace Level		8				
-	Discharge of pump	450 lpm	2x450 lpm	MR			
	Head of the pump	40 M	40 M	MR			
	Power supply	Required	Provided	MR			
	Auto starting of pump	Required	Provided	MR			
14	Captive Water Storage for Fire Fighting.			1			
	Underground tank capacity	N/A	N/A	N/A			
	• Draw-off connection	N/A	N/A	N/A			
	• Fire service inlet	N/A	N/A	N/A			
	Access to tank	N/A	N/A	N/A			
	Overhead tank capacity	10,000 ltr	10,000 ltr	MR			
15	Exit Signage.	Required	Provided	MR			
		1	100 VIII S 100 100 100 100 100 100 100 100 100 1				

16	Provision of Lifts.					
many many (many) and the plants	Pressurization of lift shaft	N/A	N/A	N/A		
	 Pressurization of lift lobby 	N/A	N/A	N/A		
	 Communication in lift car 	N/A	N/A	N/A		
	 Firemen's grounding switch 	N/A	N/A	N/A		
	Lift signage	N/A	N/A	N/A		
17	Standby Power Supply	N/A	N/A	N/A		
18	Refuge Area.					
	Total area	N/A	N/A	N/A		
	• Location	N/A	N/A	N/A		
19	Fire Control Room					
	Detector system panel	N/A	N/A	N/A		
	Flow switch panel	N/A	N/A	N/A		
	PA system panel	N/A	N/A	N/A		
	Battery backup	N/A	N/A	N/A		
	Building floor plans	N/A	N/A	N/A		
20	Special Fire Protection Systems for Protection of Special Risks, if Any:	N/A	N/A	N/A		

Keeping in view of the compliance of the minimum standards of fire prevention and fire safety measures required as per NBC Part IV, it is recommended to issue Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

(Nagender Singh)

Assistant Divisional Officer

DO(ED)

DY. CROINNY

(Shahdara)

DOF

F.t. lelli is Prepos and put up for Bungling

Pleer.

DY, UNINUZ,