

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001


No. F.6/DFS/MS/EH/2020/SZ/ 157

Dated: 05 / 11 / 2020

FIRE SAFETY CERTIFICATE

Certified that M/s **Nando's** (A unit of Nando's Karnataka Restaurants Pvt. Ltd) situated at Outlet J West Wing, Upper Ground Floor, TDI South Bridge, Nehru Place Metro Station, Nehru Place, New Delhi-110019, building comprised of basement, upper ground floor + lower ground floor but the restaurant running at upper ground floor was issued FSC by this department in the name of M/s **Nando's** (A unit of Janpath Restaurants Pvt. Ltd) vide letter No. F.6/DFS/MS/EH/2017/SZ/1421 dated 27/09/2017. The premise was re-inspected by the officer concerned of this department on 28/09/2020 in the presence of Mr. Hemanand (Team Leader) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "**Assembly Group-D**" (Eating House) effect from 05 / 11 / 2020 for a period of **three years** in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010 as below.

Issued on 05/11/2020 at New Delhi by


(Sunil Chawdhary)
Dy. Chief Fire Officer
Delhi Fire Service
ok Az

Copy to: -

1. The Joint C.P. (Licensing), First Floor, Police Station Defence Colony, New Delhi-110049
2. The Dy. Health Officer, South MCD, Public Health Department, Central Zone, Lajpat Nagar, New Delhi-110024
3. The Director, M/s Nando's Karnataka Restaurants Pvt. Ltd at Outlet J West Wing, UGF, TDI South Bridge, Nehru Place Metro Station, Nehru Place, New Delhi-110019

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
3. The basement shall be used strictly in accordance with BBL.
4. All the staff members must know the correct method of operation of fire fighting system.
5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

INSPECTION REPORT

1	Name & Address of the Building	M/s Nando's (A unit of Nando's Karnataka Restaurants Pvt. Ltd), Outlet J West Wing, Upper Ground Floor, TDI South Bridge, Nehru Place Metro Station, New Delhi.		
2	Type of Occupancy	Assembly "Group-D" (Restaurant at UGF)		
3	Building Comprised of	Basement, Lower Ground + Upper Ground Floor		
4	Type of Case	Renewal		
5	Details of Previous NOC	F.6/DFS/MS/EH/2017/SZ/1421 Dated 27/09/2017 in F/o M/s Nando's (A unit of Janpath Restaurants Pvt. Ltd.)		
6	Fire Safety Directives Letter No	Nil		
7	Date of Inspection	28/09/2020		
8	Name of the Inspecting Officers	ADO Avtar Singh & ADO Bhupender Prakash		
9	Name & Designation of Officers from the building side	Mr. Hemanand (Team Leader)		
10	Year of construction	2009	Restaurant is at UGF of Mall building.	
11	Applicant letter No.	Outdoor Diary No. 6153 Dated 01/07/2020		
S. No	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC Requirements	Provided at Site	Remarks MR/NMR
1	Access to Building.	Provided & Maintained By TDI Mall		
	<ul style="list-style-type: none"> Road width Gate width Width of internal road 	Restaurant within TDI Mall	As above As above N/A	MR N/A N/A
2	Number, width, type and arrangements of exits.	Provided & Maintained By TDI Mall		
	a. Number of Staircase	Provided & Maintained By TDI Mall		
	<ul style="list-style-type: none"> Upper floors Basement floor 	Restt. within Mall N/A	As above N/A	MR N/A
	b. Width of Staircase	Provided & Maintained By TDI Mall		
	<ul style="list-style-type: none"> Upper floors Basement floor 	Restt. within Mall N/A	As above N/A	MR N/A
	c. Protection of exits	Provided & Maintained By TDI Mall		
	<ul style="list-style-type: none"> Fire check door Pressurization 	N/A N/A	As above As above	N/A N/A
	d. No. of continuous staircase to terrace	Required	As above	MR
	e. Width of corridor	N/A	N/A	N/A
	f. Door size	2.0 m	2.3m, 2m & 2m	MR
3	Compartmentation.	Provided & Maintained By TDI Mall		
	<ul style="list-style-type: none"> Fire check door. Sealing of electrical shafts. Fire rating of shaft door. Water curtain Fire dampers. 	N/A N/A N/A N/A N/A	As above As above N/A N/A N/A	N/A N/A N/A N/A N/A
4.	Smoke Management system.	Provided & Maintained By TDI Mall		
	<ul style="list-style-type: none"> Basement Upper floors 	30 ACPH 12 ACPH	N/A Provided	N/A MR
5.	Fire Extinguishers.	Provided & Maintained By TDI Mall		
	<ul style="list-style-type: none"> Total numbers Types ISI Marking 	Portable Fire Extinguisher ISI marked	10 Nos. ABC & Co2 Provided	MR MR MR

Renewal: M/s **Nando's** (A unit of Nando's Karnataka Restaurants Pvt. Ltd), Outlet J West Wing, Upper Ground Floor, TDI South Bridge, Nehru Place Metro Station, New Delhi.

6.	First Aid Hose Reels.	Provided & Maintained By TDI Mall		
	• Total numbers on each floor.	One (Near Restt)	As above	MR
	• Length of hose-reel hose.	30 m	As above	MR
	• Nozzle Diameter	05 mm	As above	MR
7	Automatic Fire Detection and Alarming system.	Provided & Maintained By TDI Mall		
	• Type of detectors	Required	As above	MR
	• Location of Main Panel	Required	As above	MR
	• Location of Repeater Panel	N/A	N/A	N/A
	• Alternate source of power	Required	As above	MR
	• Hooter's location	Required	As above	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	N/A	N/A	N/A
10.	Automatic Sprinkler System	Provided & Maintained By TDI Mall		
	• Basement	N/A	As above	MR
	• Upper floors	Required	Provided	MR
	• Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants.	Provided & Maintained By TDI Mall		
	• Size of Riser/Down-comer	Required	As above	MR
	• Number of Hydrant per floor	Required	As above	MR
	• Hose box.	Required	As above	MR
12.	Yard Hydrants.	Provided & Maintained By TDI Mall		
	• Total number of hydrants.	N/A	As above	N/A
	• 2. Hose box.	N/A	As above	N/A
13.	Pumping arrangements.	Provided & Maintained By TDI Mall		
	• Ground Level	Provided & Maintained By TDI Mall		
	➤ Discharge of main pump.	N/A	As above	N/A
	➤ Head of main pump.	N/A	As above	N/A
	➤ Number of main pumps.	N/A	As above	N/A
	➤ Jockey Pump output.	N/A	As above	N/A
	➤ Jockey Pump head.	N/A	As above	N/A
	➤ Standby Pump output.	N/A	As above	N/A
	➤ Standby Pump head.	N/A	As above	N/A
	➤ Auto Starting / Manual Stopping.	N/A	As above	N/A
	➤ Access to pump house	N/A	As above	N/A
	• Terrace Level	Provided & Maintained By TDI Mall		
	➤ Discharge of pump.	450 LPM	As above	MR
	➤ Head of pump.	40 m	As above	MR
	➤ Power supply.	Required	As above	MR
	➤ Auto starting of pump.	Required	As above	MR
14.	Captive water storage for Fire Fighting.	Provided & Maintained By TDI Mall		
	• Underground tank capacity.	N/A	As above	N/A
	➤ Draw-off connection.	N/A	As above	N/A
	➤ Fire Service Inlet.	N/A	As above	N/A
	➤ Access to tank.	N/A	As above	N/A
	• Overhead tank capacity.	20,000 Ltrs	As above	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.	Provided & Maintained By TDI Mall		
	• Pressurization of lift shaft.	N/A	N/A	N/A
	• Pressurization of lift lobby.	N/A	N/A	N/A
	• Communication in lift car.	N/A	N/A	N/A
	• Fireman's switch.	N/A	N/A	N/A
	• Lift signage.	N/A	N/A	N/A

17.	Standby Power Supply	Required	Provided	MR
18.	Refuge Area			
	• Total area	N/A	N/A	N/A
	• Location	N/A	N/A	N/A
19.	Fire Control Room.			
	• Detector System Panel.	Required	Provided	MR
	• Flow Switch Panel.	N/A	N/A	N/A
	• PA system Panel.	Required	Provided	MR
	• Battery backup	N/A	N/A	N/A
	• Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for the Protection of special Risk, if any :	N/A	N/A	N/A

The Fire protection systems provided in the building/premises were test checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F.6/DFS/MS/EH/2017/SZ/1421 Dated 27/09/2017 in the name of M/s Nando's (A unit of Janpath Restaurants Pvt. Ltd.), renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended in the name of M/s Nando's (A unit of Nando's Karnataka Restaurants Pvt. Ltd).

Accordingly, DFA is put up for approval and signature please.

Avtar Singh
05/10/2020

BP Prakash
05/10/2020

Signature of the Inspecting Officer
Name : Avtar Singh
Designation: ADO (M. Road)

Signature of the Inspecting Officer
Name : Bhupender Prakash.
Designation: ADO

DO (SZ)

King
05/10

DCFO (SZ)

Not posted *King*
27/10

CFP

*Info is printed
Recd to dg 2/11*



DO (SZ)

MD
2/11

Submitted please.

K. F. Prakash *King*
03/11

DCFO (SZ)

DO
3/11

King