

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6 / DFS / MS / 2020 / W2 / School / 528

Dated: 02 / 12 / 2020

FIRE SAFETY CERTIFICATE

Certified that the **Govt. Girls Sec. School** located at **Burari, Delhi-110084** comprised of **04 blocks- I & II block- ground + 01 upper floors (old building) & 02 new blocks- ground & 03 upper floors** owned/ occupied by **Govt. Girls Sec. School** was issued Fire Safety Certificated vide this office letter no. **F-6/DFS/MS/2017/917** dated **23.06.2017** the premise was re-inspected by the officer concerned of this department on **16.11.2020** in the presence of **Smt. Seema Kumari, Vice- Principal** and observed that all the fire prevention and fire safety arrangements as provided in the premise found in good working condition. The premise have therefore deemed complied with the requirements under rule 33 of the Delhi Fire Service Rules, 2010 and the building premise is fit for occupancy under **Educational "Group B"** with effect from 02/12/2020 for a period of **three years** in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40, subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010,

Issued on 02/12/2020 at New Delhi by

(Dharampal Bhardwaj)
Dy.Chief Fire Officer
Ph:-011-25156707

Copy to :-

1. The Director, Education, Government of N.C.T of Delhi. Old Sectt. Delhi - 110054.
2. The Principal, Govt. Girls Sec. School , Burari , Delhi-110084.

Conditions for the validity of Fire Safety Certificate:

- 1 All the means of escape/entry/exit shall be kept free from any obstruction.
- 2 All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3 All the staff members must know the correct method of operation of firefighting system.
- 4 The owner / occupier shall submit a declaration **every year** in **Form "K"** provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <http://delhi.gov.in./wps/wcm/connect/doi/fire/FIRE/Home/Forms>.
- 5 This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6 "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in **Form 'J'** [sub rule (1) of rule 37] along with a copy of this Certificate, **six months** prior to its expiry".

2/24

INSPECTION REPORT

- 1. Name & address of the building : Govt. Girls Sec. School , Burari , Delhi-110084.
- 2. Type of Occupancy : Educational
- 3. Type of Case : Renewal Case (04 blocks- 02 block- G+01 floors (Old building) & 02 block- G + 03 upper floors(New building))
- 4. Details of previous NOC : F6/DFS/MS/2017/917 Dated: 23.06.2017
- 5. Fire Safety directives letter No : NBC Part-4
- 6. Date of inspection : 16.11.2020
- 7. Name of the Inspecting Officers : ADO (RN)
- 8. Name and designation of officers from the building side : Smt. Seema Kumari, Vice- Principal
- 9. Year of Construction : --
- 10. Applicant's letter No. : Online E-Mail I.D dated: 29.10.2020

	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR
1	Access to building			
	• Road width	Accessible	Accessible	MR
	• Gate width	Accessible	Accessible	MR
	• Width of internal road	NA	NA	NA
2	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases	Block-I-02 Block-II-01 Block-III & IV- 02	Block-I-03 Block-II-01 Block-III & IV- 02 each	MR
	• Upper Floors			
	• Basements	NA	NA	NA
	b. Width of staircases			
	• Upper Floors	1.50m	Block-I-(G+1)- 1.50m x 02 Block-II (G+1)-1.50m x 01 Block-III & IV(G+3)-1.80m x02 each blocks	MR
	• Basements	NA	NA	NA
	c. Protection of exits			
	• Fire check door	NA	NA	NA
	• Pressurization	NA	NA	NA

[Handwritten signature]

	d. No. of continuous staircases to terrace	01	Provided	MR
	e. Width of Corridor			
	f. Door Size	Required	Provided	MR
		1 m	1.10m	MR
3	Compartmentation.			
	• Fire check door	NA	NA	NA
	• Sealing of electrical shafts	NA	NA	NA
	• Fire Rating of shaft door	NA	NA	NA
	• Water Curtain	NA	NA	NA
	• Fire Dampers	NA	NA	NA
4	Smoke Management System.			
	• Basements	30 a/c per hour	NA	NA
	• Upper floors	12 a/c per hour	Natural Ventilated	MR
5	Fire Extinguishers			
	• Total numbers	50nos	80nos	MR
	• Types	ABC/Co2	ABC-40 Co2-40	MR
	• ISI marking	ISI Marked	Provided	MR
6	First-Aid Hose Reels.((New Block-III & IV))			
	• Total numbers on each floor	03	04,Provided	MR
	• Length of hose reel hose	30m	30m	MR
	• Nozzle diameter	5mm	5mm	MR
7	Automatic fire detection and alarming system.			
	• Type of detectors	NA	NA	NA
	• Location of Main Panel	NA	NA	NA
	• Location of Repeater Panel	NA	NA	NA
	• Alternate source of power	NA	NA	NA
	• Hooters' Location	NA	NA	NA
8	MOEFA			
		NA	NA	NA
9	Public Address System.			
10	Automatic Sprinkler System.			
	• Basement	NA	NA	NA
	• Upper Floor	NA	NA	NA
	• Sprinkler above false ceiling	NA	NA	NA

11	Internal Hydrants			NA	Provided	NA	
	<ul style="list-style-type: none"> • Size of riser/down-comer • Number of hydrants per floor • Hose Box 	NA	Provided	NA			
		NA	01	NA			
		NA					
12	Yard Hydrants.			NA	NA	NA	
	<ul style="list-style-type: none"> • Total number of hydrants • Hose Box 	NA	NA	NA			
		NA	NA	NA			
13	Pumping Arrangements.(for New Block-III & IV)						
	<ul style="list-style-type: none"> • Ground Level <ul style="list-style-type: none"> ➤ Discharge of main Pump ➤ Head of Main pump ➤ Number of main pumps ➤ Jockey Pump out put ➤ Jockey pump head ➤ Standby Pump out put ➤ Standby Pump Head ➤ Auto Starting/ Manual stopping ➤ Pump House Access • Terrace level <ul style="list-style-type: none"> ➤ Discharge of pump ➤ Head of the pump ➤ Power Supply ➤ Auto Starting of pump 	N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
		NA	NA	NA			
		NA	NA	NA			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
		450lpm	450lpm x 02 each block	MR			
		40m	40m	MR			
		Required	Provided	MR			
		Required	Provided	MR			
		14	Captive Water Storage for fire fighting.(New Block-III & IV)				
			<ul style="list-style-type: none"> • Underground tank capacity ➤ Draw-off connection ➤ Fire service inlet ➤ Access to tank • Overhead Tank capacity 	NA	NA	NA	
				NA	NA	NA	
NA	NA			NA			
NA	NA			NA			
10,000 ltr	10,000 ltr. each block			MR			
Required	Provided	MR					
15	Exit Signage.						
16	Provision of Lifts.						

	<ul style="list-style-type: none"> • Pressurization of Lift Shaft • Pressurization of Lift lobby • Communication In lift Car • Fireman's Grounding Switch • Lift Signage 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.			
	<ul style="list-style-type: none"> ➤ Total Area ➤ Location 	N/A	N/A	N/A
19	Fire Control Room			
	<ul style="list-style-type: none"> • Detector System Panel • Flow Switch Panel • PA System Panel • Batter backup • Building Floor Plans 	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition, at the time of inspection. The management has complied all the shortcomings issued and communicated by this department vide letter of even no. 686 dated 16.10.2020.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in NBC Part-4, the FSC issued vide letter of even no 917 dated 23.06.2017 renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended

Signature of the Inspecting Officer
 Name :- C.L. Meena
 Designation:- ADO/RN

[Signature] 23/11/2020

DO (NW)

[Signature] 23/11/2020

By CRs (w2)

[Signature] 24/11/2020

ADO/RN

30/DO (NW)
23/11/2020

As approved, F.T. letter is put up for your signature pl.

[Signature] 26/11/2020