

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F 6/DFS/MS/2020/EH/WZ / 176

Dated 7/12/2020

FIRE SAFETY CERTIFICATE

Certified that the M/s Burger King located at ground floor, Unit No-01, D-Block, Metro Walk, Sec-10, Rohini, Delhi-110085 in the building comprised of Ground floor only owned/occupied by M/s Burger King Pvt. Ltd was granted NOC by this department vide letter no. F.6/DFS/MS/2017/EH/WZ/1279 dated 25.08.2017. The premises was re-inspected by the officers concerned of this department on **23.11.2020** in the presence of **Mr Suraj (Store Manager)** and found that the building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules,2010. Hence the NOC is renewed and premises is fit for occupancy **Class (Assembly)** for ground floor only with effect from 7/12/2020 for a period of **03 (Three) years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ...7/12/2020..... at New Delhi by


(Atul Garg)
Director
Tel:-01123414000


Copy to:-

1. The Dy. Health Officer, North MCD, Civil Line Zone, Sec-5, Rohini, Delhi-110054.
2. Mr Suraj (Store Manager), M/s Burger King located at ground floor, Unit No-01, D-Block, Metro Walk, Sec-10, Rohini, Delhi-110085.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on **WWW.dfs.Delhigovt.nic.in**
8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

17

INSPECTION REPORT

Ground floor only

1. Name & address of the building : M/s Burger King India Pvt. Ltd., Shop No. 21-24, Sec-10, D-Mall, Rohini, Delhi-110085.
2. Type of Occupancy : Assembly
3. Type of Case : Renewal
4. Details of previous NOC : F.6/DFS/MS/2017/EH/WZ/1279 dated 25.08.2017
5. Fire Safety directives letter No : NBC Part-4
6. Date of inspection : 23.11.2020
7. Name of the Inspecting Officers : A.K.Sharma ADO (Rohini)
8. Name and designation of officers from the building side : Mr. Suraj (Store Manager)
9. Year of Construction : 2017
10. Applicant's letter No. : Online application no.2020092407278 dated 29.09.2020

Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR
1. Access to building (Amusement Park of Adventure Island Metro Park issued FSC vide letter No. F6 DFS/MS/WZ/2020/427 dated 22.10.2020)			
• Road width	09m	09m	MR
• Gate width	06	06	MR
• Width of internal road	NA	NA	NA
2. Number, Width, Type & Arrangement of Exits [Provided & Maintained by Mall management]			
a. Number of staircases			
• Upper Floors	Restaurant within Mall	As Above	NA
• Basements	Restaurant within Mall	As Above	NA
b. Width of staircases			
• Upper Floors	Restaurant within Mall	As Above	NA
• Basements	Restaurant within Mall	As Above	NA
c. Protection of exits			
• Fire check door	Restaurant within Mall	As Above	NA
• Pressurization	Restaurant within Mall	As Above	NA
d. No. of continuous staircases to terrace	Restaurant within Mall	As Above	NA
e. Width of Corridor			
f. Door Size	(02 Exits)	Provided, out of which one door is in kitchen	MR (old case)
3. Compartmentation.			
• Fire check door	Restaurant within Mall	As Above	NA
• Sealing of electrical shafts	Restaurant within Mall	As Above	NA
• Fire Rating of shaft door	Restaurant within Mall	As Above	NA
• Water Curtain	Restaurant within Mall	As Above	NA
• Fire Dampers	Restaurant within Mall	As Above	NA
4. Smoke Management System. [Provided & Maintained by Mall management]			
• Basements	Restaurant within Mall	As Above	NA
• Upper floors	Restaurant within Mall	As Above	NA
5. Fire Extinguishers			

18

	<ul style="list-style-type: none"> Types IS marking 	ABC/Co2	ABC-06 /Co2-02	MR
		Yes	Yes	MR
6	First-Aid Hose Reels. [Provided & Maintained by Mall management]			
	<ul style="list-style-type: none"> Total numbers on each floor Length of hose reel hose Nozzle diameter 	01(G. Floor)	As Above	MR
		30 m	As Above	MR
		5mm	As Above	MR
7	Automatic fire detection and alarming system. [Provided & Maintained by Mall management]			
	<ul style="list-style-type: none"> Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location 	Restaurant within Mall	As Above	NA
		Restaurant within Mall	As Above	NA
		Restaurant within Mall	As Above	NA
		Restaurant within Mall	As Above	NA
		Restaurant within Mall	As Above	NA
8	MOEFA	Required	Provided	MR
9	Public Address System.	NA	As Above	NA
10	Automatic Sprinkler System [Provided & Maintained by Mall management]			
	<ul style="list-style-type: none"> Basement Upper Floor Sprinkler above false ceiling 	Restaurant within Mall	As Above	NA
		Restaurant within Mall	As Above	NA
		Restaurant within Mall	As Above	NA
11	Internal Hydrants [Provided & Maintained by Mall management]			
	<ul style="list-style-type: none"> Size of riser/down-comer Number of hydrants per floor Hose Box 	100mm	As Above	MR
		One (near to Restaurant)	As Above	MR
		One (near to Restaurant)	As Above	MR
12	Yard Hydrants. [Provided & Maintained by Mall management]			
	<ul style="list-style-type: none"> Total number of hydrants Hose Box 	NA	NA	NA
		NA	NA	NA
13	Pumping Arrangements. [Provided & Maintained by Mall management]			
	<ul style="list-style-type: none"> ➤ Ground Level ➤ Discharge of main Pump ➤ Head of Main pump ➤ Number of main pumps ➤ Jockey Pump out put ➤ Jockey pump head ➤ Standby Pump out put ➤ Standby Pump Head ➤ Auto Starting/ Manual stopping ➤ Pump House Access 	NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
	<ul style="list-style-type: none"> • Terrace level ➤ Discharge of pump ➤ Head of the pump 	[Provided & Maintained by Mall management]		
		NA	As Above	MR
		NA	As Above	MR
		Required	As Above	MR

	➤ Power Supply	Required	As Above	MR
	➤ Auto Starting of pump			
14	Captive Water Storage for fire fighting [Provided & Maintained by Mall management]			
	• Underground tank capacity	NA	As Above	NA
	➤ Draw-off connection	NA	As Above	NA
	➤ Fire service inlet	NA	As Above	NA
	➤ Access to tank	NA	As Above	NA
	• Overhead Tank capacity	NA	As Above	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts. [Provided & Maintained by Mall management]			
	• Pressurization of Lift Shaft	NA	NA	NA
	• Pressurization of Lift lobby	NA	NA	NA
	• Communication In lift Car	NA	NA	NA
	• Fireman's Grounding Switch	NA	NA	NA
	• Lift Signage	NA	NA	NA
17	Standby power supply	NA	NA	NA
18	Refuge Area. [Provided & Maintained by Mall management]			
	➤ Total Area	NA	NA	NA
	➤ Location	NA	NA	NA
19	Fire Control Room [Provided & Maintained by Mall management]			
	• Detector System Panel	NA	NA	NA
	• Flow Switch Panel	NA	NA	NA
	• PA System Panel	NA	NA	NA
	• Batter backup	NA	NA	NA
	• Building Floor Plans	NA	NA	NA
20	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA	NA

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F.6/DFS/MS/2017/EH/WZ/1279 dated 25.08.2017. Renewal under rule 37 of the Delhi Fire Service rules 2010 is recommended.

Validity of the Mall F.S.C. & Door width is not mentioned in ins. report

[Signature]
 Signature of the Inspecting Officer
 Name: Ajay Kumar Sharma
 Designation: ADO (Rohini)

DO(NW)

[Signature]
 26/11/2020
 ADO (Rohini)

- For FSC of main occupancy, column no. of inspection proforma may kindly be perused.

- For width of door it is already mentioned in inspection notes.

Do (Cover)