GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE : NEW DLEHI - 110 001

No. F.6/DFS/MS/Motel/SZ/2020/ 541

Dated: 23/12/200

FIRE SAFETY CERTIFICATE

Certified that the Motel Building Block No. 2, Celebration Garden (Under Sartaj Hotels Apartments & Villas Pvt. Ltd.) Khasra No. 369 min, 371, 372 min, 376 min,377 min and 396, NH-8, Village Rangpuri, New Delhi-37, comprised of Basement and Ground floor has already been issued FSC by this department vide letter F6/ DFS/ MS/Motel/ SZ /2017/1561 Dated 01/11/2017. The premise was re-inspected by the officer concerned of this department on 18/12/2020 in the presence of Mr. K. A Lal & found to have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building is fit for occupancy Group A "Residential Building" with effect 22 / 12 2020 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010.

Issued on 27/1/200 at New Delhi by

(Sunil Chawdhary) Dy. Chief Fire Officer (SZ) Delhi Fire Service

Copy to:-

- 1. The Joint Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi-110049
- 2. The AE (Bldg.), SDMC, Najafgarh Zone, 1st Floor, New Zonal Building, Dhansa Stand, Najafgarh, New Delhi-110043
- 3. The Authorized Signatory, Motel Building Block No. 2, Celebration Garden (Under Sartaj Hotels Apartments & Villas Pvt. Ltd.) Khasra No. 369 min, 371, 372 min, 376 min, 377 min and 396, NH-8, Village Rangpuri, New Delhi-110037

Conditions for the validity of fire safety certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of firefighting system.
- 4. The owner/ occupier shall submit a declaration every year in Form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in.
- 5. This fire safety certificate may not in any way be treated as regularization of unauthorized construction, if any.
- 6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry."

		Motel Building Block No. 2, Celebration Garden, NH-8, Village Rangpuri, New Delhi-37							
1.	,	INSPECTION REPORT ne & address of the building: Motel Building Block No. 2, Celebration Garden (Under Sartaj Hotels Apartments & Villas Pvt. Ltd.) Khasra No. 369 min, 371, 372 min, 376 min,377 min and 396, NH-8, Village Rangpuri, New Delhi-37							
2.		e of Occupancy : Group A "Residential" (Motel) Building [Basement + G. Floor]							
3.			e of Case : Renewal						
1				1561 Dated 01/11/201	.7				
5.		The state of the s	1000/1445 Dated 2	2/08/2000					
6.		e of inspection : 18/12/2020							
7.		ne of Inspecting Officer : Sh. Rajesh Kumar ADO (BCP)							
8.		me and designation of officers							
		m the building side : Mr. K.A Lal (Manager)							
9.		ar of Construction : 2010							
and the last section is not been section in the last section in the last section is not been section in the last section in the last section in the last section in the last section is not been section in the last section in th	and the same of the same of	plicant's letter No : Gmail dated 01/12/2020							
S.	1	Inimum Standards on fire prevention and	Old NOC	Provided at site	Remarks				
No	-	re safety U/R 33	Requirement		MR/NMR				
1.	F	ccess to building	10	Duncided	MD				
	1	Road width	12m	Provided	MR				
		Gate width	5m	Provided	MR				
		Width of internal road	6m	Provided	MR				
2.	-	umber, Width, Type & Arrangement of Exi	ts						
	8	Number of staircases		Sing 1					
	-	Upper Floors	-NA-	-NA-	-NA-				
		Basements	3 Nos	Provided	MR				
	ł	. Width of staircases							
		Upper Floor	-NA-	-NA-	-NA-				
			2m	2.5m,1.75m &	MR(old case)				
-		Basements	2111	1.06m	ivire(ord case)				
		Protection of exits			The same per annual transportation of the same of the				
		Fire check door	-NA-	-NA-	-NA-				
		Pressurization	-NA-	-NA-	-NA-				
	(No. of continuous staircases to terrace							
	6	. Width of Corridor	Required	One	MR				
	1	Door Size	-NA-	-NA-	-NA-				
		,aS''	2m	2.25m (Final Exit)	MR				
3.		Compartmentation							
		Fire check door	-NA-	-NA-	-NA-				
		Sealing of electrical shafts	-NA-	-NA-	-NA-				
		Fire Rating of shaft door							
		Water Curtain	-NA-	-NA-	-NA-				
		Fire Dampers	-NA-	-NA-	-NA-				
			-NA-	-NA-	-NA-				
4.	4	moke Management System		Mal N. C.					
		Basements	30 ACPH	Exhaust Fans	MR				
		Upper floors	12 ACPH	-NA-	-NA-				
5.		Fire Extinguishers	06	D :1 1	MD				
		Total numbers	26	Provided	MR				
		Types	NosABC/W.Co ₂	10/10/06 Nos	MR				
		IS marking	/Co ₂	Yes	MR				
			ISI						
6.		First-Aid Hose Reels		-	_				
		Total numbers on each floor	Required	2 Nos	MR				
		 Length of hose reel hose 	30m	Provided	MR				
		Nozzle diameter	5mm	Provided	MR				
7.		Automatic fire detection and alarming system							
		Type of detectors	Smoke & Heat	Provided	MR				
1		Location of Main Panel	Required	Ground Floor	MR				
		Location of Repeater Panel	-NA-	-NA-	MR				
		Alternate source of power	=IV/A=	-INA-	IVIIX				

Required

Alternate source of power

MR

Provided

	Motel Building Block No. 2, Celebratio	n Garden, NH-8, Villag	ge Rangpuri, New Delhi-37			
	Hooters' Location	Required	All Floors	MR		
8.	MOEFA	Required	Provided	MR		
9.	Public Address System	Required	Provided	MR		
10.	Automatic Sprinkler System	D : 1	D :1.1	7.00		
	Basement	Required	Provided	MR		
	Upper Floors Sprinkler shows false seiling	Required	Provided	MR		
11	Sprinkler above false ceiling	-NA-	-NA-	-NA-		
11.	Internal Hydrants Size of riser/down-comer	100mm	Provided	MR		
	Number of hydrants per floor	Required	2 Nos	MR		
	Hose Box	Required	2 Nos	MR		
12.	Yard Hydrants	required	2 1103	IVIIC		
A. And &		Required	4 Nos	MR		
	Total number of hydrantsHose Box	Required	4 Nos	MR		
13.	Pumping Arrangements	Required	4 1108	IVIK		
13.	Ground Level					
		Required	2280 LPM	MR		
	Head of Main pump	Required	70m	MR		
	Number of main pumps	Required	One	MR		
	Jockey Pump out put	Required	180 LPM	MR		
	> Jockey pump head	Required	70m	MR		
	Standby Pump out put	Required	2280 LPM	MR		
	Standby Pump Head	Required	70m	MR		
	Auto Starting/Manual Stopping	Required	Provided	MR		
	Pump House Access	Required	Provided	MR		
	Terrace level					
	Discharge of pump	Required	900& 180 LPM	MR		
	➤ Head of the pump	Required	35m	MR		
	Power Supply	Required	Provided	MR		
	Auto Starting of pump	Required	Provided	MR		
14.	Captive Water Storage for fire fighting					
		1,50,000 Lts	1,00,000 Lts (At Ground	MR(old case		
	Underground tank capacity		level in M.S. Tank)	, and the second		
	> Draw-off connection	Required	Not required since tank is at Ground Level	-NA-		
	Fire service inlet	Required	Provided	MR		
	> Access to tank	Required	Provided	MR		
	Overhead Tank capacity	50,000 Lts	25,000 Lts	MR(old case		
15.	Exit Signage.	Required	Provided	MR		
16.	Provision of Lifts.					
	Pressurization of Lift Shaft	-NA-	-NA-	-NA-		
	Pressurization of Lift lobby	-NA-	-NA-	-NA-		
	Communication In lift Car	-NA-	-NA-	-NA-		
	Fireman's Grounding Switch	-NA-	-NA-	-NA-		
	Lift Signage	*				
		-NA-	-NA-	-NA-		
17.	Standby power supply	Required	Provided	MR		
18.	Refuge Area.					
	> Total Area	-NA-	-NA-	-NA-		
10	> Location	-NA-	-NA-	-NA-		
19.	Fire Control Room					
	Detector System Panel	-NA-	-NA-	-NA-		
	Flow Switch Panel	-NA-	-NA-	-NA-		
	PA System Panel	-NA-	-NA-	-NA-		
	Battery backup	-NA-	-NA-	-NA-		
			1			

Motel Building Block No. 2, Celebration Garden, NH-8, Village Rangpuri, New Delhi-37

		Building Floor Plans	-NA-	-NA-	-NA-
20.	0. Special Fire Protection System for Protection of special Risks, if any:				

The fire protection system provided in the premises were checked, tested at random and found functional at the time of inspection. Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F6/ DFS/ MS/Motel/ SZ /2017/1561 Dated 01/11/2017, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Designation: ADO (BCP)

ADO/B/CP
As approved, f.t. tettel en putup
for your sonature Pl.

11.5.00