GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No. F.6/DFS/MS/GH/2020/SZ/ 152

Dated: 31/12/2020

FIRE SAFETY CERTIFICATE

Certified that the Barkat Home Guest House located at 7, Basti Hazrat Nizamuddin, New Delhi comprised of Basement/lower ground floor (storage), ground floor (reception + 05 guest rooms) First floor & Second floor having 05 guest rooms at each floor (Total- 15 guest rooms) was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/GH/2018/SZ/808 dated 24/08/2018. The premise was re-inspected by officer concerned of this department on 28/12/2020 in the presence of Mr. Ishrat Ullah Khan (Manager) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class "Residential (Hotel) Group-A" as above with effect from31 1.2. 2020...... for a period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued 31/12/2020 at New Delhi by

(Sunil Chawdhary)
Dy. Chief Fire Officer
Delhi Fire Service

Copy to: -

- 1. The Manager, Barkat Home Guest House,7, Basti Hazrat Nizamuddin, New Delhi-110013.
- 2. The Joint Commissioner of Police,(LIC.), 1st floor P.S. Defence Colony, New Delhi 110049

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept from any obstruction.
- 2.All the fire safety arrangements provided therein shall be maintained in good working condition at all times. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 3. All the staff members must know the correct method of operation of fore fighting system.
- 4. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rule of 2010. The form is available on www.dfs.delhigovt.nic.in.
- 5. The certificate may not be treated in any case for the regularization (clause 2.8 & UBBL-2016) of the unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- **6.**The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.

1	Name & Address of the Building	M/s Barkat Home Guest House, 7, Basti Hazrat				
3-17-0	The state of the s	Nizamuddin, New Do				
2	Type of Occupancy	Residential & Lodging, Group-A				
3	Building Comprised of	Lower Ground/Basement (Storage), Ground floor (Reception + 05 Guest rooms), 1 st floor (05 guest rooms) and Second floor (05 guest rooms)				
4	Type of Case	Renewal				
5	Details of Previous NOC	F6/DFS/MS/GH/2018/SZ/808 dated 24/04/2018				
6	Fire Safety Directives Letter No	Nil				
7	Date of Inspection	N11 28/12/2020				
	Name of the Inspecting Officers	ADO Avtar Singh				
8	Name & Designation of Officers	Mr. Ishrat Ullah Khan (Manager)				
	from the building side					
10	Year of construction	2006-07				
11	Applicant letter No.	Email dated 24/12/2020				
S. No	Minimum standards on Fire Prevention and Fire Safety U/R 33	As per old NOC- 2015	Provided at Site	Remarks MR/NMR		
1	Access to Building.			1.00		
	Road width	6 m	Provided	MR		
	Gate width	-N/A-	Directly approachable	MR		
	 Width of internal road 	-N/A-	-N/A-	-N/A-		
2	Number, width, type & arrangement of exits.					
	a) Number of Staircase					
	Upper floors	02 nos	Provided	MR		
	Basement floor	02 nos	Provided	MR		
	b) Width of Staircase		* *			
	> Upper floors	1.25 m each	1.45 m & 0.42 m	MR		
	Basement floor	1.25 m each	2.15 m & 1.25 m	MR		
	c) Protection of exits					
	> Fire check door	-N/A-	-N/A-	-N/A-		
	Pressurization	-N/A-	-N/A-	-N/A-		
	d)No. of continuous staircase to terrace	Required	01 nos	MR		
	e) Width of corridor	1 m	Provided	MR		
	f) Door size	1 m	Provided	MR		
3	Compartmentation.					
	• Fire check door.	-N/A-	-N/A-	-N/A-		
	Sealing of electrical shafts.Fire rating of shaft door.	-N/A-	-N/A-	-N/A-		
		-N/A-	-N/A-	-N/A-		
	• Water curtain	-N/A-	-N/A-	-N/A-		
	• Fire dampers.	-N/A-	-N/A-	-N/A-		
4.	Smoke Management system.					
	Basement	30 ACPH	Exhaust fan	MR		
	• Upper floors	12 ACPH	-N/A-	-N/A-		
5.	Fire Extinguishers.					
	Total numbers	ISI marked	10 Nos	MR		
	• Types		ABC & CO ₂	MR		
	ISI Marking		Provided	MR		
6.	First Aid Hose Reels.	And the second				
	Total numbers on each floor	01 nos	Provided at each floo	or MR		

	• Length of hose-reel hose.	30 111	1101100			
	Nozzle Diameter	5 mm	Provided	MR		
7	Automatic fire detection & alarming system.					
	Type of detectors Location of Main Panel	Carbon monoxide (CO) type	Provided	MR		
	 Location of Nam 1 and Location of Repeater Panel 	-N/A-	-N/A-	-N/A-		
	Alternate source of power	-N/A-	-N/A-	-N/A-		
	Hooter's location	-N/A-	-N/A-	-N/A-		
	MOEFA	-N/A-	-N/A-	-N/A-		
8.		Required	Provided	MR		
9.	Public Address System	Required	Provided	MR		
	Automatic Sprinkler System	Δ.				
10.	Basement	Required	Provided	MR		
	BasementUpper floors	-N/A-	-N/A-	-N/A-		
	 Sprinkler above false ceiling 	-N/A-	-N/A-	-N/A-		
11	Internal Hydrants.	1,112				
11.	2D: /D	-N/A-	-N/A-	-N/A-		
	Size of Riser / Down-comerNumber of Hydrant per floor	-N/A-	-N/A-	-N/A-		
	Hose box.	-N/A-	-N/A-	-N/A-		
10		1 4/ 1 7				
12.	Yard Hydrants.	-NA-	Provided	-NA-		
	Total number of hydrants.Hose box.	-NA-	Provided	-NA-		
13		1112				
13.	Pumping arrangements.			3		
	Ground Level	-N/A-	-N/A-	-N/A-		
	Discharge of main pump.	-N/A-	-N/A-	-N/A-		
	> Head of main pump.	-N/A-	-N/A-	-N/A-		
	Number of main pumps.Jockey Pump output.	-N/A-	-N/A-	-N/A-		
	Jockey Pump output.Jockey Pump head.	-N/A-	-N/A-	-N/A-		
	Standby Pump output.	-N/A-	-N/A-	-N/A-		
	> Standby Pump head.	-N/A-	-N/A-	-N/A-		
	> Auto Starting/Manual	-N/A-	-N/A-	-N/A-		
	Stopping. > Pump house access.	-N/A-	-N/A-	-N/A-		
	•	-1N/A-	7 11 2			
	Terrace Level	450 LPM	450 LPM & 225 LPM	1 MR		
	Discharge of pump.	450 LPWI 40 m	40 m each	MR		
	Head of pump.Power supply.	Required	Provided D.G. Set	MR		
	> Auto starting of pump.	Required	Provided	MR		
14.	c c c -1.4	ing.		8		
14.	Underground tank capacity.	-N/A-	-N/A-	-N/A-		
	Draw-off connection.	-N/A-	-N/A-	-N/A-		
	> Fire Service Inlet.	Required	Provided	MR		
	Access to tank.	-N/A-	-N/A-	-N/A-		
	 Overhead tank capacity. 	5,000 ltrs	5,000 ltrs	MR		
15	5. Exit Signage.	Required	Provided	MR		
15	5. Exit digitage.					
10	• Pressurization of lift shaft.	-N/A-	-N/A-	-N/A-		
	• Pressurization of lift lobby.	-N/A-	-N/A-	-N/A-		
	• Communication in lift car.	-N/A-	-N/A-	-N/A-		
	Fireman's switch	27/4	NI/A	-N/A-		

_ (C _T		1.0	-N/A-	-N/A-	-N/A-		
	•	Lift signage.	Required	Provided DG Set	MR		
17	7 Standby Power Supply Required Provided BG Set						
18.	Refug	e Area	-N/A-	-N/A-	-N/A-		
		Total area	-N/A-	-N/A-	-N/A-		
	•	Location	1112				
19.	Fire C	Control Room.	-N/A-	-N/A-	-N/A-		
	•	Detector System Panel. Flow Switch Panel.	-N/A-	-N/A-	-N/A-		
	•	PA system Panel.	-N/A-	-N/A-	-N/A-		
	•	To the large	-N/A-	-N/A-	-N/A-		
	•		-N/A-	-N/A-	-N/A-		
20.	Spe the P	cial Fire Protection System for rotection of special Risk, if any.	Required	02 ABC type fire extinguisher cap. 5 kg found provided near elect. panel	-N/A-		

The Fire protection systems provided in the premises were checked / operated at random and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 37 of the Delhi Fire Service Rules 2010.

The condition of the Gazette notification dated 27/05/2019 on mentioned below found complied. No Kitchen Provided MR

1. No Kitchen on rooftop/basement.

No Storage Provided MR

2. No Storage of inflammable material on rooftop. 3. No temporary roofing over the rooftop.

Not Provided MR

4. No Inflammable material of construction in passage/corridor.

Not Provided MR No Gas Bank provided MR

5. Gas Bank, if any

Provided MR

6. Carbon Monoxide type Detectors. 7. Fire Doors of min. 01 hr. rating

Not Required MR

(If number of occupants more than 10 on each floor)

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

: Avtar Singh

Designation: ADO (M.Rd)

DO (SD)