GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001**

No F 6 / DFS / MS / 2020/ Gru / WZ / 03 FIRE SAFETY CERTIFICATE

Dated 04 / 0 | /2020

Certified that the M/s Hotel New City Guest House located at A-7, G.T. Karnal Road, Adarsh Nagar, Delhi-110033 comprised of basement, ground and two upper floors (Guest house at 1st and 2nd floor only having 18 guest rooms) owned/occupied by Hotel New City was issued fire safety certificate vide letter no. F6/DFS/MS/2017/GH/WZ/92 dated 20/01/2017. The premises was re-inspected by the officer concerned of Fire Service on 14/12/2020 in the presence of Sh. Shyam Lal (Partner) and observed that all the fire prevention & fire safety arrangements as provided in the premises found in good working condition The premises have therefore, deemed complied with the requirement under rule 33 of Delhi Fire Service Rules, 2010 and the building is fit for occupancy Class -A-1 Residential for 18 guest rooms only with effect from 04 101 202 -- for a period of **03 (Three) years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ...O.H. J. O.I. . 20.21. at New Delhi by

(DharampalBhardwai) Dy. Chief Fire Officer Ph-011-25156707

Op

Copy to:-

1. The Addl. CP/Lic., Ist Floor, PS Defence Colony, New Delhi.

2. The Manager, M/s Hotel New City Guest House, A-7, G T K Road, Adarsh Nagar, Delhi-110033.

Conditions for the validity of Fire Safety Certificate:

All the means of escape/entry/exit shall be kept free from any obstruction.

- All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- All the staff members must know the correct method of operation of firefighting system.
- The owner / occupier shall submit a declaration every year in Form "K" provided in the first is available form on Rules 2010. The Service Delhi Fire schedule of http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.
- This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
- "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

1. Name & address of the building: M/s Hotel New City Guest House, A-7, G T K Road, Adarsh Nagar, Delhi-110033. (B+G+02 Floor) : Residential (A-1) for 18 guest rooms Type of Occupancy 2. :Renewal Type of Case 3. :F6/DFS/MS/2017/GH/WZ/92 dated 20.01.2017 4. Details of previous NOC Basement- other property :NBC Part IV 5. Fire Safety directives letter No Ground floor- other property : 14/12/2020 6. Date of inspection First floor- 09 guest rooms 7. Name of the Inspecting Officers : ADO (RN) Second floor- 09 guest rooms 8. Name and designation of officers : Mr. Shyam Lal (Partner) from the building side : 2008 9. Year of Construction : Online E-mail I.D dated 24.11.2020 10. Applicant's letter No. Provided at site Remarks NBC/BBL Minimum Standards on fire prevention MR/NMR Requirement and fire safety U/R 33 Access to building MR 20m (approx) 06m Road width NA Directly accessible NA Gate width NA Width of internal road NA NA Number, Width, Type & Arrangement of Exits a. Number of staircases MR 02 02 Upper Floors NA NA NA Basements (other property) b. Width of staircases MR (old case) 1.50m (iron 1.50 m staircase) & 1.25m Upper Floors NA NA NA Basements c. Protection of exits MR Provided Required Fire check door NA NA NA Pressurization MR 01 01 d. No. of continuous staircases to terrace NA NA NA e. Width of Corridor MR 1.0m 1.0m f. Door Size Compartmentation. MR Provided Required Fire check door NA NA NA Sealing of electrical shafts NA NA NA Fire Rating of shaft door NA NA NA Water Curtain NA NA NA Fire Dampers Smoke Management System. 4 NA NA(other property) 12 a/c per hour Basements 9

1

2

	Upper floors	12 a/c per hour	Natural Ventilated	MIK	
5	Fire Extinguishers				
	Total numbers	06nos	08nos	MR	
	• Types	ABC&Co2	08ABC	MR	
	ISI marking	Yes	Yes	MR	
6	First-Aid Hose Reels.				
	Total numbers on each floor	01	01	MR	
	 Length of hose reel hose 	30m	30m	MR	
	Nozzle diameter	5mm	5mm	MR	
7	Automatic fire detection and alarming system.				
	Type of detectors	Required(carbon	Provided(carbon	MR	
	Location of Main Panel	monoxide) Required	monoxide) Provided	MR	
	Location of Repeater Panel	NA	NA	NA	
	Alternate source of power	NA	NA	NA	
	Hooters' Location				
	Hooters Location	NA	NA	NA	
8	MOEFA	Required	Provided	MR NA	
9	Public Address System.	NA	NA	IVA	
10	Automatic Sprinkler System.				
	Basement	NA	NA	NA	
	Upper Floor	NA	NA	NA	
	Sprinkler above false ceiling	NA	NA	NA	
11	Internal Hydrants				
	Size of riser/down-comer	NA	NA	NA	
	Number of hydrants per floor	NA	NA	NA	
	Hose Box	NA	NA	NA	
12	Yard Hydrants.				
	Total number of hydrants	NA	NA	NA	
	Hose Box	NA	NA	NA	
13	Pumping Arrangements.				
	Ground Level				
	Discharge of main Pump	N/A	N/A	N/A	
	➤ Head of Main pump	N/A	N/A	N/A	
	Number of main pumps	N/A	N/A	N/A	
	> Jockey Pump out put	N/A	N/A	N/A	
	> Jockey pump head	N/A	N/A	N/A	
	Standby Pump out put	N/A	N/A	N/A	
	Standby Pump HeadAuto Starting/ Manual stopping	N/A	N/A	N/A	
	Auto Starting/ Manual stoppingPump House Access	N/A	N/A	N/A	
	Terrace level				
	Discharge of pump	450lpm	450 lpm	MR	
	> Head of the pump	35m	35m	MR	

2		> Power Supply	Required	Provided	MR	
N		> Auto Starting of pump	Required	Provided	MR	
14	Captive Water Storage for fire fighting.					
	•	Underground tank capacity	NA	NA	NA	
	>	Draw-off connection	NA	NA	NA	
	>	Fire service inlet	NA	NA	NA	
	>	Access to tank	NA	NA	NA	
	•	Overhead Tank capacity	5,000 ltrs	5000 ltr.	MR	
15	Exit Sig	nage.	Required	Provided	MR	
16	Provision of Lifts.					
	•	Pressurization of Lift Shaft	N/A	N/A	N/A	
	•.	Pressurization of Lift lobby	N/A	N/A	N/A	
	•	Communication In lift Car	NA	NA	NA	
	•	Fireman's Grounding Switch	NA	NA	NA	
	•	Lift Signage	NA	NA	NA	
17	Standby	power supply	Required	Provided inverter	MR	
18	Refuge Area.					
	>	Total Area	N/A	N/A	N/A	
	>	Location	N/A	N/A	N/A	
19	Fire Control Room					
	•	Detector System Panel	N/A	N/A	N/A	
	•	Flow Switch Panel	N/A	N/A	N/A	
	•	PA System Panel	N/A	N/A	N/A	
	•	Batter backup	N/A	N/A	N/A	
	•	Building Floor Plans	N/A	N/A	N/A	
20		rire Protection Systems for on of special Risks, if any:	NA	NA	NA	

The compliance of the provision contained as per gazette notification no F.5(189)/AD/LB/2016/40534065 dated 27.05.2019 Les Compliant.

The fire protection systems provided in the building were tested/ checked randomly and found in good working conditions.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to renew Fire Safety Certificate issued vide this department letter of even no. 92 dated 20.01.2017 under rule 35 of the Delhi Fire Service Rules 2010.

DO(NW)

29/M mr.

Signature of the Inspecting Officer

Name: - C.L. Meena Designation:- ADO/RN